

10CFR50.54(f)

Palo Verde Nuclear Generating Station

Gregg R. Overbeck Senior Vice President Nuclear

TEL (623) 393-5148 FAX (623) 393-6077

Mail Station 7602 P.O. Box 52034 Phoenix, AZ 85072-2034

102-04669-GRO/SAB/RJR March 15, 2002

U.S. Nuclear Regulatory Commission ATTN: Document Control Desk Washington, DC 20555-0001

- References: 1. Letter 102-04603-CDM/SAB/RJR, dated September 4, 2001, "Response to NRC Bulletin 2001-01: Circumferential Cracking of Reactor Pressure Vessel Head Penetration Nozzles." from C. D. Mauldin, APS to USNRC.
 - 2. Letter dated November 5, 2001, "Palo Verde Nuclear Generating Station, Units 1, 2, and 3 - Telephone Conference Summary RE: Responses to Bulletin 2001-01," from L. R. Wharton, USNRC to G. R. Overbeck, APS.
 - 3. Letter 102-04628-GRO/SAB/RJR, dated December 06, 2001, "Revised Inspection Schedule in Response to NRC Bulletin 2001-01, from Gregg R. Overbeck, APS to USNRC.
 - 4. Telephone Conferences, dated December 13, 2001 and December 14, 2001, Discussion on Supplemental Response Letter (Reference 3) between APS Staff and USNRC Staff.
 - 5. Letter 102-04650-GRO/SAB/RJR, dated January 29, 2002, "Response to NRC Bulletin 2001-01 Request for Additional Information," from Gregg R. Overbeck, APS to USNRC.

Dear Sirs:

Subject: Palo Verde Nuclear Generating Station (PVNGS)

Units 1, 2 and 3

Docket Nos. STN 50-528, 50-529, and 50-530 NRC Bulletin 2001-01 Inspection Method

This letter amends the Arizona Public Service Company (APS) response to NRC Bulletin 2001-01, Circumferential Cracking of Reactor Pressure Vessel Head Penetration Nozzles.

A088