5

Alleg. No. Facility Attendees Brief Title/Description

IP-2 OI Repanel of IP-2 SG issue - to include NRR staff.

9:30 a.m.

REPANEL

蚁 7A

RI-2000-A-0142 10:45 a.m. Indian Point 2/3 OI

Репу

Seabrook

Vermont Yankee

Turkey Point

REPAREL FOR LATE DANUALT

BURETIONS FOR SCHMOT TO ASK

A Williams Power home-office supervisor, makes occasional site visits and directs workers to perform "unsafe" work activities, in order to put contracted jobs back on schedule.

Within the last 2-years, home-office supervisor was at Indian Point, and directed workers to blow down a contaminated area with compressed air, to expedite the painting process. This resulted in 2 workers becoming internally contaminated.

HONE CAUS DAPES WHO ON CALLY WHAT SA.O/
MAY TOWN - Clary - 100 ROD

JULY - 29 JULY - 100 ROD

JULY - 29 JULY - 100 ROD

A SMED ON MINE THAN I PHINE CALL

whithm RE