Docket No. 50-315

Mr. John Dolan, Vice President Indiana and Michigan Electric Company c/o American Electric Power Service Corporation 1 Riverside Plaza Columbus, Ohio 43216

Dear Mr. Dolan:

The Commission has issued the enclosed Amendment No. 105 to Facility Operating License No. DPR-58 for the Donald C. Cook Nuclear Plant, Unit Nos. 1. The amendment consists of changes to the Technical Specifications in response to your application dated February 10, 1987.

The amendment revises the Technical Specifications to allow ice condenser surveillances due to be performed about May 10, 1987 to be extended to the next refueling outage scheduled about July 1987.

A copy of the Safety Evaluation is also enclosed. The notice of issuance will be included in the Commission's next bi-weekly Federal Register notice.

Sincerely,

David L. Wigginton, Project Manager Project Directorate III-3 Division of Reactor Projects

Enclosures:

1. Amendment No.10% to DPR-58

2. Safety Evaluation

cc w/enclosures: See next page

Office: Surname: LA/PDIII-3 PKneutzer

Date:

05/ /87

05/**7** /87

PD/PDIII-3 DWigginton 05/**7**/87 Mr. John Dolan Indiana and Michigan Electric Company

> The Honorable John E. Grotberg United States House of Representatives Washington, DC 20515

Donald C. Cook Nuclear Plant

cc:
Mr. M. P. Alexich
Vice President
Nuclear Operations
American Electric Power Service
Corporation
1 Riverside Plaza
Columbus, Ohio 43215

Regional Administrator, Region III U.S. Nuclear Regulatory Commission 799 Roosevelt Road Glen Ellyn, Illinois 60137

Attorney General Department of Attorney General 525 West Ottawa Street Lansing, Michigan 48913

J. Feinstein
American Electric Power
Service Corporation
1 Riverside Plaza
Columbus, Ohio 43216

Township Supervisor Lake Township Hall Post Office Box 818 Bridgeman, Michigan 49106

W. G. Smith, Jr., Plant Manager Donald C. Cook Nuclear Plant Post Office Box 458 Bridgman, Michigan 49106

U.S. Nuclear Regulatory Commission Resident Inspectors Office 7700 Red Arrow Highway Stevensville, Michigan 49127

Gerald Charnoff, Esquire Shaw, Pittman, Potts and Trowbridge 1800 M Street, N.W. Washington, DC 20037

Mayor, City of Bridgeman Post Office Box 366 Bridgeman, Michigan 49106

Special Assistant to the Governor Room 1 - State Capitol Lansing, Michigan 48909

Nuclear Facilities and Environmental Monitoring Section Office Division of Radiological Health Department of Public Health 3500 N. Logan Street Post Office Box 30035 Lansing, Michigan 48909



NUCLEAR REGULATORY COMMISSION WASHINGTON, D. C. 20555

INDIANA AND MICHIGAN ELECTRIC COMPANY

DOCKET NO. 50-315

DONALD C. COOK NUCLEAR PLANT, UNIT NO. 1

AMENDMENT TO FACILITY OPERATING LICENSE

Amendment No. 108 License No. DPR-58

- The Nuclear Regulatory Commission (the Commission) has found that:
 - A. The application for amendment by Indiana and Michigan Electric Company (the licensee) dated February 10, 1987, complies with the standards and requirements of the Atomic Energy Act of 1954, as amended (the Act), and the Commission's rules and regulations set forth in 10 CFR Chapter I;
 - B. The facility will operate in conformity with the application, the provisions of the Act, and the rules and regulations of the Commission;
 - C. There is reasonable assurance (i) that the activities authorized by this amendment can be conducted without endangering the health and safety of the public, and (ii) that such activities will be conducted in compliance with the Commission's regulations;
 - D. The issuance of this amendment will not be inimical to the common defense and security or to the health and safety of the public; and
 - E. The issuance of this amendment is in accordance with 10 CFR Part 51 of the Commission's regulations and all applicable requirements have been satisfied.

Accordingly, the license is amended by changes to the Technical Specifications as indicated in the attachment to this license amendment, and paragraph 2.C.(2) of Facility Operating License No. DPR-58 is hereby amended to read as follows:

(2) Technical Specifications

The Technical Specifications contained in Appendices A and B, as revised through Amendment No. 108, are hereby incorporated in the license. The licensee shall operate the facility in accordance with the Technical Specifications.

This license amendment is effective as of the date of issuance. 3.

FOR THE NUCLEAR REGULATORY COMMISSION

David L. Wigginton, Acting Project Director Project Directorate III-3

Division of Reactor Projects

Attachment: Changes to the Technical **Specifications**

Date of Issuance: May 8, 1987

ATTACHMENT TO LICENSE AMENDMENT

AMENDMENT NO.108 FACILITY OPERATING LICENSE NO. DPR-58

DOCKET NO. 50-315

Revise Appendix A Technical Specifications by removing the page identified below and inserting the enclosed page. The revised page is identified by amendment number and contains marginal lines indicating the area of change.

REMOVE

INSERT

3/4 6-27

3/4 6-27

SURVEILLANCE REQUIREMENTS (Continued)

shall be constituted of one basket each from Radial Rows 1, 2, 4, 6, 8 and 9 (or from the same row of an adjacent bay if a basket from a designated row cannot be obtained for weighing) within each bay. If any basket is found to contain less than 1220 pounds of ice, a representative sample of 20 additional baskets from the same bay shall be weighed. The minimum average weight of ice from the 20 additional baskets and the discrepant basket shall not be less than 1220 pounds/basket at a 95% level of confidence.

The ice condenser shall also be subdivided into 3 groups of baskets, as follows: Group 1 - bays 1 through 8, Group 2 - bays 9 through 16, and Group 3 - bays 17 through 24. The minimum average ice weight of the sample baskets from Radial Rows 1, 2, 4, 6, 8 and 9 in each group shall not be less than 1220 pounds/basket at a 95% level of confidence.

The minimum total ice condenser ice weight at a 95% level of confidence shall be calculated using all ice basket weights determined during this weighing program and shall not be less than 2,371,450 pounds.*

- Verifying, by a visual inspection of at least two flow passages per ice condenser bay, that the accumulation of frost or ice on flow passages between ice baskets, past lattice frames, through the intermediate and top deck floor grating, or past the lower inlet plenum support structures and turning vanes is restricted to a nominal thickness of 3/8 inches. If one flow passage per bay is found to have an accumulation of frost or ice greater than this thickness, a representative sample of 20 additional flow passages from the same bay shall be visually inspected. If these additional flow passages are found acceptable, the surveillance program may proceed considering the single deficiency as unique and acceptable. More than one restricted flow passage per bay is evidence of abnormal degradation of the ice condenser.*
- c. At least once per 40 months by lifting and visually inspecting the accessible portions of at least two ice baskets from each 1/3 of the ice condenser and verifying that the ice baskets are free of detrimental structural wear, cracks, corrosion or other damage. The ice baskets shall be raised at least 12 feet for this inspection.

^{*} The provisions of Specification 4.0.6 are applicable.



NUCLEAR REGULATORY COMMISSION WASHINGTON, D. C. 20555

SAFETY EVALUATION BY THE OFFICE OF NUCLEAR REACTOR REGULATION

RELATED TO AMENDMENT NO. 108 TO FACILITY OPERATING LICENSE NO. DPR-58

INDIANA AND MICHIGAN ELECTRIC COMPANY

DONALD C. COOK NUCLEAR PLANT, UNIT NO.1

DOCKET NO. 50-315

Introduction

By letter dated February 10, 1987, Indiana and Michigan Electric Company (licensee) proposed certain changes to the Technical Specifications (TS) for the Donald C. Cook Nuclear Plant, Unit No. 1, concerning the ice condenser ice baskets and flow passages. Specifically, the licensee requested an extension of the surveillance interval for weighing ice baskets and inspection of ice condenser flow passages. Additional clarification and justification for the request was provided by letter dated April 30, 1987.

Evaluation

Currently, the TS require surveillance, by weighing, of the ice baskets at least once per 9 months and visual inspection of ice condenser flow passages at the same interval. The current TS require those ice condenser surveillances be performed by May 10, 1987. The licensee proposed extending the surveillance intervals until the end of the Cycle 9-10 refueling outage (currently anticipated to begin at the end of June 1987) in order to avoid a surveillance outage (plant shutdown) before the upcoming refueling outage. A surveillance outage to satisfy the current technical specifications surveillance schedule is necessary since the surveillance in question cannot completely be performed at power due to ALARA (occupational radiation exposure) considerations. Visual inspection of ice condenser flow paths involves inspection of lattice frames, intermediate and top deck gratings, lower plenum support structures, turning vanes, and at least two flow passages (between baskets) per bay. More than half of the inspections must be conducted in the ice condenser lower plenum and therefore are subject to ALARA considerations; the remainder are performed in the accessible upper plenum region. Relative to the weighing of ice baskets, all ice baskets, except those in the rows adjacent to the containment wall and the crane wall, can generally be weighed with personnel access to the upper plenum region only and thus at power. The baskets in rows 1 and 9 often cannot be weighed without first freeing the baskets due to their tendency to become frozen in place. This additional operation requires personnel to enter the lower plenum which raises ALARA concerns. The licensee argued that the proposed extensions to the surveillance schedule should apply to all of the subject surveillances on the grounds that the administrative burden of performing the partial surveillances outweighs the benefit to safety provided by a small potential gain in safety margin.

To buttress the request for a schedule extension, the licensee evaluated the results of past surveillances to determine the impact of the proposed request. With regard to ice condenser flow path visual inspections, the licensee has noted that 6 of the 8 visual inspections performed since 1982 have satisfied the acceptance criteria. The two exceptions, occurring in

October 1983 and July 1985, resulted when inspections were performed after ice replenishment and prior to post-maintenance cleanup. After post-maintenance cleanup, surveillance results were acceptable. Both surveillance failures resulted from maintenance performed in modes 5 or 6 and were corrected before the plant entered mode 4. Inspection of the ice condenser in the as-found condition following power operation has not shown any problems with blockage of flow passages. Furthermore, there have been no ice replenishment operations during the current period of operation. Thus, the staff concludes that the relatively recent history of visual inspections indicates that the existence of flow blockage is unlikely; additionally, the proposed surveillance extension involves a reasonably short period of time of operation at power. Consequently, the staff finds the proposed change to TS 4.6.5.1.b.3 extending the surveillance interval for flow passage verification will have no significant impact on safety and is, therefore, acceptable.

With regard to the weighing of ice baskets, the licensee has evaluated past ice basket weights and the effect of sublimation to determine the impact of the proposed schedule extension on the ability of the ice condenser to perform its safety function. Technical Specification 4.5.5.1.b.2 which requires weighing of ice baskets at 9-month intervals also requires a minimum weight of 1220 pounds of ice per basket with a total ice condenser weight of 2,371,450 pounds. The minimum weight of 1220 pounds per basket contains a 10% conservative allowance for ice loss through sublimation with the intent to assure a minimum ice weight of 1098 pounds at the end of the surveillance interval.

The licensee, using data from past surveillance intervals, has performed several sets of calculations to estimate the amount of ice that will be present in each basket at the end of the current surveillance interval including an extension period. Specifically, calculations were performed to estimate ice weights on July 31, 1987. Calculations were performed for the period ending July 31, 1987 even though the refueling outage is scheduled to begin at the end of June 1987 in order to provide a measure of conservatism in the calculation. Calculations were performed to estimate the ice weight per basket for each ice condenser bay and each row group, this distinction being required by the technical specifications.

The first set of calculations estimated ice losses using data from the last five surveillance intervals. The ice loss rate calculations were performed using average expected values and rates at the lower 95 percent confidence level. These ice loss rates, both average rates and the rates at the lower 95 percent confidence level, were then applied to the "as-left" ice weight of the latest surveillance, June 1986.

The results of the licensee's calculations performed at the lower 95 percent confidence level indicate that all bays except bays 1, 7 and 24 are expected to have average basket weights above 1220 pounds. Importantly, bays 1, 7 and 24 are expected to have average basket weights above 1098 pounds, which is established as the minimum acceptable ice weight for operation in the bases for the technical specifications. Estimates of basket weights for row groups resulted in the prediction that all row-groups except row groups 1-2, 4-3, and 9-3 are expected to have average weights above 1220 pounds. Again it is important to note that the exceptions are expected to have average weights above 1098 pounds. Using the same basic approach, the licensee estimated that the total ice condenser ice weight, with at least 95% confidence, would be 2,545,376 pounds in comparison with the limit of 2,371,450 pounds required by TS 4.6.5.1.b.2.

As noted above, the licensee estimated ice weights using data from the last five surveillances. The staff, in that regard, requested the licensee justify the use of ice weights over that period by comparison with the data from the last surveillance interval in order to determine if more recent trends are apparent. Furthermore, the staff requested the licensee confirm that there have been no significant events at the plant, e.g., inadvertent door openings or defrosting, since the last surveillance which may affect the ice inventory. In response to staff queries, the licensee responded that there have been no significant events at the plant since the last ice weighing which would materially affect the ice inventory or invalidate the use of past data to estimate current performance.

Additionally, the licensee performed a second set of calculations using ice loss data from the last surveillance interval to determine if more recent trends in ice loss could be determined. The results of the licensee's calculations indicated that when the most recent ice weight losses were subtracted from the lower 95 percent confidence limit of ice weights there were two bays and one row group below the TS limit of 1220 pounds per basket. However, those three groups remained above the 1098 pounds per basket limit established in the bases for the technical specifications.

The first two sets of calculations described above were performed assuming ice weight measurements reflecting a gain in ice weight were, for analysis purposes, a zero ice loss. Thus, no credit was taken for the fact that random weighing of baskets can result in basket ice weights increasing from one surveillance to the next, especially if surveillance occurs frequently. The assumption that an ice weight gain can be modeled as a zero ice loss was originally thought by the licensee to be conservative and is so in the case of average ice losses. However, when statistical methods are used to estimate ice losses at the lower 95 percent confidence level an ice gain will result in a larger standard deviation than a zero ice loss. Therefore, the actual data reflecting an ice weight gain should be used in the prediction of the weights. The licensee, in response to this matter, performed a third set of calculations using actual ice weight increases as appropriate with data from the last five surveillance intervals. The results of these calculations indicate that all but five bays would have a basket weight greater than 1220 pounds with 95 percent confidence; those five bays would have a weight greater than 1098 pounds.

For ice condenser row groups it was estimated, with 95 percent confidence, that all but seven row groups would exceed the limit of 1220 pounds per basket. Of those seven row groups, five were predicted to have ice weights above 1098 pounds per basket; however, the basket weights in row groups 1-2 and 4-3 were predicted to be 1048 pounds and 1061 pounds, respectively. Thus, two row groups would contain, by July 31, 1987, less ice than the minimum limit established in the bases for the technical specifications.

In response to this situation, the licensee has responded that the licensing basis containment safety analysis for D. C. Cook Unit 1 was based on a total ice weight of 2,000,000 pounds or 1029 pounds per basket. Therefore, even though two row groups may not contain sufficient ice to satisfy the bases for the technical specifications, adequate ice would be present to satisfy the assumptions of the safety analysis. The staff has discussed this apparent discrepancy between the technical specifications and the licensing basis safety analysis and the licensee has indicated their intent to pursue this matter as part of an overall program to modify the technical specifications and surveillance related to ice weight.

The staff has considered the arguments provided by the licensee and concurs that the proposed change to TS 4.6.5.1.b.2 to allow an extension of the surveillance interval for weighing the ice baskets is warranted, and does not present a significant safety impact. The surveillance interval extension proposed by the licensee involves a relatively brief time period of operation at power and analysis indicates that the ice condenser, over that time period, will contain sufficient ice, adequately distributed, to perform its safety function.

ENVIRONMENTAL CONSIDERATION

This amendment involves a change in the installation or use of a facility component located within the restricted area as defined in 10 CFR Part 20. The staff has determined that the amendment involves no significant increase in the amounts, and no significant change in the types, of any effluents that may be released offsite, and that there is no significant increase in individual or cumulative occupational radiation exposure. The Commission has previously published a proposed finding that this amendment involves no significant hazards consideration and there has been no public comment on such finding. Accordingly, this amendment meets the eligibility criteria for categorical exclusion set forth in 10 CFR §51.22(c)(9). Pursuant to 10 CFR 51.22(b), no environmental impact statement or environmental assessment need be prepared in connection with the issuance of this amendment.

CONCLUSION

The staff has concluded, based on the considerations discussed above, that (1) there is reasonable assurance that the health and safety of the public will not be endangered by operation in the proposed manner, and (2) such activities will be conducted in compliance with the Commission's regulations, and the issuance of the amendment will not be inimical to the common defense and security or to the health and safety of the public.

Principal Contributor: C. Tinkler

Date: May 8, 1987