

Howard W. Bergendahl
Vice President - Nuclear

419-321-8588
Fax: 419-321-8337

Docket Number 50-346

License Number NPF-3

Serial Number 2768

April 25, 2002

United States Nuclear Regulatory Commission
Document Control Desk
Washington, D. C. 20555-0001

Subject: Davis-Besse Nuclear Power Station License Condition 2.C(7) Report for the Thirteenth Refueling Outage

Ladies and Gentlemen:

This letter is submitted in accordance with the requirements of the Operating License for the Davis-Besse Nuclear Power Station (DBNPS), Unit Number 1. License Condition 2.C(7) requires the FirstEnergy Nuclear Operating Company (FENOC) to report to the Nuclear Regulatory Commission (NRC) information related to specific indications identified during inservice inspection of steam generator tubes. This letter satisfies License Condition 2.C(7) in its entirety for the inspections performed during the recent thirteenth refueling outage. No supplemental report will be provided. The information specified by the license condition is provided below:

- a. No License Condition 2.C(7) indications were found inboard of any installed repair roll.
- b. Three tubes had License Condition 2.C(7) indications in the heat affected zone adjacent to the tube-to-tubesheet seal weld in the upper tubesheet. These three tubes were repaired by repair roll in accordance with Technical Specification 4.4.5.4 requirements.
- c. Based on the License Condition 2.C(7) indications identified, no leakage from any such indication in the original tube-to-tubesheet rolls, tube-to-tubesheet re-roll repairs, and heat affected zones of seal welds would be expected following a large-break loss-of-coolant accident (LBLOCA).

The best-estimate primary-to-secondary leakage following a LBLOCA has been determined to be 0.00 gpm. Accordingly, the off-site dose consequences from a LBLOCA would be below 10 CFR Part 100 limits.

A001

Docket Number 50-346
License Number NPF-3
Serial Number 2768
Page 2

Should you have any questions or require additional information, please contact Mr. David H. Lockwood, Manager - Regulatory Affairs, at (419) 321-8450.

Very truly yours,

A handwritten signature in black ink, appearing to read "D. H. Lockwood". The signature is written in a cursive style with a large, sweeping initial "D".

MAR

Enclosure

cc: J. E. Dyer, Regional Administrator, NRC Region III
S. P. Sands, DB-1 NRC/NRR Project Manager
C. S. Thomas, DB-1 NRC Senior Resident Inspector
Utility Radiological Safety Board

Docket Number 50-346
License Number NPF-3
Serial Number 2768
Enclosure 1

COMMITMENT LIST

THE FOLLOWING LIST IDENTIFIES THOSE ACTIONS COMMITTED TO BY THE DAVIS-BESSE NUCLEAR POWER STATION (DBNPS) IN THIS DOCUMENT. ANY OTHER ACTIONS DISCUSSED IN THE SUBMITTAL REPRESENT INTENDED OR PLANNED ACTIONS BY THE DBNPS. THEY ARE DESCRIBED ONLY FOR INFORMATION AND ARE NOT REGULATORY COMMITMENTS. PLEASE NOTIFY THE MANAGER – REGULATORY AFFAIRS (419-321-8450) AT THE DBNPS OF ANY QUESTIONS REGARDING THIS DOCUMENT OR ANY ASSOCIATED REGULATORY COMMITMENTS.

Commitment

Due Date

None

N/A