

April 21, 1978

Docket No. 50-313

DISTRIBUTION:
Docket File ✓
NRC PDR *sent*
L PDR *sent*

ORB#4 Rdg
EGCase
WMcDonald, MIPC
~~XXXXXXXXXXXX~~
BGrimes/TJCarter
RIngram
GVising
Attorney, OELD
OI&E (3)
BScharf (10)
DEisenhut
ACRS (16)
OPA, Clare Miles
JRBuchanan
TBAbernathy

Gray File
4 Extra Cys
BJones (4)

Arkansas Power & Light Company
ATTN: Mr. William Cavanaugh, III
Executive Director, Generation
and Construction Department
P. O. Box 551
Little Rock, Arkansas 72203

Gentlemen:

The Commission has issued the enclosed Order for Modification of License which amends Facility Operating License No. DPR-51 for Arkansas Nuclear One - Unit No. 1.

The Order specifies additional limits to the operating provisions of the license which require submission of a reevaluation of Emergency Core Cooling System cooling performance calculated in accordance with the Babcock and Wilcox evaluation model, reduce the maximum reactor power level to 2311 Mwt, and require operation in accordance with procedures described in your letters dated April 17 and 21, 1978.

A copy of this Order is being filed with the Office of the Federal Register for publication.

Sincerely,

Robert W. Reid, Chief
Operating Reactors Branch #4
Division of Operating Reactors

Enclosure:
Order for Modification
of License

Const. 3
GD

OFFICE >	ORB#4: DOR	ORB#4: DOR	C-ORB#4: DOR	ELD	AP-OR: DOR	OR: DOR
SURNAME >	RIngram:ri	GVising	RReid	Ketchen	BGrimes	VStello
DATE >	4/21/78	4/21/78	4/21/78	4/21/78	4/21/78	4/21/78

Arkansas Power & Light Company

cc w/enclosures:

Phillip K. Lyon, Esquire
House, Holms & Jewell
1550 Tower Building
Little Rock, Arkansas 72201

Mr. Daniel H. Williams
Manager, Licensing
Arkansas Power & Light Company
Post Office Box 551
Little Rock, Arkansas 72203

Mr. John W. Anderson, Jr.
Plant Superintendent
Arkansas Nuclear One
Post Office Box 608
Russellville, Arkansas 72801

Arkansas Polytechnic College
Russellville, Arkansas 72801

Honorable Ermil Grant
Acting County Judge of Pope County
Pope County Courthouse
Russellville, Arkansas 72801

Chief, Energy Systems Analyses
Branch (AW-459)
Office of Radiation Programs
U. S. Environmental Protection Agency
Room 645, East Tower
401 M Street, S. W.
Washington, D. C. 20460

U. S. Environmental Protection Agency
Region VI Office
ATTN: EIS COORDINATOR
1201 Elm Street
First International Building
Dallas, Texas 75270

cc w/enclosures & incoming dtd:
4/17 & 4/21/78
Director, Bureau of Environmental
Health Services
4815 West Markham Street
Little Rock, Arkansas 72201

for this facility. The B&W ECCS Evaluation Model had been previously found to conform to the requirements of the Commission's ECCS Acceptance Criteria, 10 CFR Part 50.46 and Appendix K. The evaluation indicated that with the limits set forth in the facility's Technical Specifications, the ECCS cooling performance for the facility would conform with the criteria contained in 10 CFR 50.46(b) which govern calculated peak clad temperature, maximum cladding oxidation, maximum hydrogen generation, coolable geometry and long-term cooling.

On April 12, 1978, B&W informed the NRC that it had determined that in the event of a small break LOCA on the discharge side of a reactor coolant pump, high pressure injection (HPI) flow to the core could be reduced somewhat. Subsequent calculations indicated that in such a case the calculated peak clad temperature might exceed 2200F.

Previous small break analyses for B&W 177 fuel assembly (FA) lowered loop plants had identified the limiting small break to be in the suction line of the reactor coolant pump. For this assumed break location all high pressure ECCS flow injected into the system would add to the reactor coolant inventory once the coolant level decreased to the height of the reactor vessel nozzles.

Recently, B&W concluded that previous analyses did not consider that some of the high pressure injection (HPI) flow would be lost if the break were located in the discharge line. As a result, recent analyses have shown that the discharge line break is more limiting than the suction line break.

The Arkansas Nuclear One - Unit No. 1 plant has an ECCS configuration which consists of two high pressure injection (HPI) trains. Each train has a HPI pump and the train injects into two of the four reactor coolant system

(RCS) cold legs on the discharge side of the RCS pump. (There is also a third HPI pump installed.) The two parallel HPI trains are connected but are kept isolated by manual valves (known as the cross-over valves) that are normally closed. Upon receiving a safety injection signal the HPI pumps are started and valves in the four injection lines are opened. Assuming loss of offsite power and the worst single failure (failure of diesel to start) only one HPI pump would be available and two of the four injection valves would fail to open.

If a small break is postulated to occur in the RCS piping between the RCS pump discharge and the reactor vessel, the high pressure injection flow injected into this line (about half of the output of one high pressure pump) could flow out the break. Therefore, for the worst combination of break location and single failure, only one-half of the flow rate of a single high pressure ECCS pump would contribute to maintaining the coolant inventory in the reactor vessel. This situation had not been previously analyzed and B&W had indicated that the limits specified in 10 CFR 50.46 may be exceeded.

B&W has stated that they have analyzed a spectrum of small breaks in the pump discharge line and have determined that to meet the limits of 10 CFR 50.46, operator action is required to open the two manual operated crossover valves and to manually align the two motor driven isolation valves which had failed to open. This would allow the flow from the one

HPI pump to feed all four reactor coolant legs. B&W has assumed that 30% of the flow would be lost through the break and 70% would refill the core. The licensee has committed to provide for the necessary operator actions within the required time frame. That is, in the event of a small break and a limiting single failure, manual action will be taken to begin opening these valves within five minutes and have them fully opened and an adequate flow split obtained within 10 minutes. The analyses performed by B&W assumed that the flow split was established at 650 seconds by operator action. We conclude that the analyses are a reasonable approximation of the operator action that actually will be taken, provided specific procedures are prepared and followed to assure such action.

B&W has stated that a $.1 \text{ ft.}^2$ discharge line break, with the aforementioned operator actions, is the most limiting case. To arrive at this conclusion, B&W has performed analyses at break sizes of $.5$, $.2$, $.1$, and $.04 \text{ ft.}^2$, with and without the assumed operator action. The results for a power of 2568 Mw, which were obtained using an approved Appendix K model for blowdown, indicate core uncover for about 250 seconds for the 0.1 ft.^2 limiting break. For this break size B&W has conservatively estimated the peak clad temperature to be approximately 1200 F; well below the limits of 10 CFR 50.46(b).

B&W has indicated the manner in which the calculational methods have been revised and has indicated that their revised calculations are wholly in conformance with the requirements of 10 CFR 50.46. However, B&W has not yet had the opportunity to fully present the result of its calculations to the licensee for submittal to the NRC staff, and the staff has accordingly not had the opportunity to fully assess the new calculations. Until the licensee and the staff have an opportunity to review the B&W revised calculations, the staff has recommended and the licensee has agreed, that operating conditions be limited to a range in which ECCS performance for small break conditions is less sensitive to specific calculation inputs.

For this facility, with operation up to 2311 hwt, ECCS performance calculations for the limiting small break does not even result in core uncovering, if appropriate operator action is properly taken (as described above), thus providing a very substantial margin on peak clad temperature below the limits of 10CFR50.46(b).

Therefore, until the staff has had the opportunity to fully assess the B&W revised calculations, operation of the facility at the power level specified in this Order, and in accordance with the operating procedures specified in this Order, will assure that the ECCS

will conform to the performance requirements of 10 CFR 50.46(b). Accordingly, such limits provide reasonable assurance that the public health and safety will not be endangered. Upon notification by the NRC staff, the licensee committed to provide the staff with B&W's reevaluation of ECCS performance applicable to the licensee's facility as promptly as possible, to limit operation as specified herein, and to submit a technical specification requiring appropriate operating procedures to assure required operator action as discussed herein. Such procedures were described and the commitments confirmed by the licensee's letter of April 17, 1978, supplemented by letters dated April 21, 1978. The staff believes that the licensee's action, under the circumstances, is appropriate and that this action should be confirmed by NRC Order. Upon satisfactory completion of our assessment of the revised evaluation, we will accordingly modify the authorization to operate the facility.

IV.

Copies of the following document are available for inspection at the Commission's Public Document Room at 1717 H Street, Washington, D.C. 20555, and are being placed in the Commission's local public document room at the Arkansas Polytechnic College, Russellville, Arkansas.


- (1) Letters from Mr. Donald A. Rueter to Mr. R. W. Reid, Chief Operating Reactors Branch #4, dated April 17 and 21, 1978, and from Mr. Daniel H. Williams to Mr. R. W. Reid dated April 21, 1978.

Accordingly, pursuant to the Atomic Energy Act of 1954, as amended, and the Commission's Rules and Regulations in 10 CFR Parts 2 and 50, IT IS ORDERED THAT Facility Operating License No. DPR-51 is hereby amended by adding the following new provisions:

- (1) As soon as possible, the licensee shall submit a reevaluation wholly in conformance with 10CFR50.46 of ECCS cooling performance calculated in accordance with the B&W Evaluation Model for operation with operating procedures described in its letters of April 17, 1978, and April 21, 1978,
- (2) Until further authorization by the Commission, the power level shall not exceed 2311 Mwt, and

(3) Until further authorization by the Commission, the licensee shall operate in accordance with the procedures described in its letter of April 17, 1978, supplemented by letters dated April 21, 1978.

FOR THE NUCLEAR REGULATORY COMMISSION


Victor Stello, Jr., Director
Division of Operating Reactors
Office of Nuclear Reactor Regulation

Dated at Bethesda, Maryland,
this 21st day of April 1978.