

From: "DAVANT, GUY H" <GDAVANT@entergy.com>
To: "nxk@nrc.gov" <nxk@nrc.gov>
Date: 5/1/02 9:14AM
Subject: ANO-2 MNSA Repairs

Kaly,

A status of the ANO-2 MNSA repairs:

Five pressurizer heater sleeve nozzles were found leaking during walkdowns following shutdown. MNSAs were installed on these nozzles during the outage. One additional pressurizer heater sleeve nozzle was found leaking during a heatup walkdown in preparation for power ascension. ANO-2 is shutting down to install a MNSA on this nozzle.

If you have any other questions, please give me a call.

Guy

CC: "BURFORD, FRANCIS G" <FBURFOR@entergy.com>, "KRUPA, MICHAEL A" <MKRUPA@entergy.com>, "BENNETT, STEVE A" <SBENNE2@entergy.com>

Docket No. 50-368

Attachment 9