

## **Department of Energy**

Washington, DC 20585

QA: QA

MAY 21 2002

R. R. Dresel Bechtel SAIC Company, LLC 1180 Town Center Drive, M/S 760 Las Vegas, NV 89144

VERIFICATION OF CORRECTIVE ACTIONS AND CLOSURE OF DEFICIENCY REPORT (DR) BSC-02-D-038

The Office of Quality Assurance staff has evaluated the corrective actions of DR BSC-02-D-038 and determined the results to be satisfactory. As a result, the DR is considered closed.

If you have any questions, please contact either James Blaylock at (702) 794-1420 or Dennis C. Threatt at (702) 794-1495.


-James Blaylock for Ram B. Murthy, Acting Director

Office of Quality Assurance

OQA:JB-1216

Enclosure: DR BSC-02-D-038

Durssen!



cc w/encl:

.

-2-

## N. K. Stablein, NRC, Rockville, MD Robert Latta, NRC, Las Vegas, NV S. W. Lynch, State of Nevada, Carson City, NV Engelbrecht von Tiesenhausen, Clark County, Las Vegas, NV Duane Allred, BSC, Las Vegas, NV, M/S 280 R. E. Fray, BSC, Las Vegas, NV S. H. Horton, BSC, Las Vegas, NV R. P. Keele, BSC, Las Vegas, NV, M/S 280 D. T. Krisha, BSC, Las Vegas, NV D. M. Kunihiro, BSC, Las Vegas, NV Nelson O'Connor, BSC, Mercury, NV, M/S 763 F. L. Sanda, BSC, Las Vegas, NV, M/S 280 T. J. Wall, BSC, Las Vegas, NV W. J. Glasser, NQS, Las Vegas, NV D. G. Opielowski, NOS, Las Vegas, NV D. C. Threatt, NQS, Las Vegas, NV J. R. Dyer, DOE/YMSCO, Las Vegas, NV C. E. Hampton, DOE/YMSCO, Las Vegas, NV D. G. Horton, DOE/YMSCO, Las Vegas, NV J. M. Replogle, DOE/YMSCO, Las Vegas, NV V. W. Trebules, DOE/YMSCO, Las Vegas, NV

B. M. Terrell, DOE/YMSCO, Las Vegas, NV

## MAY 21 2002

۰. ۱ –	-		SRIGINAL
RADIOACTIVE U.S. DEPAF	CE OF CIVILIAN WASTE MANAGEME RTMENT OF ENERGY HINGTON, D.C.	1	8. DEFICIENCY REPORT CORRECTIVE ACTION REPORT NO. BSC-02-D-038 PAGE 1 OF
	RECTIVE ACTION RE	POPT	QA: LQA DEC 12/12/01
1. Controlling Document:	RECTIVE ACTION RE	2. Related F	Report No.:
AP-5.1Q, Rev. 2, Plan and Procedure Preparation, Review 3, Responsible Organization: YMSCO	, and Approval 4. Discussed With:	None	
BSC	James Whitcraft, Mary McD	aniel	
5. Requirement: AP-5.1Q, Revision 2, Step 5.6.2b), directs the Responsible revision or ICN by signing and dating the procedure title p	bage:		
"If a Q-designated procedure revision or ICN has incorpor Section 3 of Attachment 12, Expedited Change Notice."	ated an ECN, conduct and doo	cument an ev	aluation in accordance with
<ul> <li>6. Description of Condition:</li> <li>A review of 36 Expedited Change Notices (ECNs) completinitial issuance, June 30, 1999, revealed eight procedures noncompliances with the above requirement:</li> <li>a. Tco instances in which the evaluation was documented</li> <li>b. One instance with Section 3 not completed</li> <li>c. Thirteen instances with a completed ECN not found in</li> <li>d. Four instances in which completion of Section 3 was n</li> <li>Procedures in each of the above categories are as follows:</li> </ul>	with ECN Section 3 completed I after signing and dating the p the Records Information Syst	d satisfactorii procedure titl em	y and the following e page
7. Initiator: Coursellered Date 12-5-0	Yes X No	ondition exist	? (Not required for a DR)
10. Recommended Actions:			
11. QA Review: QAR Liemins Shreatt Date 1-3-	02 12. Response Due D 10 working		issuance
	Signature Jame B 23. Closure Approve	Laylord d by:	tn Date 1/23/02
22. Corrective Actions Verified QAR Junio Occasts Date 4/30/2	DOQA Jam B	Shanglord f	n Date 5/20/02
Exhibit AP-16.1Q.1		LOSURE	Rev. 12/20/199

•

OFFICE OF CIVILIAN RADIOACTIVE WASTE MANAGEMENT U.S. DEPARTMENT OF ENERGY WASHINGTON, D.C.	8. X DR/CAR Stop Work Order NO. BSC-02-D-0382/12/01 PAGE 2 OF QA: Y CA
DEFICIENCY/CORRECTIVE ACTION REPORT/STOP WORK ORDER	CONTINUATION PAGE
(Continuation page 1)	
<ol> <li>Procedures with ECN Section 3 comleted prior to signing and dating the title page AP-2.19Q, Rev. 0, ECN 1, Quality Assurance Requirements and Description Requirements N Evaluation AP-5.1Q, Rev. 1, ICN 3, BSCN 1, ECN 1, Plan and Procedure Preparation, Review and Appr AP-5.1Q, Rev. 1, ICN 2, ECN 1, Plan and Procedure Preparation, Review and AP-7.4Q, Rev. 5, ECN 1, Evaluation of Suppliers LP-4.1Q-OCRWM, Rev. 0, ICN 2, ECN 1, Procurement Actions NWI-ESF-007Q, Rev. 1, ECN 1, Water Use and Control-Subsurface (Now LP-OM-041Q-M&amp; NWI-ESF-038Q, Rev. 0, ECN 1, Identification And Control Of Items NWI-ESF-049Q, Rev. 0, ECN 1, Steel Set Jacking/Expansion (Now LP-OM-043Q-BSC)</li> </ol>	roval
<ol> <li>Procedures with ECN Section 3 completion after signing and dating the title page AP-3.20Q, Rev. 0, ECN 1, Technical/Design Verification Approval AP-5.2Q, Rev. 0, ICN 1, ECN 1, Testing Work Packages Control AP-7.4Q, Rev. 4, ECN 1, EVALUATION of Suppliers AP-7.6Q, Rev. 0, ICN 1, ECN 1, Procurement of Items and Services AP-SI.1Q, Rev. 2, ICN 4, ECN 1, Software Management LP-3.22Q-M&amp;O, Rev. 0, ECN 1, Technical Review And Approval Of Construction Submittal NWI-ESF-009Q, Rev. 0, ECN 1, Control and Distribution of Surveying Documents (Now LP NWI-ESF-047Q, Rev. 0, ICN 2, ECN 1, Receipt and Handling of Materials and Items QAP-1-0, 6, ECN 1, M&amp;O Organization QAP-7-5, Rev. 2, ECN 1, Acceptance Of Items And Services</li> </ol>	ls -OM-035Q-BSC)
3. Procedure incorporating an ECN with Section 3 not completed AP-15.2Q, Rev. 0, BSCN 1, ECN 1, Control of Nonconformances	
<ul> <li>4. Procedures with completed ECN not found in the Records Information System AP-3.4Q, Rev. 2, BSCN 1, ECN 1, Level 3 Change AP-SI.1Q, Rev. 3, ICN 1, ECN 1, Software Management LP-CAL-005Q-M&amp;O, Rev. 0, ECN 1, M&amp;TE Water Meter Calibration (Now LP-OM-039Q-M LP-CAL-005Q-M&amp;O, Rev. 0, ICN 1, ECN 1, Water Meter Flow Calibration (Now LP-OM-03 NW1-ESF-007Q, Rev. 0, ECN 3, Water Use and Control-Subsurface (Now LP-OM-041Q-M&amp;O NW1-ESF-007Q, Rev. 1, ICN Rev. 1, ECN-001, Water Use and Control-Subsurface (Now LP- NW1-ESF-008Q, Rev. 1, ECN 1, Surveying (Now LP-OM-038Q-M&amp;O) NW1-ESF-010Q, Rev. 0, ECN 1, Accuracy Test for Electronic Distance Meters (Now LP-OM- NW1-ESF-010Q, Rev. 1, ICN 2, ECN 1, Tracers, Fluids, and Materials Estimating, Accountin (Now LP-OM-040Q-M&amp;O) NW1-ESF-022Q, Rev. 0, ECN 1, Ground Support Walkdown, Maintenance, and Repair (Now NW1-ESF-046Q, Rev. 1, ECN 1, Subsurface Controlled Drilling and Blasting Operations NW1-RM-713Q, Rev. 1, ECN 1, Alphaguard &amp; Working Level Monitor Operation, Calibration (Now LP-RP-001Q-M&amp;O)</li> <li>YLP-10.3Q-OQA, Rev. 2, ECN 1, Sampling &amp; Testing of Freshly Mixed Concrete &amp; Concrete (Now LP-QC-001Q-OCRWM)</li> </ul>	9Q-M&O) O) OM-041Q-M&O) 036Q-M&O) g, and Reporting LP-OM-042Q-BSC n, & Performance Checks
	(See continuation page 2)

i

A 100 a 100

Rev. 06/01/1999 2 Gf 10

8. X DR/CAR **OFFICE OF CIVILIAN** Stop Work Order **RADIOACTIVE WASTE MANAGEMENT** D&0 **U.S. DEPARTMENT OF ENERGY** NO. BSC-02-D-038 12/12/01 WASHINGTON, D.C. PAGE 3 OF QA: DEFICIENCY/CORRECTIVE ACTION REPORT/STOP WORK ORDER CONTINUATION PAGE (Continuation page 2) 5. Procedures for which completion of Section 3 was not applicable due to procedure cancellation NLP-5-3, Rev. 1, ICN 3, ECN 1, YMP Site Construction Field Work Authorization Process YLP-10.13Q-OQA, Rev. 1, ECN 6, Rockbolts Installation and Pull Test Inspections, Verification Testing of Rockbolts YLP-10.21Q-OQA, Rev. 0, ECN 2, Monitoring of Maintenance and Operation of Surface Facilities YLP-10.24Q-OQA, Rev. 0, ECN 2, Monitoring of Control and Storage Of Materials Rev. 06/01/1999 Exhibit AP-16.1Q.2 3 of 10

Closed ECNs

...

Enclosure, Page 1

Doc. Number	Version	Document Title	ECN Effective Date	ICN Approval Date	Section 3 Completion
AP-15.2Q	Rev. 0, BSCN 1, ECN 1	Control of Nonconformances	02/13/01	05/21/01	Not
AP-2.19Q	Rev. 0, ECN 1	Quality Assurance Requirements and Description Requirements Matrix and Impact Evaluation	10/03/00	01/04/01	Completed 01/04/01
AP-3.20Q	Rev. 0, ECN 1	Technical/Design Verification	10/16/00	01/19/01	04/03/01
AP-3.4Q	Rev. 2, BSCN 1, ECN 1	Level 3 Change Control	03/02/01	04/11/01	Not Found
AP-5.1Q	Rev. 1, ICN 3, BSCN 1, ECN 1	Plan and Procedure Preparation, Review and Approval	03/21/01	04/19/01	04/19/01
AP-5.1Q	Rev. 1, ICN 2, ECN 1	Plan and Procedure Preparation, Review and Approval	12/20/00	01/24/01	01/24/01
AP-5.2Q	Rev. 0, ICN 1, ECN 1	Testing Work Packages	10/16/00	01/19/01	04/03/01
AP-7.4Q	Rev. 4, ECN 1	Evaluation of Suppliers	10/16/00	08/14/01	09/07/01
AP-7.4Q	Rev. 5, ECN 1	Evaluation of Suppliers	09/04/01	09/18/01	09/04/01
AP-7.6Q	Rev. 0, ICN 1, ECN 1	Procurement of Items and Services	10/16/00	04/30/01	05/15/01
AP-SI.1Q	Rev. 2, ICN 4, ECN 1	Software Management	10/16/00	04/01/01	07/05/01
AP-SI.1Q	Rev. 3, ICN 1, ECN 1	Software Management	06/28/01	10/25/01	Not Found
LP-3.22Q-M&O	Rev. 0, ECN 1	Technical Review And Approval Of Construction Submittals	10/16/00	01/18/01	02/01/01
LP-4.1Q-OCRWM	Rev. 0, ICN 2, ECN 1	Procurement Actions	11/28/00	02/12/01	02/12/01
LP-CAL-005Q-M&O (Now LP-OM-039Q-M&O)	Rev. 0, ECN 1	M&TE Water Meter Calibration	05/18/00	06/13/00	Not Found
LP-CAL-005Q-M&O (Now LP-OM-039Q-M&O)	Rev. 0, ICN 1, ECN 1	Water Meter Flow Calibration	03/21/01	06/06/01	Not Found
NLP-5-3	Rev. 1, ICN 3, ECN 1	Ymp Site Construction Field Work Authorization Process	10/16/00	02/01/01	N/A
NWI-ESF-007Q (Now LP-OM-041Q-M&O)	Rev. 0, ECN 3	Water Use and Control-Subsurface	08/11/99	09/23/01	Not Found
NWI-ESF-007Q (Now LP-OM-041Q-M&O)	Rev. 1, ECN 1	Water Use and Control-Subsurface	09/11/00	11/28/00	11/28/00

4 4 10

1

Closed ECNs

Enclosure, Page 2

Doc. Number	Version	Document Title	ECN Effective Date	ICN Approval Date	Section 3 Completion
NWI-ESF-007Q (Now LP-OM-041Q-M&O)	Rev. 1, ICN 1, ECN-001	Water Use and Control-Subsurface	03/21/01	06/21/01	Not Found
NWI-ESF-008Q (Now LP-OM-038Q-M&O)	Rev. 1, ECN 1	Surveying	02/28/01	06/11/01	Not Found
NWI-ESF-009Q ( Now LP-OM-035Q-BSC)	Rev. 0, ECN 1	Control and Distribution of Surveying Documents	10/28/99	12/02/99	08/23/00
NWI-ESF-010Q (Now LP-OM-036Q-M&O)	Rev. 0, ECN 1	Accuracy Test for Electronic Distance Meters	02/28/01	06/14/01	Not Found
NWI-ESF-016Q (Now LP-OM-040Q-M&O)	Rev. 1, ICN 2, ECN 1	Tracers, Fluids, and Materials Estimating, Accounting, and Reporting	04/02/01	06/21/01	Not Found
NWI-ESF-022Q ( Now LP-OM-042Q-BSC)	Rev. 0, ECN 1	Ground Support Walkdown, Maintenance, and Repair	11/19/99	01/20/00	Not Found
NWI-ESF-038Q	Rev. 0, ECN 1	Identification And Control Of Items	10/16/00	02/19/01	02/08/01
NWI-ESF-046Q	Rev. 0, ECN 1	Subsurface Controlled Drilling and Blasting Operations	10/11/99	11/09/99	Not Found
NWI-ESF-047Q	Rev. 0, ICN 2, ECN 1	Receipt and Handling of Materials and Items	10/16/00	09/14/01	09/24/01
NWI-ESF-049Q (Now LP-OM-043Q-BSC)	Rev. 0, ECN 1	Steel Set Jacking/Expansion	07/05/01	09/18/01	09/03/01
NWI-RM-713Q ( Now LP-RP-001Q-M&O)	Rev. 1, ECN 1	Alphaguard & Working Level Monitor Operation, Calibration, & Performance Checks	09/23/99	01/26/00	Not Found
QAP-1-0	6, ECN 1	M&O Organization	10/16/00	02/12/01	03/07/01
QAP-7-5	Rev. 2, ECN 1	Acceptance Of Items And Services	10/16/00	09/14/01	09/24/01
YLP-10.3Q-OQA ( Now LP-QC-001Q-OCRWM)	Rev. 2, ECN 1	Sampling & Testing of Freshly Mixed Concrete & Concrete Related Materials	09/13/99	02/28/00	Not Found
YLP-10.13Q-OQA	Rev. 1, ECN 6	Rockbolts Installation and Pull Test Inspections, Verification Testing of Rockbolts	09/15/99	04/12/00	N/A
YLP-10.21Q-OQA	Rev. 0, ECN 2	Monitoring of Maintenance and Operation of Surface Facilities	09/27/99	04/12/00	N/A
YLP-10.24Q-OQA	Rev. 0, ECN 2	Monitoring of Control and Storage Of Materials	09/09/99	04/12/00	N/Ā

•

5 2 10

	(C .	(°	
TYPE RESPONSE: Initial Complete Amended	RADIOACTIVE W/ U.S. DEPARTM	OF CIVILIAN ASTE MANAGEMENT MENT OF ENERGY IGTON, D.C.	DR/CAR NO. BSC- 22-D-038 PAGE OF QA: 20 A M-0 2/12/0-
DE	EFICIENCY/CORRECTIVE	ACTION REPORT (RES	PONSE)
14a. Immediate Actions: None Compliance Date:			
14. Remedial Actions: Complete Section 3 of Attack of Attachment 12 for any add submitted to the Records Pro	hment 12 for all procedures listed in ditional ECNs to Q procedures disc ocessing Center.	n Block 6.b and 6.c of this Defice overed during the completion d	ciency Report. Complete Section 3 eficiency. Completed forms will b
15. Extent of Condition: This condition is limited to p NWI-ESF-023Q, R0, ICN0, AP-SI.1Q, R3, ICN2, ECN1 AP-SIII.1Q, R1, ICN0, ECN1 AP-6.1Q, R6, ICN0, ECN1		this Deficiency Report and the f	ollowing ECNs:
16. Cause: (Attach results of r To be provided with the com	root cause detemination prepared in a uplete response	accordance with AP-16.4Q for a s	significant deficiency.)
	ence:		
17. Action to Preclude Recurre To be provided with the com	plete response		
	19. Response b Hete response	y: Nelson (Connor Mul June Sand 13-ros-02 Date 2/12/02 21. Concurrence:	Lew O'leum fry 13/01 Mp 13 F66. 02 fry 13/01 Phone 5-4070

6	٩	10
---	---	----

		· · · · · · · · · · · · · · · · · · ·		DR/CAR NO. BS	C-02-D-038	
Initial		OFFICE OF CIVILIAN		PAGE	OF	. 1
		ACTIVE WASTE MANA			QA: - CA	л 3/
	U.S.	DEPARTMENT OF EN	ERGY	E		
		WASHINGTON, D.C.				-
D	EFICIENCY/COF	RECTIVE ACTION REP	PORT (RESI	PONSE)	<u>.</u>	
4a. Immediate Actions: Jone						
compliance Date:						
4. Remedial Actions:	have been completed	as indicated, for the 14 ECNs i	dentified in Blo	ck 15 of this doc	ument. Correct	ted
cords will be submitted to	the Records Processi	ng Center for inclusion in the a	opropriate recor	ds packages.		
completion Date: March 2	9, 2002					
esponsible Individual: No	elson O'Connor					
5. Extent of Condition:						
					•	
See Continuation Page 1)						
	i cost couco dataminati	on propaged in accordance with A	P-16 40 for a s	ionificant deficien	cv.)	
he problem of incomplete	or unrecorded ECN f	on prepared in accordance with A orms affects virtually all organiz	zations that hav	e utilized the EC	IN process. Inc	e
he problem of incomplete roblem appears to be isola	or unrecorded ECN f	orms affects virtually all organize ECN form. Instructions to con	zations that hav aplete section 3	are not covered	in the portion o	e of
he problem of incomplete roblem appears to be isola P-5.10 that provides spec	or unrecorded ECN f ted to Section 3 of the ific instructions for r	orms affects virtually all organize ECN form. Instructions to con- preparing ECNs. Instructions to	zations that hav nplete section 3 complete Section	are not covered on 3 are included	In process. The in the portion of in Paragraph	e of
he problem of incomplete roblem appears to be isola P-5.1Q that provides spec 6.2 that directs the Respo accement of direction to co	or unrecorded ECN f ted to Section 3 of the fific instructions for p nsible Individual to complete the evaluation	orms affects virtually all organize ECN form. Instructions to con- preparing ECNs. Instructions to omplete the evaluation during the pappears to be appropriate.	zations that hav nplete section 3 complete Section the development	are not covered on 3 are included of ICNs and Rev	IN process. The in the portion o d in Paragraph visions. This	e of
The problem of incomplete roblem appears to be isola .P-5.1Q that provides spect .6.2 that directs the Respondence lacement of direction to complete the instructions to complete	or unrecorded ECN f ted to Section 3 of the fific instructions for p nsible Individual to complete the evaluation the Section 3 are clear a	orms affects virtually all organize ECN form. Instructions to con- preparing ECNs. Instructions to omplete the evaluation during the	zations that hav nplete section 3 complete Section the development	are not covered on 3 are included of ICNs and Rev	IN process. The in the portion o d in Paragraph visions. This	e of
The problem of incomplete roblem appears to be isola AP-5.1Q that provides spect .6.2 that directs the Respon- lacement of direction to com- the instructions to comple Responsible Individuals to	or unrecorded ECN f ted to Section 3 of the dific instructions for p nsible Individual to complete the evaluation the Section 3 are clear a follow the procedure.	orms affects virtually all organize ECN form. Instructions to con- preparing ECNs. Instructions to complete the evaluation during the appears to be appropriate. and unambiguous. The only pla	zations that hav nplete section 3 complete Section the development susible cause of	are not covered on 3 are included of ICNs and Rev	IN process. The in the portion o d in Paragraph visions. This	e f
The problem of incomplete roblem appears to be isola AP-5.1Q that provides spec .6.2 that directs the Respo- lacement of direction to co- the instructions to comple Responsible Individuals to Completion Date: March 5 7 Action to Preclude Becu	or unrecorded ECN f ted to Section 3 of the ific instructions for p nsible Individual to c omplete the evaluation the Section 3 are clear a follow the procedure.	orms affects virtually all organize ECN form. Instructions to com- preparing ECNs. Instructions to complete the evaluation during the appears to be appropriate. and unambiguous. The only pla onsible Individual: Nelson O'C	zations that hav nplete section 3 complete Section the development susible cause of connor	e utilized the EC are not covered on 3 are included of ICNs and Rev this deficiency is	IN process. The in the portion o I in Paragraph visions. This a failure of	
The problem of incomplete roblem appears to be isola IP-5.1Q that provides spec .6.2 that directs the Respondent lacement of direction to complet the instructions to complet tesponsible Individuals to <u>Completion Date: March 5</u> 7. Action to Preclude Recu The issuance of Rev. 3 of A CN or revision would cause	or unrecorded ECN f ted to Section 3 of the ific instructions for p nsible Individual to c omplete the evaluation te Section 3 are clear a follow the procedure. 5, 2002 Resp rrence: .P-5.10 (effective 1-0	orms affects virtually all organize ECN form. Instructions to con- preparing ECNs. Instructions to complete the evaluation during the appears to be appropriate. and unambiguous. The only pla	zations that hav nplete section 3 complete Section the development usible cause of onnor technical LPs re	e utilized the EC are not covered on 3 are included of ICNs and Rev this deficiency is	IN process. The in the portion o d in Paragraph visions. This a failure of	
The problem of incomplete roblem appears to be isola .P-5.1Q that provides spect .6.2 that directs the Respondence lacement of direction to complete .esponsible Individuals to Completion Date: March 2 7. Action to Preclude Recut the issuance of Rev. 3 of A CN or revision would cause Operations organization.	or unrecorded ECN f ted to Section 3 of the dific instructions for p msible Individual to co- pomplete the evaluation se Section 3 are clear a follow the procedure. 5, 2002 Resp rrence: uP-5.1Q (effective 1-0 te unnecessary delays.	orms affects virtually all organize ECN form. Instructions to com- preparing ECNs. Instructions to complete the evaluation during the appears to be appropriate. and unambiguous. The only pland onsible Individual: Nelson O'C 7-02) limits the use of ECNs to This limitation will isolate the	technical LPs re use of future E	e utilized the EC are not covered on 3 are included of ICNs and Rev this deficiency is elated to field act CNs primarily to	IN process. The in the portion of d in Paragraph visions. This a failure of the site	
The problem of incomplete roblem appears to be isola .P-5.1Q that provides spec .6.2 that directs the Respo- lacement of direction to com- the instructions to comple esponsible Individuals to <u>Completion Date: March 5</u> 7. Action to Preclude Recu the issuance of Rev. 3 of A CN or revision would cause Operations organization. Managers and supervisors	or unrecorded ECN f ted to Section 3 of the ific instructions for p nsible Individual to co- pomplete the evaluation te Section 3 are clear a follow the procedure. <u>5, 2002 Resp</u> rrence: LP-5.1Q (effective 1-0 te unnecessary delays.	orms affects virtually all organize ECN form. Instructions to com- preparing ECNs. Instructions to complete the evaluation during the appears to be appropriate. and unambiguous. The only plan <u>onsible Individual: Nelson O'C</u> 7-02) limits the use of ECNs to This limitation will isolate the Organization will receive a det	technical LPs re use of future E	e utilized the EC are not covered on 3 are included of ICNs and Rev this deficiency is elated to field act CNs primarily to	IN process. The in the portion of d in Paragraph visions. This a failure of the site	
The problem of incomplete roblem appears to be isola .P-5.1Q that provides spec .6.2 that directs the Respo- lacement of direction to co- the instructions to comple- tesponsible Individuals to <u>Completion Date: March 5</u> 7. Action to Preclude Recu The issuance of Rev. 3 of A CN or revision would cause Operations organization. Managers and supervisors esponsibilities in completion	or unrecorded ECN f ted to Section 3 of the ific instructions for p nsible Individual to complete the evaluation the Section 3 are clear a follow the procedure. 5, 2002 Resp rrence: uP-5.1Q (effective 1-0 te unnecessary delays. in the Site Operations ng the entire process.	orms affects virtually all organize ECN form. Instructions to com- preparing ECNs. Instructions to complete the evaluation during the appears to be appropriate. and unambiguous. The only plan <u>onsible Individual: Nelson O'C</u> 7-02) limits the use of ECNs to This limitation will isolate the Organization will receive a det	ailed briefing of	e utilized the EC are not covered on 3 are included of ICNs and Rev this deficiency is elated to field act CNs primarily to	IN process. The in the portion of d in Paragraph visions. This a failure of the site	
The problem of incomplete roblem appears to be isola AP-5.1Q that provides spect .6.2 that directs the Respon- lacement of direction to com- the instructions to comple Responsible Individuals to Completion Date: March 2 7. Action to Preclude Recu The issuance of Rev. 3 of A CN or revision would cause Operations organization.	or unrecorded ECN f ted to Section 3 of the ific instructions for p nsible Individual to complete the evaluation the Section 3 are clear a follow the procedure. 5, 2002 Resp rrence: uP-5.1Q (effective 1-0 te unnecessary delays. in the Site Operations ng the entire process. 9, 2002, Resp	orms affects virtually all organize ECN form. Instructions to com- preparing ECNs. Instructions to complete the evaluation during the appears to be appropriate. and unambiguous. The only plane onsible Individual: Nelson O'C 7-02) limits the use of ECNs to This limitation will isolate the Organization will receive a det ponsible Individual: Nelson O'C 19. Response by: Nelson O'Co	ailed briefing of	e utilized the EC are not covered on 3 are included of ICNs and Rev this deficiency is elated to field act CNs primarily to n the ECN proces	IN process. The in the portion of d in Paragraph visions. This a failure of divities when an othe Site ss and their	
The problem of incomplete roblem appears to be isola AP-5.1Q that provides spec .6.2 that directs the Respo- lacement of direction to co- The instructions to comple Responsible Individuals to <u>Completion Date: March 5</u> 7. Action to Preclude Recu The issuance of Rev. 3 of A CN or revision would cause Operations organization. Managers and supervisors esponsibilities in completion Completion Date: March 2 8. Due Date: March 29, 2 For submittal of com	or unrecorded ECN f ted to Section 3 of the ific instructions for p nsible Individual to complete the evaluation the Section 3 are clear a follow the procedure. 5, 2002 Resp rrence: uP-5.1Q (effective 1-0 te unnecessary delays. in the Site Operations ng the entire process. 9, 2002, Resp 002 uplete response	orms affects virtually all organize ECN form. Instructions to com- preparing ECNs. Instructions to complete the evaluation during the appears to be appropriate. and unambiguous. The only plan <u>onsible Individual: Nelson O'C</u> 7-02) limits the use of ECNs to This limitation will isolate the Organization will receive a det	ations that hav nplete section 3 complete Section development usible cause of onnor technical LPs re use of future E ailed briefing of	e utilized the EC are not covered on 3 are included of ICNs and Rev this deficiency is elated to field act CNs primarily to n the ECN proces	IN process. The in the portion of d in Paragraph visions. This a failure of the site	
The problem of incomplete roblem appears to be isola AP-5.1Q that provides spec .6.2 that directs the Respo- lacement of direction to co- The instructions to comple Responsible Individuals to <u>Completion Date: March 5</u> 7. Action to Preclude Recu The issuance of Rev. 3 of A CN or revision would caus Operations organization. Managers and supervisors esponsibilities in completi Completion Date: March 2 8. Due Date: March 29, 2	or unrecorded ECN f ted to Section 3 of the ific instructions for p nsible Individual to complete the evaluation the Section 3 are clear a follow the procedure. 5, 2002 Resp rrence: uP-5.1Q (effective 1-0 te unnecessary delays. in the Site Operations ng the entire process. 9, 2002, Resp 002 uplete response	orms affects virtually all organize ECN form. Instructions to com- preparing ECNs. Instructions to complete the evaluation during the appears to be appropriate. and unambiguous. The only plan <u>onsible Individual: Nelson O'C</u> 7-02) limits the use of ECNs to This limitation will isolate the Organization will receive a det ponsible Individual: Nelson O'C 19. Response by: Nelson O'Co Min 3/2/02 Min Will	zations that hav nplete section 3 complete Section the development susible cause of connor technical LPs re- use of future E- ailed briefing on connor nnor Date March 7,	re utilized the EC are not covered on 3 are included of ICNs and Rev this deficiency is elated to field act CNs primarily to n the ECN proces	IN process. The in the portion of d in Paragraph visions. This a failure of divities when an othe Site ss and their	
he problem of incomplete roblem appears to be isola P-5.1Q that provides spec 6.2 that directs the Respo- lacement of direction to co- he instructions to comple- esponsible Individuals to completion Date: March 2 7. Action to Preclude Recu he issuance of Rev. 3 of A CN or revision would cause operations organization. fanagers and supervisors esponsibilities in completion completion Date: March 2 8. Due Date: March 29, 2	or unrecorded ECN f ted to Section 3 of the ific instructions for p nsible Individual to co- pomplete the evaluation te Section 3 are clear a follow the procedure. 5, 2002 Resp rrence: uP-5.1Q (effective 1-0 te unnecessary delays. in the Site Operations ng the entire process. 9, 2002, Resp 002 uplete response prective action	orms affects virtually all organize ECN form. Instructions to compreparing ECNs. Instructions to complete the evaluation during the appears to be appropriate. and unambiguous. The only pla <u>onsible Individual: Nelson O'C</u> 7-02) limits the use of ECNs to This limitation will isolate the Organization will receive a det ponsible Individual: Nelson O'C 19. Response by: Nelson O'Co Mi 3/2/02 Mi 2/2/02	ailed briefing on connor technical LPs re use of future E ailed briefing on connor Date March 7, nce:	re utilized the EC are not covered on 3 are included of ICNs and Rev this deficiency is elated to field act CNs primarily to n the ECN proces	IN process. The in the portion of d in Paragraph visions. This a failure of divities when an othe Site ss and their we or we or e 5-4070	

(` (`	
OFFICE OF CIVILIAN RADIOACTIVE WASTE MANAGEMENT U.S. DEPARTMENT OF ENERGY	8. X DR/CAR Stop Work Order BSC-02-D-038
WASHINGTON, D.C.	PAGE OF NLC QA: LQA 3/7/02
DEFICIENCY/CORRECTIVE ACTION REPORT/STOP WORK ORDER	
(Continuation Page 1)	OUTINOATION FAGE
<ul> <li>a.) The following ECNs have evaluations (Section 3) documented after signing and dating the pr AP-3.20Q, Rev. 0, ECN 1, Technical/Design Verification Approval AP-5.2Q, Rev. 0, ECN 1, ECN 1, Testing Work Package Control AP-7.4Q, Rev. 4, ECN 1, ECN 1, Testing Work Package Control AP-7.6Q, Rev 0, ICN 1, ECN 1, Procurement of Items and Services AP-7.6Q, Rev 0, ICN 1, ECN 1, Procurement of Items and Services AP-SI.1Q, Rev. 2, ICN 4, ECN 1, Software Management LP-3.22Q-M&amp;O, Rev. 0, ECN 1, Technical Review and Approval of Construction Submittals NWI-ESF-009Q, Rev. 0, ECN 1, Control and Distribution of Surveying Documents NWI-ESF-047Q, Rev. 0, ICN 2, ECN 1, Receipt and Handling of Materials and Items QAP-1-0, 6, ECN 1, M&amp;O Organization QAP-7-5, Rev. 2, ECN 1, Acceptance of Items and Services</li> <li>No additional instances of ECN Section 3 completion after signing and dating where discovered v condition. No further actions have been taken on these ECNs.</li> </ul>	
<ul> <li>b.) The following ECN was identified as having incomplete Section 3 not completed: AP-15.2Q, Rev. 0, BSCN 1, ECN 1, Control of Nonconformances</li> <li>Additionally, the following ECNs were discovered to have Section 3 not complete, during the dete AP-SI.1Q, Rev. 3, ICN 2, ECN1, Software Management</li> <li>AP-SIII.3Q, Rev. 1, ECN 1, Submittal and Incorporation of Data to the Technical Data Managem AP-6.1Q, Rev. 6, ICN 0, ECN 1, Controlled Distribution</li> </ul>	
Evaluations have been performed, by Responsible Individuals, for these 4 procedures and are docu forms.	mented on Section 3 of the ECN
<ul> <li>c.) The following ECNs were not found in the Records Information System:</li> <li>AP-3.4Q, Rev. 2, BSCN 1, ECN 1, Level 3 Change</li> <li>AP-SI.1Q, Rev. 3, ICN 1, ECN 1, Software Management</li> <li>LP-CAL-005Q, Rev 0, ICN 1, ECN 1, M&amp;TE Water Meter Calibration</li> <li>NWI-ESF-007Q, Rev. 0, ECN 3, Water Use and Control-Subsurface</li> <li>NWI-ESF-010Q, Rev. 0, ECN 1, Accuracy Test for Electronic Distance Meters</li> <li>NWI-ESF-016Q, Rev. 1, ICN 2, ECN 1, Tracers, Fluids, and Materials Estimating, Accounting, a</li> <li>NWI-ESF-022Q, Rev. 0, ECN 1, Ground Support Walkdown, Maintenance and Repair</li> <li>NWI-ESF-046Q, Rev. 0, ECN 1, Alphaguard &amp; Working Level Monitor Operation Calibration, &amp;</li> <li>YLP-10.3-OQA, Rev. 2, ECN 1, Sampling &amp; Testing of Freshly Mixed Concrete &amp; Concrete Rela</li> </ul>	Performance Checks
ECN forms have been recovered and Section 3 evaluations performed, by Responsible Individuals, procedures.	for each of the previous 10
(See Continuation Page 2)	

<u> </u>	
OFFICE OF CIVILIAN RADIOACTIVE WASTE MANAGEMENT U.S. DEPARTMENT OF ENERGY WASHINGTON, D.C.	8. X DR/CAR Stop Work Order BSC-02-D-038 PAGE OF QA: I- QA - 3/7/2
DEFICIENCY/CORRECTIVE ACTION REPORT/STOP WORK ORDER	CONTINUATION PAGE
(Continuation Page 2) The following ECNs were listed in this DR as not found in the Records Information System, how found and are listed as follows: LP-CAL-005Q-M&O, Rev. 0, ECN 1, M&TE Water Meter Calibration, MOL.20000905.0198 NWI-ESF-007Q, Rev. 1, ICN 1, ECN-001, Water Use and Control-Subsurface, MOL.20011009.0 NWI-ESF-008Q, Rev. 1, ECN 1, Surveying, MOL.20011009.0371	
No other instances of completed ECNs not being found in the Records Information System were extent of condition.	discovered while determining the
d.) The following procedures for which completion of Section 3 was not applicable due to proced in this DR: NLP-5-3, Rev. 1, ICN 3, ECN 1, YMP Site Construction Field Work Authorization Process YLP-10.13Q-OQA, Rev. 1, ECN 6, Rockbolts Installation and Pull Test Inspections, Verification YLP-10.21Q-OQA, Rev. 0, ECN 2, Monitoring of Maintenance and Operation of Surface Facilit YLP-10.24Q-OQA, Rev. 0, ECN 2, Monitoring of Control and Storage of Materials	n Testing of Rockbolts
No further instances of ECNs not applicable due to procedure cancellation were discovered durin condition. No actions were taken on these ECNs.	g the determination of extent of
Completion Date: March 1, 2002	
Responsible Individual: Nelson O'Connor	

\_\_\_\_\_

Rev. 06/01/1999 9 af 10

Submittal Page of OFFICE OF CIVILIAN RADIOACTIVE WASTE MANAGEMENT	✓ DR/CAR/QO SWO
U.S. DEPARTMENT OF ENERGY	NO. BSC-02-D-038
WASHINGTON, D.C.	PAGE OF
WASHINGTON, D.C.	QA: QA
CONDITION ADVERSE TO QUALITY CONTINUATION	PAGE
Verification of corrective action for this DR was conducted by reviewing the following documents:	
AP-3.20Q, Rev. 0, EDN 1, Technical/Design Verification Approval	MOL.20011018.0164
AP-5.2Q, Rev. 0, ICN 1, ECN 1, Testing Work Package Control	MOL.20011018.0166
AP-7.4Q, Rev. 4, ECN 1, Evaluation of Suppliers	MOL.20011018.0168
AP-7.6Q, Rev. 0, ICN 1, ECN 1, Procurement of Items and Services	MOL.20011018.0170
AP-SI.1Q, Rev. 2, ICN 4, ECN 1, Software Management	MOL.20011018.0172
LP-3.22Q-M&O, Rev. 0, ECN 1, Technical Review and Approval of Construction Submittals	MOL.20011018.0174
NWI-ESF-009Q, Rev. 0, ECN 1, Control and Distribution of Surveying Documents	MOL.20000905.0200
NWI-ESF-047Q, Rev. 0, ICN 2, ECN 1, Receipt and Handling of Materials and Items	MOL.20011029.0238
QAP-1-0, Rev. 6, ECN 1, M&O Organization	MOL.20011018.0181
QAP-7-5, Rev. 2, ECN 1, Acceptance of Items and Services	MOL.20011029.0240
AP-15.2Q, Rev. 0, BSCN 1, ECN 1, Control of Nonconformances	MOL.20020312.0175
AP-SI.1Q, Rev. 3, ICN 2, ECN 1, Software Management	MOL.20020417.0177
AP-SIII.3Q, Rev. 1, ECN 1, Submittal and Incorporation of Data to the Technical Data Managemen	t System MOY-020221-10
AP-6.1Q, Rev. 6, ICN 0, ECN 1, Controlled Distribution	MOL.20020312.0187
AP-3.4Q, Rev. 2, BSCN 1, ECN 1, Level 3 Change	MOL.20020312.0179
AP-SI.1Q, Rev. 3, ICN 1, ECN 1, Software Management	MOL.20020312.0185
LP-CAL-005Q, Rev. 0, ICN 1, ECN 1, M&TE Water Meter Calibration	MOL.20020312.0181
NWI-ESF-007Q, Rev. 0, ECN 3, Water Use and Control-Subsurface	MOL.20020312.0165
NWI-ESF-010Q, Rev. 0, ECN 1, Accuracy Test for Electronic Distance Meters	MOL.2002.0312.0177
NWI-ESF-016Q, Rev. 1, ICN 2, ECN 1, Tracers, Fluids, and Material Estimating, Accounting, and	Reporting MOL.20020312.0183
NWI-ESF-022Q, Rev. 0, ECN 1, Ground Support Walkdown, Maintenance and Repair	MOL.20020312.0173
NWI-ESF-046Q, Rev. 0, ECN 1, Subsurface Controlled Drilling and Blasting Operations	MOL.20020312.0171
NWI-RM-713Q, Rev. 1, ECN 1, Alphaguard & Working Level Monitor Operation Calibration & Performance Checks	MOL.20020312.0169
YLP-10.3-OQA, Rev. 2, ECN 1, Sampling & Testing of Freshly Mixed Concrete & Concrete Related Materials	MOL.20020312.0167

In addition to the above, NWI-ESF-023Q, Concrete Batch Plant Operations, Rev. 0, ICN 0, ECN 01, (MOY-020221-10) which was cited in the initial response but not in the complete response was reviewed and was completed according to the required corrective action.

Based on review of objective evidence, it was determined that corrective action for this DR was satisfactorily implemented and it is recommended that this DR be closed.

Dennis Threatt, QAR Date

NOTE: DR committed to a detailed briefing to be provided to managers and supervisors in Site Operations. Reviewed agenda, briefing materials, and attendance rosters of 3/25/02 Weekly Staff Meeting which indicated the detailed briefing was provided. Denuise Theatt 5/14/2002 UP