

February 14, 1996

Mr. John R. McGaha, Jr.
Vice President - Operations
Entergy Operations, Inc.
River Bend Station
P. O. Box 220
St. Francisville, LA 70775

SUBJECT: CORRECTION TO AMENDMENT NO. 87 TO FACILITY OPERATING LICENSE NO.
NPF-47 (TAC NO. M92482) - RIVER BEND STATION, UNIT 1

Dear Mr. McGaha:

On January 29, 1996, the Commission issued Amendment No. 87 to Facility Operating License No. NPF-47 for the River Bend Station, Unit 1. The amendment revised the Technical Specifications (TSs) for the drywell to permit bypass testing on a 10-year frequency with increased testing if performance degrades, changed the drywell air lock testing and surveillance requirements, deleted action notes for the drywell air lock and drywell isolation valves when the bypass leakage limit is not met, and deleted the specific leakage limits for the drywell air lock seal.

An error has been identified on TS page 3.6-61. The error is in the column entitled "FREQUENCY" for Surveillance Requirement (SR) 3.6.5.1.3. The statement following the "AND" should read as follows: "48 months following a test with bypass leakage greater than the bypass leakage limit". A corrected TS page 3.6-61 is enclosed.

Sincerely,

ORIGINAL SIGNED BY:

David L. Wigginton, Senior Project Manager
Project Directorate IV-1
Division of Reactor Projects III/IV
Office of Nuclear Reactor Regulation

Docket No. 50-458

Enclosure: TS page 3.6-61

cc w/encl: See next page

DISTRIBUTION:

DOUGLAS	PUBLIC	PD4-1 r/f	JKilcrease, RIV f/r
PNoonan	OGC (15B18)	DWigginton	
ACRS	JDyer, RIV	GHill (2)	
CGrimes	JRoe	LHurley, RIV	

Document Name: RB92482.COR

OFC	LA/PD4-1	PM/PD4-1
NAME	PNoonan	DWigginton/vw
DATE	2/14/96	2/14/96
COPY	(YES)/NO	(YES)/NO

OFFICIAL RECORD COPY

9602150333 960214
PDR ADDCK 05000458
P PDR

NUREG FILE CENTER CSPV

CR



UNITED STATES
NUCLEAR REGULATORY COMMISSION
WASHINGTON, D.C. 20555-0001

February 14, 1996

Mr. John R. McGaha, Jr.
Vice President - Operations
Entergy Operations, Inc.
River Bend Station
P. O. Box 220
St. Francisville, LA 70775

SUBJECT: CORRECTION TO AMENDMENT NO. 87 TO FACILITY OPERATING LICENSE NO.
NPF-47 (TAC NO. M92482) - RIVER BEND STATION, UNIT 1

Dear Mr. McGaha:

On January 29, 1996, the Commission issued Amendment No. 87 to Facility Operating License No. NPF-47 for the River Bend Station, Unit 1. The amendment revised the Technical Specifications (TSs) for the drywell to permit bypass testing on a 10-year frequency with increased testing if performance degrades, changed the drywell air lock testing and surveillance requirements, deleted action notes for the drywell air lock and drywell isolation valves when the bypass leakage limit is not met, and deleted the specific leakage limits for the drywell air lock seal.

An error has been identified on TS page 3.6-61. The error is in the column entitled "FREQUENCY" for Surveillance Requirement (SR) 3.6.5.1.3. The statement following the "AND" should read as follows: "48 months following a test with bypass leakage greater than the bypass leakage limit". A corrected TS page 3.6-61 is enclosed.

Sincerely,

A handwritten signature in black ink, appearing to read "D. Wigginton", is written over the typed name.

David L. Wigginton, Senior Project Manager
Project Directorate IV-1
Division of Reactor Projects III/IV
Office of Nuclear Reactor Regulation

Docket No. 50-458

Enclosure: TS page 3.6-61

cc w/encl: See next page

Mr. John R. McGaha
Entergy Operations, Inc.

River Bend Station

cc:

Winston & Strawn
ATTN: Mark J. Wetterhahn, Esq.
1400 L Street, N.W.
Washington, DC 20005-3502

Mr. J. E. Venable
Manager - Nuclear Licensing
Entergy Operations, Inc.
River Bend Station
P. O. Box 220
St. Francisville, LA 70775

Mr. Layne McKinney, Director
Joint Operations Cajun
10719 Airline Highway
P. O. Box 15540
Baton Rouge, LA 70895

Senior Resident Inspector
P. O. Box 1051
St. Francisville, LA 70775

President of West Feliciana
Police Jury
P. O. Box 1921
St. Francisville, LA 70775

Regional Administrator, Region IV
U.S. Nuclear Regulatory Commission
611 Ryan Plaza Drive, Suite 1000
Arlington, TX 76011

Ms. H. Anne Plettinger
3456 Villa Rose Drive
Baton Rouge, LA 70806

Administrator
Louisiana Radiation Protection Division
P. O. Box 82135
Baton Rouge, LA 70884-2135

Gary F. Hall
Vice President & Controller
Cajun Electric Power Cooperative
10719 Airline Highway
P.O. Box 15540
Baton Rouge, LA 70895

Mr. Jerry W. Yelverton
Executive Vice President and
Chief Operating Officer
Entergy Operations, Inc.
P. O. Box 31995
Jackson, MS 39286

Mr. Michael B. Sellman
General Manager - Plant Operations
Entergy Operations, Inc.
River Bend Station
Post Office Box 220
St. Francisville, LA 70775

Mr. James J. Fisicaro
Director - Nuclear Safety
Entergy Operations, Inc.
River Bend Station
Post Office Box 220
St. Francisville, LA 70775

Mr. Jerrold G. Dewease
Vice President - Operations Support
Entergy Operations, Inc.
P. O. Box 31995
Jackson, MS 39286-1995

The Honorable Richard P. Ieyoub
Attorney General
State of Louisiana
P. O. Box 94095
Baton Rouge, LA 70804-9095

Wise, Carter, Child & Caraway
Attn: Robert B. McGehee, Esq.
P. O. Box 651
Jackson, MS 39205

SURVEILLANCE REQUIREMENTS (continued)

SURVEILLANCE	FREQUENCY
<p>SR 3.6.5.1.3 Verify bypass leakage is less than or equal to the bypass leakage limit.</p> <p>However, during the first unit startup following bypass leakage testing performed in accordance with this SR, the acceptance criterion is $\leq 10\%$ of the drywell bypass leakage limit.</p>	<p>-----NOTE----- SR 3.0.2 is not applicable for extensions > 12 months. -----</p> <p>24 months following 2 consecutive tests with bypass leakage greater than the bypass leakage limit until 2 consecutive tests are less than or equal to the bypass leakage limit</p> <p><u>AND</u></p> <p>48 months following a test with bypass leakage greater than the bypass leakage limit</p> <p><u>AND</u></p> <p>120 months</p>