Form TI-1 Case Resolution

Case Status	Open	Closed X			
RCODE: 643421 Region: 1					
OLD - Complete Name, Address, Contact, Phone Number:					
Lyndall Nonwovens 860-646-1233					
NEW - Complete Name, Address, Contact, Phone Number:					
Lyndall Eastern, Inc. Lyndall & Folds Division 615 Parker Street Manchester, CT 06045-0151 Bill Franks: President 860-646-1233 ext. 278 or 222					
Agreement State Licensee? (Double Check)	Yes	No X			
Moved to an Agreement State?	Yes	No X			
Describe Follow-up: (Telephone, Int	ternet, Chamber of Commerce, Othe	er)			
Bill Franks, President, said 15 years ago they operated a lab that may have had radioactive devices. He is not aware of possessing any devices now.					
Jeff Griffis, RIII, (on rotation at HQ) stated this case was closed by the contractor and no further regional follow-up is necessary. (E-mail attached)					
Describe Communication with Registration Vendor: None					
Vendor Follow-up Action: None					
Final Action Taken: Updated HQ with findings. Placed in Adams.					
Cause of Bad Address / Lesson Lea	arned: Company address and name o	changed. The NRC was not notified.			

RCODE: 643421

Form TI-2: Device Information

RCODE:								
ID	Model Number	Serial Number	Isotope	Activity (mCi)	Sold Date	Vendor	Status (A or N)	Comments
1	BAL		SR90	100	19952	Honeywell- Measurex Corp.		
2	SCL-1B		SR90	42	19684	LFE Corp.		
For additional GLD's received by the licensee identified during the inspection:								
ID	Model Number	Serial Number	Isotope	Activity	Sold Date	Vendor	Status	Comments

Status Codes: A - Source accounted for N - Source not accounted for

Form TI-3: General Licensee Inspection Documentation

RCOD	E: 2342					
Genera	General Licensee Information:					
	Check Box if Current Complete Name, Mailing Address, Contact, and Phone Number is Same as Provided by ORNL. If not, include correct information below:					
X	Lyndall Eastern, Inc. Lyndall & Folds Division 615 Parker Street Manchester, CT 06045-0151 Bill Franks: President 860-646-1233 ext. 278 and 222					
Results	s of inspection: (check the appropriate boxes)					
	The general licensee of record is located at the address of record and					
	all GLD are accounted for					
	not all GLD are accounted for					
	The general licensee of record is \underline{not} located at the address of record, however GLD are being used under new ownership at the address of record and					
	all GLD are accounted for					
	not all GLD are accounted for					
	The general licensee of record is $\underline{\text{not}}$ located at the address of record, however they are using GLD at another location and					
	all GLD are accounted for					
	not all GLD are accounted for;					
	Neither the general licensee of record nor the facility operated by the general licensee are located at the address of record and the site has been abandoned or is being used for AN alternate purpose.					
Х	Other: (explain)Jeff Griffis, RIII, (on rotation at HQ) stated this case was closed by the contractor and no further regional follow-up is necessary. (E-mail attached)					
Gauge	Information:					
ID	For each gauge for which status is unaccounted for (see last column of Form TI-2), provide any conclusions about location of the gauge:					

Stephanie Tullio, Nuclear Safety Intern Nuclear Materials Safety Branch 2 Inspector:

Approved By: John D. Kinneman, Chief Nuclear Materials Safety Branch 2

RCODE: 643421 3 Completion Date: June 19, 2002

RCODE: 643421 4