



Scott A. Bauer
Department Leader
Regulatory Affairs
Palo Verde Nuclear
Generating Station

10 CFR 50.55a

Tel: 623/393-5978
Fax: 623/393-5442
e-mail: sbauer@apsc.com

Mail Station 7636
P.O. Box 52034
Phoenix, AZ 85072-2034

102-04817-SAB/TNW/RJR
July 16, 2002

U.S. Nuclear Regulatory Commission
ATTN: Document Control Desk
Mail Station P1-37
Washington, DC 20555-0001

Dear Sirs:

**Subject: Palo Verde Nuclear Generating Station (PVNGS)
Units 1,2 and 3 Docket Nos. STN 50-528, 50-529, and 50-530
Unit 2 Second 10-Year Interval – Tenth Refueling Outage Inservice
Inspection Summary**

Pursuant to 10 CFR 50.55a and IWA-6240 of Section XI of the American Society of Mechanical Engineers (ASME) Boiler and Pressure Vessel Code, 1992 Edition, 1992 Addenda, Arizona Public Service Company (APS) hereby submits in enclosure 1 the PVNGS Unit 2 Inservice Inspection Report for the tenth refueling outage. This refueling outage was conducted from March 16, 2002 through April 17, 2002.

This letter does not make any commitments to the NRC.

Please contact Thomas N. Weber at (623) 393-5764 if you have any questions or require additional information.

Sincerely,

SAB/TNW/RJR/kg

Enclosure

cc: E. W. Merschoff
J. N. Donohew
D. G. Naujock
N. L. Salgado

A047

A member of the **STARS** (Strategic Teaming and Resource Sharing) Alliance

Callaway • Comanche Peak • Diablo Canyon • Palo Verde • South Texas Project • Wolf Creek