DISTRIBUTION

20-203 DOCKS1 102 20-582330F

9.16L D T 0.330

Minneapolis, Minnesota 55401 414 Micollet Mall - 8th Floor Muclear Support Services Mr. L. O. Mayer, Manager :NTTA northern States Power Company

Gentlemen:

MONTICELLO MUCLEAR GENERATING PLAMT PRAIRIE ISLAND MUCLEAR GEMERATING PLANT UNLT NOS. 172 าหาดเกา

sen tent 2.11.7.4 noiteotification 4.7.11.2 that has

neen sent to you as part of the Standard Technical Specifications

(SIS) for Fire Protection by letter dated December 6, 1976.

Sincerely,

The state of the s Themal .d sinned tyd her & Isalalao

Division of Operating Reactors Operating Reactors Branch #2 : Dennis L. Ziemann, Chief

TBAbernathy

DEisenhut 018E (3)

ТУМатрась

PWO Connor

RPSnaider

MGrotenhis RMdiggs (2) DLZiemann Tlcarter

ORB #2 Reading Local PDR NKC PDR (3) Docket (3)

EAReeves

VStello

ACRS (16)

OEFD - SLewis/Riddle/GLewis

Specification 4.7.11.2 Euclosure:

See next page cc m/eucj:

-91/ 01/2L

nnsme i Z 10

DOR: 0RB #2

DOR:088 #1

15/10/18

Tywambach

DOK: 0KB #S

79bran29A

12/9/76

15/4/76 MGrotenhuis

DOK:00KB #5

₩201440

SURNAME

Form AEC-318 (Rev. 9-53) AECM 0240 DATE -

TO S. GOVERNMENT PRINTING OFFICE: 1974-526-166



UNITED STATES NUCLEAR REGULATORY COMMISSION WASHINGTON, D. C. 20555

December 10, 1976

Docket Nos. 50-282/306 50-263

> Northern States Power Company ATTN: Mr. L. O. Mayer, Manager Nuclear Support Services 414 Nicollet Mall - 8th Floor Minneapolis, Minnesota 55401

Gentlemen:

RE: PRAIRIE ISLAND NUCLEAR GENERATING PLANT UNIT NOS. 1/2 MONTICELLO NUCLEAR GENERATING PLANT

We are enclosing a corrected Specification 4.7.11.2 that has been sent to you as part of the Standard Technical Specifications (STS) for Fire Protection by letter dated December 6, 1976.

Sincerely,

Dennis L. Ziemann, Chief Operating Reactors Branch #2 Division of Operating Reactors

Enclosure: Specification 4.7.11.2

cc w/encl:
See next page

cc w/enclosure: Gerald Charnoff, Esquire Shaw, Pittman, Potts and Trowbridge 1800 M Street, N. W. Washington, D. C. 20036

Arthur Renquist, Esquire Vice President - Law Northern States Power Company 414 Nicollet Mall Minneapolis, Minnesota 55401

Howard J. Vogel, Esquire Legal Counsel 2750 Dean Parkway Minneapolis, Minnesota 55416

Mr. Steve J. Gadler 2120 Carter Avenue St. Paul, Minnesota 55108

Mr. Kenneth Dzugan Environmental Planning Consultant Office of City Planner Grace Building 421 Wabasha Street St. Paul, Minnesota 55102

Sandra S. Gardebring, Esquire Special Assistant Attorney General Minnesota Pollution Control Agency 1935 W. County Road B2 Roseville, Minnesota 55113

Anthony Z. Roisman, Esquire Roisman, Kessler and Cashdan 1025 15th Street, N. W., 5th Floor Washington, D. C. 20005

The Environmental Conservation Library Minneapolis Public Library 300 Nicollet Mall Minneapolis, Minnesota 55401

PLANT SYSTEMS

SPRAY AND/OR SPRINKLER SYSTEMS

LIMITING CONDITION FOR OPERATION

3.7.11.2 The spray and/or sprinkler systems located in the following areas shall be OPERABLE:

(Plant dependent)

c.

APPLICABILITY: All modes

ACTIONS:

With a spray and/or sprinkler system inoperable establish a continuous fire watch with backup fire suppression equipment in the unprotected area(s), and

- In MODES 1, 2, 3 or 4 restore the system to OPERABLE status within 7 days or be in at least HOT STANDBY within . 6 hours and in COLD SHUTDOWN within the following 30 hours.
- In MODES 5 or 6 restore the system to OPERABLE status within 7 days or prepare and submit a Special Report to the Commission pursuant to Specification 6.9.2 within the next 10 days outlining the cause of inoperability and the plans for restoring the system to OPERABLE status.

SURVEILLANCE REQUIREMENTS

- The spray and/or spinkler systems shall be demonstrated to be 4.7.11.2 OPERABLE:
 - At least once per 92 days by cycling each testable valve through one complete cycle.
 - At least once per 12 months: ь.
 - 1. By performing a system functional test which includes simulated automatic actuation of the system and verifying that the automatic valves in the flow path actuate to their correct positions.
 - By inspection of spray headers to verify their integrity
 - By inspection of each nozzle to verify no blockage.
 - c. At least once per 5 years by an air flow test of the open head spray and/or sprinkler system.