

From: Larry Bell
To: Steven Long
Date: 12/17/01 8:26AM
Subject: Sump Switchover

> NRP

Steve,

I received your voice mail, and I looked at the Owner's Group guidelines. I can see no steps that would require action outside of the control room for sump switchover. As you know, the sump suction valves are opened, the BWST outlet valves are closed, and the HPI recircs should be verified closed. All of these actions can be accomplished from the control room.

I have something that might help your group. We have placed the Owner's Group guidelines on the internal web, and the addresses follow:

CE
http://papaya.nrc.gov/ceepg/index_ceepg.htm

GE
http://papaya.nrc.gov/bwrepg/index_bwr.htm

B&W
http://papaya.nrc.gov/geog/index_baw.htm

We are trying to get an electronic copy of the Westinghouse ERGs and we are working through channels. That takes a while, but if we are successful, we will also post those on our internal web.

Merry Christmas,

Larry Bell

B-203