

Executive Director for Operations Brief

Tuesday, October 2, 2001 4:00 p.m. - 5:00 p.m. Room: O-17B4

Commissioners' Technical Assistants Brief

Wednesday, October 3, 2001 1:00 p.m. - 2:00 p.m.

Room: 18th Floor Commissioners' Conference Room

Purpose:

1) To discuss and focus on the results of the staff's Bulletin 2001-01, "Circumferential Cracking of Reactor Pressure Vessel Head Penetration Nozzles," response reviews for the high susceptibility plants

2) To discuss the basis for the next Regulatory Action to be taken

Success: EDO & Commissioners' Technical Assistants understand the results of the staff's review and the next Regulatory Action(s)

Introduction:

Jake Zimmerman

5 mins.

Discussion of Reviews:

Andrea Lee

20 mins.

Discussion of Next Regulatory Action(s):

Mark Reinhart

20 mins.

Information in this record was deleted in accordance with the Freedom of Information

Act, exemptions 4

EDIA 2002-229

1/2



PROCESS/STATUS/SCHEDULE

Action Items Completed

Bulletin Issued - August 3, 2001

Bulletin Responses Received - September 4, 2001

Preliminary Review of Responses Complete - September 12, 2001

- NRR & RES 7 Submittals
 - Plants that have found Cracking & Leakage (5 plants) Bin 1
 - Plants with High Susceptibility, < 5 EFPY of Oconee 3 (7 plants) Bin 2
- NRR/DLPM PM "Tiger" Team 37 Submittals
 - Plants with Moderate Susceptibility, b/w 5 & 30 EFPY of Oconee 3 (32 plants) Bin 3
 - Plants with Low Susceptibility, > 30 EFPY of Oconee 3 (25 plants) Bin 4

Pre-decisional Information - Not for Public Disclosure Temporary Instruction (TI) Issued to Regions - September 20, 2001

PLANTS WITH CRACKING/LEAKAGE HISTORY (BIN 1) AND HIGH SUSCEPTIBILITY PLANTS (BIN 2)

Plants Oconee 1	Last Inspection		Next Inspection				CCDP* (IPE)	Regulatory Action
	Date	Method Qual Visual - 100%	Date		Method		1	DIAMABAN 7
	11/2000		03/2002	OK:	Qual. Visual - 100%	OK	1E-2 3.5E-3 (Response)	NO
Oconee 2	04/2001	Qual. Visual - 100%		ОК	Qual. Visual - 100%	OK	1E-2 3.5E-3 (Response)	NO
Oconee 3	2/2001	Qual. Visual - 100%	11/2001	ОК	Qual. Visual - 100%	OK	1E-2 3.5E-3 (Response)	NO
ANO-1	03/2001	Qual. Visual - 100%		OK	Qual. Visual - 100%	OK	3E-3	NO NO
D.C. Cook 2	09/1994	ID NDE - 91%	11/2001	OK	Remote Visual & ECT/UT	OK	4.7E-3	NO .
Súrry 1	Spr 2000		10/2001	OK	Qual. Visual • 100%	OK	5.8E-9	NO **
TMI-1	09/1999	Eff. Visual - 100%	10/2001	OK	Qual. Visual - 100%	OK	7.5E-3	
North Anna 1	02/1996	ID NDE - 31%	09/2001	ОК	Qual. Visual (100%) & ECT/UT ****	NO	6.6E-3	YES ****
Robinson	04/2001	Visual - Partial		NO	Qual. Visual • 100% ****	NO.	2E-2	# YES****
Davis-Besse			04/2002		Qual. Visual - 100%	OK	6.9E-3	YES TO SEE
North Anna 2	Spr 2001			NO	Qual. Visual - 100%****	NO	6.6E-3	YES ****
Suny 2	Fall 2000		03/2002	NO:	Qual. Visual - 100%	OK	5.3E-3	YES **

Conditional core damage probability.

Licensee has committed to qualified visual examination per conference call (September 21, 2001).

Prior inspection at last RFO, in accordance with GL 88-05 & GL 97-01.

Licensee may or does not have sufficient information to demonstrate that last inspection was a qualified visual examination.

Rre-decisional Information Not for Public Disclosure

NEXT REGULATORY ACTION

- Adequate Protection
 - Special Circumstance
 - ► Risk
 - Deterministic Standards
- Regulatory Action
 - ▶ Phone call with Licensee
 - Meeting with Licensee
 - Implement Regulatory Action



PERFORMANCE GOALS

Maintain Safety

- Purpose of the bulletin is to collect information to determine if additional regulatory action is necessary
- Information to date provides a sufficient technical basis to show that conditions adverse to quality are being managed for most, but not all plants in the short-term
- Additional cracking should be anticipated long-term management needed

Increase Public Confidence

- Participation at public meetings via telephone
- ▶ Maintaining current information on Bulletin 2001-01 & Alloy 600 Web Sites
- Disciplined and timely reviews of plant-specific responses and regulatory action(s)

Make NRC Activities and Decisions More Effective, Efficient, and Realistic

- Reviews prioritized based on susceptibility groupings and plant outage schedules
- Use of Risk Insights

Reduce Unnecessary Regulatory Burden

- Information requested in the bulletin was minimized
- Stakeholder meetings on resolution of issue (Short- and Long-term)
- Inspection, Assessment, and Repair methods must be developed to manage this issue



STEPS TO SUPPORT REGULATORY ACTION

- Brief NRR Leadership Team 9/20/01 (Complete)
- Brief NRR Executive Team 9/26/01 (Complete)
- NRR Management Phone Calls w/ Licensees' 9/28/01 (Complete)
 - Robinson 2
 - Davis-Besse
 - North Anna 2
 - Surry 2
- Brief Executive Director for Operations 10/2/01



Pre-decisional information Not for Rublic Disclosure

- Brief Commission Technical Assistants 10/3/01
- Brief Committee to Review Generic Requirements 10/11/01