

# Form TI-1 Case Resolution

Case Status:	Open	Closed <input checked="" type="checkbox"/>
RCODE: 41991		
Region: II		
OLD - Complete Name, Address, Contact, Phone Number:		
<b>Consolidation Coal Company</b> <b>Shoemaker Mine</b> <b>Route 3, Big Wheeling Creek Rd.</b> <b>Wheeling, WV 26003</b>		
NEW - Complete Name, Address, Contact, Phone Number:		
<b>Consolidation Coal Company</b> <b>Shoemaker Mine</b> <b>Route 1, Goldenridge Rd.</b> <b>Dallas, WV 26036</b>		
<b>Paul Danko, Plant Superintendent</b> <b>(304) 238-1556</b>		
Agreement State Licensee? (Double Check)	Yes	No <input checked="" type="checkbox"/>
Moved to an Agreement State?	Yes	No <input checked="" type="checkbox"/>
Describe Follow-up: (Telephone, Internet, Chamber of Commerce, Other)		
<p>Visited the Mining Health Safety and Training (MSH&amp;T) office in Fairmont, WV, and spoke to Brian Mills, an inspector (304) 367-2706. Mr. Mills told NRC inspectors that the Shoemaker Mine was still in operation and gave inspectors directions to the mine. Mr. Mills said to contact Tom Olzer in the Safety Office for Shoemaker Mine (304) 238-1508. Inspectors called Mr. Olzer and visited the site. On site, the inspectors spoke to the site superintendent, Paul Danko (304) 238-1556. Two of the three devices in GLTS records were still in use at the plant, and one had been transferred to another plant appropriately. The inspectors also found a new device in operation at the mine that had been transferred and installed according to NRC regulations (see attached transfer report). All of the devices had been leak tested on August 8, 2002, and staff at the mine were familiar with the safe use and regulation of such devices.</p>		
Describe Communication with Registration Vendor: <b>None necessary.</b>		
Vendor Follow-up Action: <b>N/A</b>		
Final Action Taken: <b>Forwarded all information gathered to the GLTS staff in HQ.</b>		
Cause of Bad Address/Lesson Learned: <b>Licensee mailing address changed without notifying NRC. NRC failed to document the data in transfer records sent by this recipient. The plant superintendent showed inspectors copies of transfer reports addressed to the NRC (but GLTS did not show the data from the transfer reports?).</b>		

RCODE: 41991

Licensee Name: **Consolidation Coal Company**

# Form TI-2: Device Information

RCODE: 41991								
ID (Device Key)	Model Number	Serial Number	Isotope	Activity (mCi)	Sold Date	Vendor	Status (A or N)	Comments
349411	5203	B208	Cs-137	1000	19874	TN Technologies, Inc.	A	
349412	5203	B209	Cs-137	1000	19874	TN Technologies, Inc.	A	
349401	5202	B1804	Cs-137	500	19932	TN Technologies, Inc.	A	Transferred to Consolidation Coal (Consol), Bailey Prep Plant in Graysville, PA 19981
For additional GLD's received by the licensee identified during the inspection:								
ID	Model Number	Serial Number	Isotope	Activity	Sold Date	Vendor	Status	Comments
	5202	B2663	Cs-137	100	???? X-fered to plant 19981	TN Technologies, Inc.	A	Transferred from Consolidation Coal (Consol), Bailey Prep Plant in Graysville, PA 19981

\* BAILEY PREP PLANT  
- RCODE 054164

Status Codes:  
A - Source accounted for  
N - Source not accounted for

RCODE: 41991

Licensee Name: Consolidation Coal Company

# Form TI-3: General Licensee Inspection Documentation

RCODE: 41991	
General Licensee Information:	
	Check Box if Current Complete Name, Mailing Address, Contact, and Phone Number is Same as Provided by ORNL. If not, include correct information below:
	<p><b>Consolidation Coal Company</b>  <b>Shoemaker Mine</b>  <b>Route 1, Goldenridge Rd.</b>  <b>Dallas, WV 26036</b></p> <p><b>Paul Danko, Plant Superintendent</b>  <b>(304) 238-1556</b></p>
Results of inspection: (check the appropriate boxes)	
	The general licensee of record is located at the address of record and
	all GLD are accounted for
	<u>not</u> all GLD are accounted for
	The general licensee of record is <u>not</u> located at the address of record, however GLD are being used under new ownership at the address of record and
	all GLD are accounted for
	<u>not</u> all GLD are accounted for
✓	The general licensee of record is <u>not</u> located at the address of record, however they are using GLD at another location and
✓	all GLD are accounted for
	<u>not</u> all GLD are accounted for;
	Neither the general licensee of record nor the facility operated by the general licensee are located at the address of record and the site has been abandoned or is being used for AN alternate purpose.
	Other: (explain) <b>Address of use was good, mailing address was bad.</b>
Gauge Information:	
ID	For each gauge for which status is unaccounted for (see last column of Form TI-2), provide any conclusions about location of the gauge:

Inspector: **N. Jeff Griffis**  
**Materials Licensing and Inspection, Branch 1**

Approved By: **Tom Decker, Chief** *J. L. Hansen*  
**MLIB1**

Completion Date: **10/31/2002**

RCODE: 41991

Licensee Name: **Consolidation Coal Company**

