NOTE TO: Robert M. Bernero, Director

Division of Systems Integration

FROM:

Frank J. Congel, Branch Chief

Radiological Assessment Branch, DSI

SUBJECT: TASK INTERFACE AGREEMENTS CHARGED TO RAB INDICATED AS

UNFINISHED

REFERENCE: Note: Bernero/DSI A/Ds and B/Cs, dated 10-21-85

I have reviewed the list of "delinquent" TIAs provided by your note of 21 October 1985, and see that four TIAs are still charged out to RAB. I have examined each of these four and found that they can be closed out for the following reasons:

TIA 83-120, La Crosse - BWR Pipe Cracks, TAC 53264, due 7-31-84

This TIA concerned the review of the LaCross submittal for pipe cracks. Although RAB never received a submittal, this review was mooted by Generic Letter 84-07, which directed Licensees to request NRR review of the pipe crack repair and/or replacement only if the expected man-rem cumulative dose was greater than 2,000 man-rem. Those licensees who met this criterion either withdrew their submittals or never sent them in. Thus, this TIA should be closed out.

TIA 84-11, Dresden 2 - Fire Protection Issues, TAC 53499, due 8-31-84

This TIA has, apparently, been misassigned to RAB. We do not do fire protection issues, and have no record of this TIA or TAC.

TIA 84-61, Gaseous Effluent Sampling, TAC 40023, due 12-31-85

This is a generic TAC number applied by Helen Nicolaras and assigned to METB and RAB. The problem was strictly METB related, and METB has the issue. RAB should be removed from the TIA.

TIA 85-15, Maine Yankee-Containment Hi Range Monitor, dated 5-30-85

RAB provided assistance to Region I for this effort, attending and participating in an enforcement conference. The licensee is complying with the Region's requirements. This TIA should be closed out.

If you have any questions regarding any of the above, please contact Oliver Lynch, on 2-7542.

Frank J. Congel, Chief

Radiological Assessment Branch

Division of Systems Integration, NRR

cc: D. Muller

J. Miller

0. Lynch

8511040524 851025 CF ADOCK 03000237