



**FPL Energy**  
**Seabrook Station**

FPL Energy Seabrook Station  
P.O. Box 300  
Seabrook, NH 03874  
(603) 773-7000

November 8, 2002

Docket No. 50-443  
NYN-02118

U.S. Nuclear Regulatory Commission  
Attention: Document Control Desk  
Washington, D.C. 20555-0001

Seabrook Station  
Response to Request for Information – Steam Generator Tube

FPL Energy Seabrook, LLC (FPLE Seabrook) provides in the enclosed, the Root Cause Analysis pertaining to the Steam Generator "D" tube cracking issue as requested by the Nuclear Regulatory Commission (NRC) staff during an October 9, 2002 conference call. This root cause analysis reflects information obtained as of November 5, 2002. FPLE Seabrook continues to investigate this issue and will notify the NRC if there are material changes to the analysis.

Should you have any questions pertaining to this matter, please contact Mr. James M. Peschel, Manager - Regulatory Programs at (603) 773-7194.

Very truly yours,

FPL Energy Seabrook, LLC.

Gene F. St. Pierre *FOR GENE ST. PIERRE*  
Station Director  
Seabrook Station

*A001*

U.S. Nuclear Regulatory Commission  
NYN-02118/Page 2

cc:

H. J. Miller, NRC Region 1 Administrator  
R. D. Starkey, NRC Project Manager, Project Directorate I -2  
G. F. Dentel, NRC Senior Resident Inspector