

## APPENDIX C

### SPECIAL AND INFREQUENTLY PERFORMED INSPECTIONS

This appendix lists inspection procedures that are implemented infrequently for special situations. The inspections listed in the table below are to be performed only when authorized by the Regional Administrator after a review and assessment of plant events or conditions, or to fulfill NRC's obligations under domestic interagency memoranda of understanding, or because of participation in international agencies. These inspections are not part of the baseline or supplemental inspection program elements.

IMC 2516, "Policy and Guidance for the License Renewal Inspection Programs," includes IP 71003, "Post-approval Site Inspection for License Renewal." Regions should ensure IP 71003 inspections are conducted when necessary.

Number	Inspection Procedure Title
36100	10 CFR Part 21 Inspections at Nuclear Power Reactors
40001	Resolution of Employee Concerns
50001	Steam Generator Replacement Inspection
60705	Preparation for Refueling
60710	Refueling Activities
60854	Preoperational Testing of an ISFSI
60855	Operation of an ISFSI
60856	Review of 10 CFR 72.212(b) Evaluations
71003	Post-Approval Site Inspection For License Renewal
85102	Material Control and Accounting - Reactors
81001	Independent Spent Fuel Storage Installations
85420	Inspection of IAEA Safeguards For Inspectors at Power Reactors
92050	Review of Quality Assurance For Extended Construction Delay
92709	Licensee Plans for Coping with Strikes
92711	Continued Implementation of Strike Plans During an Extended Strike
92712	Resumption of Normal Operations After a Strike
93001	OSHA Interface Activities
93800	Augmented Inspection Team Implementing Procedure
93812	Special Inspection