

Crystal River Nuclear Facility

Summary Report - NCRs Initiated Since 5/23/02

Sorted by Origination Date, Ar Number, Priority

Selection Criteria: AR Type = NCR and AR Status not = Canceled with Attribute of 1A POT'L OPER/REPORT

AR #	Originator	AR Subject	Orig. Date	AR Status	Priority	Potential Oper/Report	NCR Owner
00061363	SUSAN	MCPHERSON (ERASE THIS MESSAGE AND ENTER TEXT HERE)	20020528	INPROG			CR3 UNITEVAL GRP
00061364	SUSAN	MCPHERSON CR3 ACE APPLICATION NOT FUNTIONING PROPERLY	20020528	H/APPR		N	CR3 UNITEVAL GRP
THE PROCESS TO INITIATE THE RSTEM MODULE WITHIN THE CR3 ACE APPLICATION IS NOT FUNCTIONING AS DESIGNED. WHEN SELECTIN G THE RSTEM BUTTON AFTER LOGGING INTO THE APPLICATION, THE QTURN MODULE IS INITIATED INSTEAD OF THE RSTEM MODULE.							
00061366	LASHAN	LECORN PAYROLL CHECKS DELIVERED TO INCORRECT MAIL DROP	20020528	H/APPR	5	N	CR3 UNITEVAL GRP
TWO EMPLOYEES PAYROLL CHECKS BOTH ADDRESSED TO NU19, WERE I NADVERTENTLY PLACED IN A NAB MAIL POUCH AND SUBSEQUENTLY D ELIVERED TO THE INCORRECT MAIL DROP.							
00061370	BERRY	FOSTER LIVE SEA TURTLE RESCUED AT THE INTAKE	20020528	H/APPR		Y	CR3 UNITEVAL GRP
ON MAY 28, 2002 AT 1700, A SEA TURTLE PREVIOUSLY RESCUED AT CR#3 INTAKE AREA WAS IDENTIFIED BY FPC MARICULTURE STAFF A S A GREEN SEA TURTLE. THIS IS THE 72ND LIVE SEA TURTLE RE SCUE AT THE CRYSTAL RIVER ENERGY COMPLEX IN THIS BIENNIAL P ERIOD. THE TURTLE IS BEING TRANSPORTED TO THE CLEARWATER M ARINE SCIENCE CENTER DUE TO DISTRESS FROM TUMORS. THIS IS R EPORTABLE AS A 4-HOUR REPORT UNDER 10 CFR 50.72 (B) (2) (XI) AS THIS EVENT IS RELATED TO THE PROTECTION OF THE ENVIRON MENT FOR WHICH A NOTIFICATION TO OTHER GOVERNMENT AGENCIES (NATIONAL MARINE FISHERIES SERVICE AND FLORIDA FISH AND WIL DLIFE CONSERVATION COMMISSION) HAS BEEN OR WILL BE MADE. A FOUR HOUR ENS REPORT HAS BEEN MADE TO THE NRC PER 10 CFR 5 0.72 §1816".							
00061371	MARJORIE	FULLER NRC FTS-2001 PHONES OOS FOR SEVERAL HOURS	20020528	H/APPR		N	CR3 UNITEVAL GRP
FTS-2001 PHONES, BOTH AT THE TSC AND EOF, WERE OUT OF SERVI CE FOR SEVERAL HOURS. THIS WAS IDENTIFIED WHEN ONE OF THE PHONES WAS PICKED UP AND LOUD STATIC WAS HEARD. THE REMAIN DER OF THE FTS-2001 PHONES WERE TESTED AND THE SAME STATIC WAS HEARD. THE NRC OPERATIONS CENTER WAS NOTIFIED AT 1100 AND HAD SERVICE RESTORED AT APPROXIMATELY 1600. THE FTS-2 001 PHONES AFFECTED INCLUDED: ENS, HPN, MCL AND RSCL.							
00061372	BRADFORD	TAYLOR OP-707 REV 63 DOES NOT CONTROL ALIGNMENT OF SOME EDG VALVES	20020528	INPROG		N	CR3 UNITEVAL GRP
OP-707 REV 63 DOES NOT REFERENCE CERTAIN INSTRUMENT ISOLATI ON VALVES. THE AFFECTED VALVES ARE DJV-94 THROUGH DJV-97. THE AFFECTED INSTRUMENTS ARE DJ-30-PI THROUGH DJ-33-PI. T HE VALVES PROVIDE ISOLATION TO THE PANEL GAGES LOCATED ON T HE RADIATOR HOUSING OF EGDG-1A AND EGDG-1B, NEAR THE OIL CO OLERS. THE AFFECTED INSTRUMENTS PROVIDE INDICATION OF PUM P SUCTION HEAD FOR THE JACKET WATER AND INTERCOOLER PUMPS O F THE ASSOCIATED DIESEL ENGINE.							