

UNCLASSIFIED
DOCKETED
USMRC

ZYUW
2003 JAN 29 PM 2:40

OFFICE OF THE SECRETARY
RULEMAKINGS AND
ADJUDICATIONS STAFF

UNCLASSIFIED

UUUU

01 04 071000Z MAR 96 RR

HQ AFSC KIRTLAND AFB NM//CC//

ALSAFECOM 002/1996

COMNAVSAFECEN NORFOLK VA//SE//

INFO HQ USAF WASHINGTON DC//XO/SEI//

UNCLAS
SUBJECT: MUTUAL SUPPORT DURING EMERGENCIES & THE EJECTION DECISION

1. RECENT MISHAPS HAVE IDENTIFIED THREE CRITICAL SAFETY CONCERNS THAT NEED TO BE BROUGHT TO THE ATTENTION OF CREWMEMBERS IMMEDIATELY.

2. FIRST, THERE IS AN ALARMING INCREASE IN THE NUMBER OF CREWMEMBERS EJECTING BELOW PUBLISHED MINIMUM EJECTION ALTITUDES IN THE LAST 12 MONTHS. THERE WERE 27 SUCCESSFUL EJECTIONS FROM 24 AIRCRAFT.

OVERALL, THIRTY SEVEN PERCENT (10 EJECTIONS) OCCURRED BELOW PUBLISHED MINIMUMS AND 3 OCCURRED AT THE 2000 FOOT AGL CONTROLLED EJECTION ALTITUDE.

SEVENTY THREE PERCENT (8 OF THE 11 EJECTIONS) IN THE PAST SIX MONTHS WERE BELOW MINIMUMS. THE MAJORITY OF THE ABOVE EJECTIONS OCCURRED IN AIRSPACE FOR WHICH THE CREW HAD MISSION PLANNED AND BRIEFED MINIMUM EJECTION ALTITUDES.

3. A CREWMEMBER THAT EJECTS AT THE 2000 FOOT AGL CONTROLLED EJECTION ALTITUDE HAS APPROXIMATELY ONE MINUTE AND FORTY SECONDS IN THE PARACHUTE. A WELL TRAINED AND DISCIPLINED

ROBERT LEE, LT COL, USAF
HQ AFSC/SEI/6-0853

ORIN E. GODSEY, BRG GEN, CC
CRC: 27980

UNCLASSIFIED

071000ZMAR96

State's
Exhibit 57

UT-48483

SECY-02

Template = secy-028

UNCLASSIFIED

ZYUW

02 04 071000Z MAR 96 RR UUUU

NO

CREWMEMBER, WITH NO COMPLICATIONS, CAN COMPLETE THE REQUIRED POST EJECTION STEPS AND PERFORM A SAFE PARACHUTE LANDING FALL IN THE AVAILABLE TIME. UNFORTUNATELY, THAT SELDOM HAPPENS.

CREWMEMBERS FREQUENTLY BEGIN THEIR PROCEDURES AND CAN BECOME

DISTRACTED UNTIL THEY REALIZE GROUND IMPACT IS IMMINENT.

THEY SELDOM MANEUVER THEIR PARACHUTE TO THE BEST LANDING SITE OR

ORIENT THEMSELVES INTO THE WIND. WHEN THE CREWMEMBER IS NOT IN

CONTROL OF HIS OR HER PARACHUTE LANDING, THE PROBABILITY OF INJURIES

INCREASES. ANY INJURY CAN LEAD TO DELAYED RESCUE, INCREASED INJURY,

CAPTURE, OR DEATH. PRESSING BELOW MINIMUM EJECTION ALTITUDES AND NOT

COMPLETING VITALLY IMPORTANT POST-EJECTION PROCEDURES BEFORE LANDING

ARE UNSAFE PRACTICES THAT MUST BE CORRECTED.

4. ANOTHER SIGNIFICANT PROBLEM HAS BEEN INADEQUATE COMMUNICATIONS

BETWEEN LEAD, WINGMEN, AND/OR OTHER CREWMEMBERS THAT PREVENTED

CORRECT ASSESSMENT OF VARIOUS AIRBORNE SITUATIONS AND TIMELY EJECTION

DECISIONS. RECENT FLIGHT MISHAP REPORTS REVEALED A DOWNWARD

TREND IN THE QUALITY OF MUTUAL SUPPORT DURING NORMAL OPS OR WHEN

FACED WITH AN AIRCRAFT MALFUNCTION OR IN-FLIGHT EMERGENCY (IFE). THE

WELL-PROVEN CHALLENGE AND RESPONSE METHOD APPEARS TO HAVE BROKEN

DOWN. CRITICAL CHECKLIST ACTIONS HAVE BEEN MISSED BY FORMATION

ROBERT LEE, LT COL, USAF
HQ AFSC/SEFL, 6-0853



ORIN L. GODSEY, BRG GEN, CC
CRC: 27980

UNCLASSIFIED 071000ZMAR96

UNCLASSIFIED

03 04 071000Z MAR 96 RR UUUU ZYUW

NO MEMBERS AND UNCHALLENGED BY OTHER PARTICIPANTS. ERRONEOUS ASSUMPTIONS AND POOR AIRMANSHIP HAVE FLOURISHED WITHOUT CHALLENGE. EVEN MORE DISTURBING IS THE FACT THAT IN ALMOST ALL POORLY HANDLED IFE(S), AT LEAST ONE FORMATION MEMBER NOTED THE DISCREPANCIES AND HAD THE SMARTS, THE SOLUTION(S), OR THE TIME TO GET MORE INFORMATION, BUT DID NOT SPEAK UP. THE EXCUSES FOR FAILING TO SUPPORT THE IFE FLIGHT MEMBER INCLUDED: "IT WAS NOT MY AIRCRAFT" OR "I WAS JUST A STUDENT, A WINGEE, OR A BACKSEATER." ALSO, INAPPROPRIATE CHASE FORMATION POSITIONING DURING AN IFE SIGNIFICANTLY DEGRADED THE ABILITY TO SUPPORT THE IFE PILOT AS NOTED ABOVE. FUTILE REPEATED ATTEMPTS TO RECOVER FAILED ENGINES ARE DRIVING CREWS TO CONTROLLED EJECTIONS WELL BELOW THE RECOMMENDED 2000 FEET AGL MINIMUM IN RECENT MISHAPS. THESE DELAYS WERE NOT CHALLENGED BY CHASE PILOTS OR BACKSEATERS BECAUSE OF A RECENT CONTROLLED EJECTION AT LESS THAN 400 FEET AGL. A PILOT SUFFERED SEVERE INJURIES. IT IS IMPERATIVE THAT ALL FORMATION MEMBERS PROVIDE ACTIVE AND FULL FLEDGED SUPPORT DURING IFE(S). HUMAN FACTORS SPECIALISTS INDICATE THAT CREWMEMBERS, WHEN CONFRONTED WITH IFE INDUCED STRESS, MAY NEED EXTERNAL OR INTERPERSONAL INTERVENTION TO ALTER THEIR INAPPROPRIATE PERFORMANCE/ACTIONS.

ROBERT LEE, LT COL, USAF
HQ AFSC/SEFL, 610853

RL
ORIN L. GODSEY, BRG GEN, CC
CRC: 27980

UNCLASSIFIED

071000ZMAR96

UT-48485

UNCLASSIFIED

04 04 071000Z MAR 96 RR

UUUU

ZYUW

NO

5. FINALLY, RECENT SEARCH AND RESCUE COMBAT AIR PATROL (SARCAP) PERFORMANCE FOLLOWING AN EJECTION HAS BEEN POOR. IN SOME INSTANCES, THE SARCAP AIRCRAFT CAME VERY CLOSE TO CRASHING. FAILURE TO MONITOR ALTITUDE AND AIRSPEED HAS CAUSED LOW ALTITUDE WARNINGS IN THE HUD AND VOICE INDICATORS. ANOTHER PROBLEM HAS BEEN CAPPING TOO HIGH, WHICH LIMITS ASSISTANCE TO THE DOWNED CREWMEMBER. ADDITIONALLY, ONE AIRCRAFT PREMATURELY DEPARTED THE SARCAP WITHOUT INSURING THAT THE DOWNED CREWMEMBER WAS VISUALLY ACQUIRED BY RESCUE FORCES. THE PROCEDURES ARE IN PLACE. STRICT ADHERENCE WILL MAXIMIZE AIRCREW SAFETY IN FUTURE MISHAPS/ INCIDENTS.

6. REQUEST YOU BRING THESE ISSUES TO THE ATTENTION OF ALL CREWMEMBERS IMMEDIATELY.

ROBERT LEE, LT COL, USAF
HQ AFSC/SEFL 610853

ORIN L. GODSEY, BRG GEN, CC
CRC: 27980

UNCLASSIFIED

071000ZMAR96

UT-48486

NUCLEAR REGULATORY COMMISSION

License No. _____ **Order No. 57**
In the matter of PFS
Staff _____ IDENTIFIED
Applicant _____ RECEIVED
Intervenor REJECTED _____
Other _____ WITHDRAWN _____
DATE 4/10/02 Witness _____
Clerk _____ pol