

U.S. Nuclear Regulatory Commission
Page 2
February 19, 2003

Enclosed are the TVA commitments. This letter is being sent in accordance with NRC Regulatory Issue Summary 2001-05.

If you have any questions about this change, please telephone me at (423) 843-7170 or J. D. Smith at (423) 843-6672.

Sincerely,



Pedro Salas
Licensing and Industry Affairs Manager

I declare under penalty of perjury that the foregoing is true and correct. Executed on this 19 day of February, 2003.

Enclosures

cc (Enclosures):

Mr. Raj K. Anand, Senior Project Manager
U.S. Nuclear Regulatory Commission
MS 0-8G9
One White Flint North
11555 Rockville Pike
Rockville, Maryland 20852-2739

U.S. Nuclear Regulatory Commission
Page 3
February 19, 2003

JDS:DVG:SJM

Enclosures

cc (Enclosures):

R. J. Adney, LP 6A-C
J. L. Beasley, OPS 4A-SQN
M. J. Burzynski, BR 4X-C
D. L. Koehl, POB 2B-SQN
J. E. Maddox, LP 6A-C
NSRB Support, LP 5M-C
R. T. Purcell, OPS 4A-SQN
J. A. Scalice, LP 6A-C
K. W. Singer, LP 6A-C
E. J. Vigluicci, ET 10A-K
WBN Site Licensing Files, ADM 1L-WBN
EDMS, WTC A-K (RE: S64 030115 800)

ENCLOSURE
TENNESSEE VALLEY AUTHORITY
SEQUOYAH NUCLEAR PLANT (SQN)
UNIT 1
DOCKET NO. 327

TVA COMMITMENTS

The following TVA commitments are compensatory actions that will be in effect when making the 22 lifts described in Topical Report 24370-TR-C-002 during the Unit 1 steam generator replacement outage. These commitments will be specifically proceduralized in our procedure for compensatory measures written for this evolution.

1. Any load drop in the zone where the potential for piping damage exists, TVA will commence an orderly shutdown of Unit 2 in accordance with technical specifications.
2. In the event of a load drop in the zone where the potential for piping damage exists, the four alternate supply valves for the standby emergency diesel generator will be opened immediately to preclude damage to the diesel generators if a start signal is generated due to some reason unrelated to the load drop.
3. In the event of a load drop in the zone where the potential for piping damage exists, an immediate operator action is to ensure that there are at least two running ERCW pumps per train.