

March 3, 2003

Mr. Bryce L. Shriver
Senior Vice President and
Chief Nuclear Officer
PPL Susquehanna, LLC
769 Salem Blvd., NUCSB3
Berwick, PA 18603-0467

SUBJECT: ANNUAL ASSESSMENT LETTER - SUSQUEHANNA STEAM ELECTRIC
STATION (REPORT 50-387/03-01, 50-388/03-01)

Dear Mr. Shriver:

On February 6, 2003, the NRC staff completed its end-of-cycle plant performance assessment of the Susquehanna Steam Electric Station Units 1 and 2. The end-of-cycle review for Susquehanna involved the participation of all technical divisions in evaluating performance indicators (PIs) for the most recent quarter and inspection results for the period from January 1 through December 31, 2002. The purpose of this letter is to inform you of our assessment of your safety performance during this period and our plans for future inspections at your facility so that you will have an opportunity to prepare for these inspections and to inform us of any planned inspections that may conflict with your plant activities.

Overall, both of the Susquehanna units operated in a manner that preserved public health and safety and fully met all cornerstone objectives. Plant performance for the most recent quarter was within the Licensee Response Column of the NRC's Action Matrix, based on all inspection findings being classified as having very low safety significance (Green) and all PIs indicating performance at a level requiring no additional NRC oversight (Green). Therefore, we plan to conduct only baseline inspections at your facility through March 31, 2004.

While Susquehanna's plant performance for the most recent quarter is within the Licensee Response Column of NRC's Action Matrix, there was a safety significant inspection finding during the first three quarters of the assessment cycle where plant performance was within the Regulatory Response Column of NRC's Action Matrix. The one inspection finding of low to moderate safety significance (White) was in the Emergency Preparedness cornerstone and affected both units. The inspection finding involved several occurrences wherein on-shift staffing was below the minimum staffing requirements specified in the Emergency Plan. This White finding was considered for six quarters, rather than the normal four quarters, because of issues associated with PPL's root cause assessment of the White inspection finding. We conducted two supplemental inspections regarding this White finding. The first supplemental inspection concluded that PPL's root cause analysis was narrowly focused and, as a result, we did not have reasonable assurance that PPL's corrective actions would prevent recurrence. We performed a second supplemental inspection after PPL performed a second root cause analysis. In our second supplemental inspection we concluded that PPL had performed a

sufficiently broad evaluation and PPL's actual and planned corrective actions were adequate to address the underlying causes of the White finding.

Additionally, the staff has identified a substantive cross-cutting issue at Susquehanna in the area of human performance. The substantive cross-cutting issue is based on the multiple findings with a common performance deficiency of operators' failure to implement procedures. Our inspection activities documented eight findings of very low safety significance (Green) where operators did not properly implement PPL procedures. These included findings in the Barrier Integrity, Mitigating Systems, and Emergency Preparedness cornerstones. Examples included procedures which controlled 125VDC emergency control power to an emergency diesel generator and emergency service water pumps, seismic protection of 4kV emergency switchgear, reactor water cleanup spent resin transfer, and evaluation and communication of plant conditions during a declared Unusual Event. Although PPL developed a number of initiatives early in 2002 to address operator procedure implementation problems, PPL has not made substantial progress to improve procedure content and standards. Effective actions to reduce human performance errors related to operators' procedure implementation are important because the errors can affect the operability, availability, reliability of risk-significant equipment, and could initiate plant transients during normal and emergency plant operation. We will focus on PPL's progress in addressing this substantive cross-cutting performance issue during our normal baseline inspection program.

Also, on January 13, 2003, the staff issued a Severity Level III Notice of Violation in accordance with the enforcement policy for a problem that occurred on July 26, 2002. Specifically, after PPL loaded a Dry Shielded Canister with 52 spent fuel bundles, PPL incorrectly backfilled the canister with argon gas, rather than helium gas as required by the Certificate of Compliance. In our letter transmitting the violation, we indicated that the staff accepted PPL's corrective action for the violation.

The enclosed inspection plan details the inspections scheduled through March 31, 2004. The inspection plan is provided to minimize the resource impact on your staff and to allow for scheduling conflicts and personnel availability to be resolved in advance of inspector arrival onsite. Routine resident inspections are not listed due to their ongoing and continuous nature. The inspections in the last six months of the inspection plan are tentative and may be revised after our mid-cycle review meeting.

As you are aware, since the terrorist attacks on September 11, 2001, the NRC has issued several Orders and threat advisories to enhance security capabilities and improve guard force readiness. We have conducted inspections to review your implementation of these requirements and have monitored your actions in response to changing threat conditions. For calendar year 2003, we plan to continue these inspections, conduct portions of the security baseline inspection program, as well as perform additional inspections to evaluate your compliance with new requirements that may be ordered. Based on our final determinations in this regard, we will notify you of any inspection plan changes.

In accordance with 10 CFR 2.790 of the NRC's "Rules of Practice," a copy of this letter and its enclosure will be made available electronically for public inspection in the NRC Public Document Room or from the Publicly Available Records (PARS) component of NRC's document system

Mr. Bryce L. Shriver

3

(ADAMS). ADAMS is accessible from the NRC Web site at <http://www.nrc.gov/reading-rm/adams.html> (the Public Electronic Reading Room).

If circumstances arise which cause us to change this inspection plan, we will contact you to discuss the change as soon as possible. Please contact Dr. Mohamed Shanbaky of my staff at 610-337-5209 with any questions you may have regarding this letter or the inspection plan.

Sincerely,

/RA/

A. Randolph Blough, Director
Division of Reactor Projects

Docket Nos. 50-387, 50-388
License Nos. NPF-14, NPF-22

Enclosure: Susquehanna Inspection/ Activity Plan

cc w/encl: J. H. Miller, President - PPL Generation, LLC
R. L. Anderson, Vice President - Nuclear Operations for PPL Susquehanna LLC
R. A. Saccone, General Manager - Nuclear Engineering
A. J. Wrape, III, General Manager, Nuclear Assurance
T. L. Harpster, General Manager - Plant Support
K. Roush, Manager, Nuclear Training
G. F. Ruppert, Manager, Nuclear Operations
J. D. Shaw, Manager, Station Engineering
T. P. Kirwin, Manager, Nuclear Maintenance
R. M. Paley, Manager, Work Management
Director, Bureau of Radiation Protection
R. E. Smith, Jr., Manager, Radiation Protection
W. F. Smith, Jr., Manager, Corrective Action & Assessments
D. F. Roth, Manager, Quality Assurance
R. R. Sgarro, Manager, Nuclear Regulatory Affairs
R. Ferentz, Manager - Nuclear Security
C. D. Markley, Supervisor - Nuclear Regulatory Affairs
M. H. Crowthers, Supervising Engineer
H. D. Woodeshick, Special Office of the President
B. A. Snapp, Esquire, Associate General Counsel, PPL Services Corporation
R. W. Osborne, Allegheny Electric Cooperative, Inc.
Board of Supervisors, Salem Township
J. Johnsrud, National Energy Committee
Supervisor - Document Control Services
Commonwealth of Pennsylvania (c/o R. Janati, Chief, Division of Nuclear Safety,
Pennsylvania Bureau of Radiation Protection)

Distribution w/encl: H. Miller, RA/J. Wiggins, DRA (1)
 A. Blough, DRP
 W. Lanning DRS
 J. Rogge, DRP
 R. Crlenjak, DRS
 M. Shanbaky, DRP
 D. Florek, DRP
 S. Iyer, DRP
 S. Hansell, DRP - SRI Susquehanna
 J. Richmond, DRP - RI Susquehanna
 DRS Branch Chief (5)
 P. Kaufman, DRS
 J. Noggle, DRS
 P. Frechette, DRS
 N. McNamara, DRS
 D. Screnci, ORA
 N. Sheehan, ORA
 T. McGinty, RI EDO Coordinator
 RidsNrrDipmlipb
 Institute of Nuclear Power Operations (INPO)
 R. Laufer, NRR
 R. Guzman, NRR
 T. Colburn, PM, NRR
 D. Skay, NRR (Backup)
 Region I Docket Room (with concurrences)

DOCUMENT NAME: G:\Branch4\Assessment\SUS\2003 SSES ROP 3 EOC Letter_rev4.wpd
 After declaring this document "An Official Agency Record" it **will/will not** be released to the Public. **To receive a copy of this document, indicate in the box: "C"** = Copy without attachment/enclosure **"E"** = Copy with attachment/enclosure **"N"** = No copy

OFFICE	RI/DRP	RI/DRP	RI/DRP
NAME	DFlorek /MMS for/	MShanbaky /MMS/	ABlough /ARB/
DATE	03/03/03	03/03/03	02/28/03

OFFICIAL RECORD COPY

Susquehanna
Inspection / Activity Plan
12/29/2002 - 03/27/2004

Unit Number	Inspection Activity	Title	No. of Staff on Site	Planned Dates		Inspection Type
				Start	End	
	7112102 - OCC RAD SAFETY - ALARA		1			
1, 2	IP 7112102	ALARA Planning and Controls		02/10/2003	02/11/2003	Baseline Inspections
	71122.03 - REMP		1			
1, 2	IP 7112203	Radiological Environmental Monitoring Program		03/03/2003	03/07/2003	Baseline Inspections
	71121 - OCC RAD SAFETY		1			
1, 2	IP 7112101	Access Control to Radiologically Significant Areas		03/17/2003	03/21/2003	Baseline Inspections
1, 2	IP 7112102	ALARA Planning and Controls		03/17/2003	03/21/2003	Baseline Inspections
	7111108 - INSERVICE INSPECTION		1			
2	IP 7111108G	Inservice Inspection Activities - BWR		03/24/2003	03/28/2003	Baseline Inspections
	7111107B - HEAT SINK		1			
1, 2	IP 7111107B	Heat Sink Performance		04/14/2003	04/18/2003	Baseline Inspections
	71151 - EP PI VERIFICATION		1			
1, 2	IP 71151	Performance Indicator Verification		04/21/2003	04/25/2003	Baseline Inspections
	T1148BC - SEC ICM		6			
1, 2	IP 2515/148	Inspection of Nuclear Reactor Safeguards - Interim Compensatory Measures		04/21/2003	04/25/2003	Safety Issues
	7111121 - SSDI		6			
1, 2	IP 7111121	Safety System Design and Performance Capability		04/28/2003	05/02/2003	Baseline Inspections
1, 2	IP 7111121	Safety System Design and Performance Capability		05/12/2003	05/16/2003	Baseline Inspections
	8/11 EXM - OPERATOR LICENSING INITIAL EXAMS		3			
1	U01501	SUSQUEHANNA 1&2 INITIAL EXAM (7/28/03)		07/07/2003	07/11/2003	Not Applicable
1	U01501	SUSQUEHANNA 1&2 INITIAL EXAM (7/28/03)		08/11/2003	08/15/2003	Not Applicable
	71122.02 - RADWASTE		1			
1, 2	IP 7112202	Radioactive Material Processing and Transportation		08/04/2003	08/08/2003	Baseline Inspections
	71121.01 - OCC RAD SAFETY		1			
1, 2	IP 7112101	Access Control to Radiologically Significant Areas		09/29/2003	10/03/2003	Baseline Inspections
1, 2	IP 7112102	ALARA Planning and Controls		09/29/2003	10/03/2003	Baseline Inspections
1, 2	IP 71151	Performance Indicator Verification		09/29/2003	10/03/2003	Baseline Inspections
	7111111B - L O REQUALIFICATION INSPECTION		2			
1, 2	IP 7111111B	Licensed Operator Requalification		10/06/2003	10/10/2003	Baseline Inspections
	7111112B - MAINTENANCE RULE		1			
1, 2	IP 7111112B	Maintenance Effectiveness		12/15/2003	12/19/2003	Baseline Inspections
	71152B - PROBLEM IDENTIFICATION AND RESOLUTION		4			
1, 2	IP 71152B	Identification and Resolution of Problems		01/12/2004	01/16/2004	Baseline Inspections
1, 2	IP 71152B	Identification and Resolution of Problems		01/26/2004	01/30/2004	Baseline Inspections

This report does not include INPO and OUTAGE activities.
This report shows only on-site and announced inspection procedures.

Susquehanna
Inspection / Activity Plan
12/29/2002 - 03/27/2004

Unit Number	Inspection Activity	Title	No. of Staff on Site	Planned Dates		Inspection Type
				Start	End	
	71121	- OCC RAD SAFETY - ALARA	1			
1, 2	IP 7112102	ALARA Planning and Controls		02/09/2004	02/13/2004	Baseline Inspections
	7111108G	- INSERVICE INSPECTION	1			
1	IP 7111108G	Inservice Inspection Activities - BWR		03/08/2004	03/12/2004	Baseline Inspections
	7111117B	- PERMANENT PLANT MODS	3			
1, 2	IP 7111102	Evaluation of Changes, Tests, or Experiments		03/15/2004	03/19/2004	Baseline Inspections
1, 2	IP 7111117B	Permanent Plant Modifications		03/15/2004	03/19/2004	Baseline Inspections