



**UNITED STATES
NUCLEAR REGULATORY COMMISSION
REGION IV
611 RYAN PLAZA DRIVE, SUITE 400
ARLINGTON, TEXAS 76011-4005**

March 4, 2003

J. V. Parrish (Mail Drop 1023)
Chief Executive Officer
Energy Northwest
P.O. Box 968
Richland, Washington 99352-0968

**SUBJECT: ANNUAL ASSESSMENT LETTER - COLUMBIA GENERATING STATION
(REPORT 50-397/2003-01)**

Dear Mr. Parrish:

On February 5, 2003, the NRC staff completed its end-of-cycle plant performance assessment of Columbia Generating Station. The end-of-cycle review for Columbia Generating Station involved the participation of all technical divisions in evaluating performance indicators for the most recent quarter and inspection results for the period from January 1 through December 31, 2002. The purpose of this letter is to inform you of our assessment of your safety performance during this period and our plans for future inspections at your facility so that you will have an opportunity to prepare for these inspections and to inform us of any planned inspections that may conflict with your plant activities.

Overall, Columbia Generating Station operated in a manner that preserved public health and safety and fully met all cornerstone objectives. Plant performance for the most recent quarter was within the Regulatory Response Column of the NRC's Action Matrix, based on a low to moderate (White) inspection finding identified in the Mitigating System Cornerstone. The White finding, which was identified in the first quarter of the assessment period, involved degraded performance of safety-related 4160-volt breakers.

While plant performance for the most recent quarter is within the Regulatory Response Column of the Action Matrix, there was an additional safety significant inspection finding that was present during the first two quarters of the assessment cycle. During the first two quarters, plant performance was within the Degraded Cornerstone Column of the Action Matrix based on a finding of substantial safety significance (Yellow) in the Emergency Preparedness Cornerstone that was identified in the third quarter of 2001. The finding involved the failure to meet the requirements of 10 CFR 50.54(q) in that Columbia Generating Station did not follow and maintain emergency plans and procedures which met the standards in 10 CFR 50.47(b). The licensee's actions associated with this finding were completed during the second quarter of the assessment period. The NRC staff performed a supplemental inspection and verified the adequacy of the corrective actions taken. As a result, plant performance exited the Degraded Cornerstone Column and entered the Regulatory Response Column in July 2002, based on the White finding (discussed above) identified during the first quarter of the assessment period. Subsequently, the licensee completed their corrective actions and the NRC verified the

adequacy of those actions through performance of a supplemental inspection associated with a finding of low to moderate safety significance (White) in December 2002.

In our annual assessment letter dated March 4, 2002, we advised you of a substantive crosscutting issue in the area of human performance. This issue had been identified as a result of multiple findings related to a lack of procedural adherence by numerous personnel. These deficiencies were noted in several areas and affected multiple cornerstones.

The NRC staff conducted a focused problem identification and resolution inspection that reviewed corrective actions to address this human performance crosscutting issue. The NRC staff reviewed performance data and statistics for the past 2 years, which showed marked improvement for the nonoutage period since April 2001. However, because a number of the human performance issues occurred during the previous refueling outage, this issue will remain open to assess the implementation effectiveness of the corrective actions during the scheduled 2003 refueling outage. The effectiveness of these actions will be reviewed as part of the baseline inspection program, including a problem identification and resolution inspection scheduled for June 2003.

The enclosed inspection plan details the inspections scheduled through March 31, 2004. The inspection plan is provided to minimize the resource impact on your staff and to allow for scheduling conflicts and personnel availability to be resolved in advance of inspector arrival onsite. Routine resident inspections are not listed due to their ongoing and continuous nature. The inspections in the last 6 months of the inspection plan are tentative and may be revised at the midcycle review meeting.

As you are aware, since the terrorist attacks on September 11, 2001, the NRC has issued several Orders and threat advisories to enhance security capabilities and improve guard force readiness. We have conducted inspections to review your implementation of these requirements and have monitored your actions in response to changing threat conditions. For calendar year 2003, we plan to continue these inspections and conduct portions of the security baseline inspection program, as well as perform additional inspections to evaluate your compliance with new requirements that may be ordered. Based on our final determinations in this regard, we will notify you of any inspection plan changes.

In accordance with 10 CFR 2.790 of the NRC's "Rules of Practice," a copy of this letter and its enclosure will be made available electronically for public inspection in the NRC Public Document Room or from the Publicly Available Records (PARS) component of NRC's document system (ADAMS). ADAMS is accessible from the NRC Web site at <http://www.nrc.gov/reading-rm/adams.html> (the Public Electronic Reading Room).

If circumstances arise which cause us to change this inspection plan, we will contact you to discuss the change as soon as possible. Please contact William B. Jones at 817/860-8147 with any questions you may have regarding this letter or the inspection plan.

Sincerely,

/RA/

Ellis W. Merschoff
Regional Administrator

Docket: 50-397
License: NPF-21

Enclosure:
Columbia Generating Station
Inspection/Activity Plan

cc w/enclosure:
Rodney Webring (Mail Drop PE04)
Vice President, Nuclear Generation
Energy Northwest
P.O. Box 968
Richland, Washington 99352-0968

Albert E. Mouncer (Mail Drop PE01)
Vice President, Corporate Services/
General Counsel/CFO
Energy Northwest
P.O. Box 968
Richland, Washington 99352-0968

Chairman
Energy Facility Site Evaluation Council
P.O. Box 43172
Olympia, Washington 98504-3172

Douglas W. Coleman (Mail Drop PE20)
Manager, Performance Assessment
and Regulatory Programs
Energy Northwest
P.O. Box 968
Richland, Washington 99352-0968

Energy Northwest

-4-

Christina L. Perino (Mail Drop PE20)
Manager, Licensing
Energy Northwest
P.O. Box 968
Richland, Washington 99352-0968

Chairman
Benton County Board of Commissioners
P.O. Box 190
Prosser, Washington 99350-0190

Dale K. Atkinson (Mail Drop PE08)
Vice President, Technical Services
Energy Northwest
P.O. Box 968
Richland, Washington 99352-0968

Thomas C. Poindexter, Esq.
Winston & Strawn
1400 L Street, N.W.
Washington, D.C. 20005-3502

Bob Nichols
Executive Policy Division
Office of the Governor
P.O. Box 43113
Olympia, Washington 98504-3113

Lynn Albin
Washington State Department of Health
P.O. Box 7827
Olympia, WA 98504-7827

Gary Robertson, Director
Division of Radiation Protection
Department of Health
P.O. Box 47827
Olympia, Washington 98504-7827

Chairman
Board of Benton County Commissioners
P.O. Box 190
Prosser, Washington 99350

Frank H. Brock, Chair
Board of Franklin County Commissioners
1016 North 4th Street
Pasco, Washington 99301

Energy Northwest

-5-

Federal Emergency Management Agency
Federal Regional Center
John Pennington, Regional Director
130 228th Street, SW
Bothell, Washington 98021-9796

Institute of Nuclear Power Operations (INPO)
700 Galleria Parkway SE
Atlanta, Georgia 30339-5943

Electronic distribution by RIV:
 Regional Administrator (**EWM**)
 DRP Director (**ATH**)
 DRS Director (**DDC**)
 Senior Resident Inspector (**GDR**)
 Branch Chief, DRP/E (**WBJ**)
 Senior Project Engineer, DRP/E (**VGG**)
 Staff Chief, DRP/TSS (**PHH**)
 RITS Coordinator (**NBH**)
 V. L. Dricks, PAO (**VLD**)
 W. A. Maier, RSLO (**WAM**)
 C. J. Gordon (**CJG**)
 DRS Branch Chiefs (**TWP, ATG, CSM**)
 W. D. Travers, EDO (**WDT**)
 C. A. Carpenter, Chief, NRR/DIPM/IIPB (**CAC**)
 R. K. Frahm, PPR Program Manager, NRR/DIPM/IIPB (**RKF**)
 R. W. Borchardt, Associate Dir. for Inspection and Programs (**RWB1**)
 B. W. Sheron, Associate Dir. for Project Licensing and Technical Analysis (**BWS**)
 S. Morris, Acting Chief, Regional Operations Staff, OEDO (**SAM1**)
 H. Berkow, NRR Project Director (**HNB**)
 S. Dembek, Chief, Section 2, NRR/DLPM (**SXD**)
 J. Cushing, NRR Project Manager (**JXC9**)
RidsNrrDipmlipb

S:\DRP\DRPDIR\EOC 2003\Assessment Letters\Col.wpd

RIV:C:DRP/E	D:DRS	D:DRP	RA	
WBJones;df;vlh	DDChamberlain	ATHowell	EW Merschoff	
/RA/	/RA/	/RA/	/RA/	
2/27/03	2/27/03	2/28/03	3/4/03	

OFFICIAL RECORD COPY

T=Telephone

E=E-mail

F=Fax

Columbia Generating Station

Inspection / Activity Plan

03/02/2003 - 03/31/2004

Unit Number	Inspection Activity	Title	No. of Staff on Site	Planned Dates Start	Planned Dates End	Inspection Type
	SEC-TI	- SECURITY ORDER VERIFICATION (2515/148)	3			
2	IP 2515/148	Inspection of Nuclear Reactor Safeguards - Interim Compensatory Measures		03/03/2003	03/07/2003	Safety Issues
	EMB	- TRIENNIAL FP	4			
2	IP 7111105T	Fire Protection		03/10/2003	03/21/2003	Baseline Inspections
	ACCESSPI	- ACRSA/PI	1			
2	IP 71151	Performance Indicator Verification		04/07/2003	04/11/2003	Baseline Inspections
2	IP 7112101	Access Control to Radiologically Significant Areas		05/12/2003	05/16/2003	Baseline Inspections
	EMB	- ISI	1			
2	IP 7111108G	Inservice Inspection Activities - BWR		05/19/2003	05/23/2003	Baseline Inspections
	OB-PIR	- CG PIR INSPECTION	5			
2	IP 71152B	Identification and Resolution of Problems		06/02/2003	06/06/2003	Baseline Inspections
2	IP 71152B	Identification and Resolution of Problems		06/16/2003	06/20/2003	Baseline Inspections
	EMB	- HEAT SINK	1			
2	IP 7111107B	Heat Sink Performance		06/09/2003	06/13/2003	Baseline Inspections
	ALARA3	- ALARA PLANNING AND CONTROLS	1			
2	IP 7112102	ALARA Planning and Controls		07/28/2003	08/01/2003	Baseline Inspections
	PSB-EP1	- EP PROGRAM BASELINE INSPECTION	1			
2	IP 7111402	Alert and Notification System Testing		08/11/2003	08/15/2003	Baseline Inspections
2	IP 7111403	Emergency Response Organization Augmentation Testing		08/11/2003	08/15/2003	Baseline Inspections
2	IP 7111404	Emergency Action Level and Emergency Plan Changes		08/11/2003	08/15/2003	Baseline Inspections
2	IP 7111405	Correction of Emergency Preparedness Weaknesses and Deficiencies		08/11/2003	08/15/2003	Baseline Inspections
2	IP 71151	Performance Indicator Verification		08/11/2003	08/15/2003	Baseline Inspections
	PSB-S1	- SECURITY BASELINE INSPECTION	1			
2	IP 7113002	Access Control (Search of Personnel, Packages, and Vehicles: Identification and Authorizat		08/25/2003	08/29/2003	Baseline Inspections
2	IP 7113003	Response to Contingency Events (Protective Strategy and Implementation of Protective Str		08/25/2003	08/29/2003	Baseline Inspections
2	IP 71151	Performance Indicator Verification		08/25/2003	08/29/2003	Baseline Inspections
	EMB	- SSD&PCI	5			
2	IP 7111121	Safety System Design and Performance Capability		09/08/2003	09/12/2003	Baseline Inspections
2	IP 7111121	Safety System Design and Performance Capability		09/22/2003	09/26/2003	Baseline Inspections
	EMB	- 50.59	1			
2	IP 7111102	Evaluation of Changes, Tests, or Experiments		09/09/2003	09/13/2003	Baseline Inspections
	RP-TM	- RAD SAFETY TEAM	4			
2	IP 7112103	Radiation Monitoring Instrumentation and Protective Equipment		09/15/2003	09/19/2003	Baseline Inspections
2	IP 7112201	Radioactive Gaseous and Liquid Effluent Treatment and Monitoring Systems		09/15/2003	09/19/2003	Baseline Inspections

This report does not include INPO and OUTAGE activities.
This report shows only on-site and announced inspection procedures.

Columbia Generating Station

Inspection / Activity Plan

03/02/2003 - 03/31/2004

Unit Number	Inspection Activity	Title	No. of Staff on Site	Planned Dates		Inspection Type
				Start	End	
	RP-TM	- RAD SAFETY TEAM	4			
2	IP 7112202	Radioactive Material Processing and Transportation		09/15/2003	09/19/2003	Baseline Inspections
2	IP 7112203	Radiological Environmental Monitoring Program		09/15/2003	09/19/2003	Baseline Inspections
	ALARA2	- ALARA PLANNING AND CONTROLS	1			
2	IP 7112102	ALARA Planning and Controls		10/20/2003	10/24/2003	Baseline Inspections
	EMB	- MAINTENANCE EFFECTIVENESS	1			
2	IP 711112B	Maintenance Effectiveness		02/09/2004	02/13/2004	Baseline Inspections

This report does not include INPO and OUTAGE activities.
This report shows only on-site and announced inspection procedures.