



FPL Energy
Seabrook Station

FPL Energy Seabrook Station
P.O. Box 300
Seabrook, NH 03874
(603) 773-7000

February 28, 2003

Docket No. 50-443

NYN-03022

U.S. Nuclear Regulatory Commission
Attn.: Document Control Desk
Washington, DC 20555-0001

Seabrook Station
2002 Annual Report of Removable
Contamination from Sealed Source or Fission Detector

Seabrook Station Technical Specification 4.7.8.3 requires a report be prepared and submitted if sealed source or fission detector leakage tests reveal the presence of greater than or equal to 0.005 microCurie of removable contamination. In accordance with this requirement, FPL Energy Seabrook, LLC hereby reports that during 2002, there were no leaking sources.

Should you have any questions, please contact Mr. William T. Cash, Health Physics Department Manager, at (603) 773-7315.

Very truly yours,

FPL Energy Seabrook, LLC



James M. Peschel
Regulatory Programs Manager

cc: H. J. Miller, NRC Region I Administrator
V. Nerses, NRC Project Manager, Project Directorate I-2
G.T. Dentel, NRC Senior Resident Inspector

A001
A017