

STATE CHANGE HISTORY

Initiate



by admin

Done

4/24/2002 12:53:44 PM

Owner (None)

SECTION 1

Activity Request Id: CAP004037  
 Activity Type: CAP Submit Date: 1/11/2000 1:00.00 AM

One Line Description: CST Inner Coating Degrading

Detailed Description: During the inspection of the south condensate storage tank (CST), a film of loose rust was observed on the floor of the tank. Additionally, the lower 6-8" of the tank wall exhibit corrosion through the coating of the tank. \SIGNIFICANCE:\- Degradation of CST.\- Potential ingress of contaminants into the secondary system.\CORRECTIVE ACTION: Operations and engineering personnel were contacted. Operations personnel cleaned the floor of the tank and engineering inspected the tank.\RECOMMENDATIONS:\- Evaluate the condition of the tank coating for possible repair or re-coating.\- Evaluate coating in north CST (T24 B) for similar condition as plant conditions allow.

Initiator: ARNOLD, RICHARD Initiator Department: SCP Chemistry PB

Date/Time of Discovery: 4/24/2002 12:53:44 PM Date/Time of Occurrence: 4/24/2002 12:53:44 PM

Identified By: (None) System: CS PB

Equipment # (1st): (None) Equipment Type (1st): (None)

Equipment # (2nd): (None) Equipment Type (2nd): (None)

Equipment # (3rd): (None) Equipment Type (3rd): (None)

Site/Unit: Point Beach - Common

Why did this occur?:

Immediate Action Taken:

Recommendations:

Notify Me During Eval?: N SRO Review Required?: N

SECTION 2

Operability Status: (None) Compensatory Actions: N

Basis for Operability:

Unplanned TSAC Entry: N External Notification: N

SECTION 3

Screened?: N Significance Level: D

INPO OE Req'd?: N Potential MRFF?: N

QA/Nuclear Oversight?: N Licensing Review?: N

Good Catch/Well Doc'd?: NA

A/1165

SECTION 4

Inappropriate Action:

Process:	N/A - Not Applicable	Activity:	(None)
Human Error Type:	(None)	Human Perf Fail Mode:	(None)
Equip Failure Mode:	(None)	Process Fail Mode:	(None)
Org/Mgt Failure Mode:	(None)	◆ Group Causing Prob:	(None)
Hot Buttons:	(None)		

SECTION 5

CAP Admin:	PBNP CAP Admin	Prescreener:	(None)
◆ Project:	Corrective Action Program (CAP)		
◆ State:	Done	◆ Active/Inactive:	Inactive
◆ Submitter:	admin	◆ Owner:	(None)
AR Type:	Parent	◆ Last Modified Date:	4/24/2002 12:53:44 PM
◆ Last Modifier:	admin	◆ Last State Change Date:	4/24/2002 12:53:44 PM
◆ Last State Changer:	admin	◆ Close Date:	1/13/2000 1:00:00 AM

NUTRK ID: CR 00-0125

# of Children: 0

References: LEVEL CÈCR 00-0129ÈO-RF-240ÈO-RF-245

Update: (01/13/00 PAH) Close to CR 00-0129.

Prescreen Comments: Minor surface rust observed inside T-24A does not appear to have degraded the integrity of the tank. Loose rust and dirt was removed from the floor of the tank prior to filling to prevent its introduction into the condensate system.

Import Memo Field: XU0111:PreScreener//

OPR Completed?: N

OLD\_ACTION\_NUM:

sub\_tsid: 0 original\_project\_id: 0

original\_issue\_id:

Site: Point Beach

Cartridge and Frame:

CHANGE HISTORY

4/24/2002 12:53:46 PM by admin  
 Submit Date Changed From 4/24/2002 12:53 44 PM To 1/11/2000 1:00.00 AM