March 18, 2003

MEMORANDUM TO: Richard J. Laufer, Chief, Section 1

Project Directorate I

Division of Licensing Project Management Office of Nuclear Reactor Regulation

FROM: Timothy G. Colburn, Senior Project Manager, Section 1 /RA/

Project Directorate I

Division of Licensing Project Management Office of Nuclear Reactor Regulation

SUBJECT: QUESTIONS FAXED TO THE LICENSEE RE: BEAVER VALLEY

POWER STATION, UNIT 1 (BVPS 1) PRE-OUTAGE STEAM GENERATOR CONFERENCE CALL (TAC NO. MB7271)

The attached questions have been faxed to the BVPS 1 licensee regarding the NRC staff's requested steam generator pre-outage telephone call. These questions were discussed with the licensee during a conference call held on March 5, 2003.

Docket No. 50-334

Attachment: As stated

March 18, 2003

MEMORANDUM TO: Richard J. Laufer, Chief, Section 1

Project Directorate I

Division of Licensing Project Management Office of Nuclear Reactor Regulation

FROM: Timothy G. Colburn, Senior Project Manager, Section 1 /RA/

Project Directorate I

Division of Licensing Project Management Office of Nuclear Reactor Regulation

SUBJECT: QUESTIONS FAXED TO THE LICENSEE RE: BEAVER VALLEY

POWER STATION, UNIT 1 (BVPS 1) PRE-OUTAGE STEAM

GENERATOR CONFERENCE CALL (TAC NO. MB7271)

The attached questions have been faxed to the BVPS 1 licensee regarding the NRC staff's requested steam generator pre-outage telephone call. These questions were discussed with the licensee during a conference call held on March 5, 2003.

Docket No. 50-334

Attachment: As stated

DISTRIBUTION:
PUBLIC
PDI-1 Reading
RLaufer
MO'Brien
TColburn

Accession Number: ML030770052

OFFICE	PDI-1/PM	PDI-1/LA	PDI-1/SC
NAME	TColburn	MO'Brien	RLaufer
DATE	3/5/03	3/6/03	3/11/03

OFFICIAL RECORD COPY

QUESTIONS FOR BEAVER VALLEY POWER STATION, UNIT 1 PRE-OUTAGE STEAM GENERATOR CALL (TAC NO. MB7271)

Based on the recent findings at Diablo Canyon (circumferential cracking in the U-bend areas of higher row tubes; i.e., rows >4), the NRC staff would like to have a pre-outage call with the Beaver Valley Power Station (BVPS) licensee to:

- 1. Make sure the licensee is aware of the findings at Diablo Canyon.
- 2. Discuss the licensee's plans to address this concern for the upcoming BVPS, Unit 1 outage early next month.
- 3. Discuss the implications of the Diablo Canyon findings on BVPS and, if there are none, to discuss why not.

It would also be helpful to know if BVPS, Unit 1 or BVPS Unit 2 has any operational primary-to-secondary leakage - and if so, how much.

Attachment