

71-9010



Atlanta Corporate Headquarters
655 Engineering Drive
Norcross, Georgia 30092
770-447-1144
Fax 770-447-1797
www.nacintl.com

August 13, 1999

U. S. Nuclear Regulatory Commission
11555 Rockville Pike
Rockville, MD 20852-2738

Attention: Document Control Desk

Subject: Request to Amend the NLI-1/2 Cask Certificate of Compliance
(Docket No. 71-9010)

- References:
1. Certificate of Compliance (CoC) No. 9010, Revision 39, Model No. NLI-1/2, May 26, 1999
 2. Safety Analysis Report for the NLI-1/2 Spent Fuel Shipping Cask USA/9010/B()F, dated May 1999
 3. NAC Letter, Submittal of Additional Changed Pages for the NLI-1/2 Cask SAR, dated July 19, 1999

NAC International (NAC) herewith submits seven copies of changed pages associated with the NLI-1/2 CoC Revision 39 (Reference 1) and Safety Analysis Report Revision May 1999 (Reference 2). A revision to the CoC is requested to accommodate the changes to the cask operating procedures shown in the enclosed SAR revisions. This letter completely supercedes the Reference 3 submittal for the NLI-1/2.

The changed pages incorporate editorial corrections to the operating procedures in the SAR as listed below. Consistent with NAC administrative practice, this proposed revision is numbered uniquely as NLI 1/2-99C to identify the applicable changed pages. Changes on these pages are marked for clarity. Upon final approval, the changed pages will be reformatted and assigned the next appropriate revision identification for the SAR. Please note that all pages containing the affected operating procedures have been included to facilitate review.

The specific changes incorporated in the enclosed changed pages are:

- Page XV-3, Section XV.2, Item 3: Configuration is capitalized.
- Page XV-4, Item 18: Word "to" is inserted after the words "supply line".
- Page XV-7, Item 4: Section number is corrected to be XV.2.3.
- Page XV-11, Item 6: Step numbers are corrected to be #4 and #5.
- Page XV-13, Item 2: Corrected to read, "...barrier portion of ..."
- Page XV-14, Note 4: Second sentence concerning torque wrench accuracy was inappropriate and is removed.

1/1
NTO1

Ltr. Encl.

Change: LA 4 0
PM 1 0

9908230130 990813
PDR ADOCK 07109010
C PDR

190008

ED990550.doc

U.S. Nuclear Regulatory Commission

August 13, 1999

Page 2

If you have any comments or questions, please contact me or Curt Lindner at (770) 447-1144.

Sincerely,

A handwritten signature in cursive script that reads "T. C. Thompson".

Thomas C. Thompson
Director, Licensing & Competitive Assessment
Engineering & Design Services

Enclosures