

From: Paul Krohn
To: Robert Caldwell
Date: 11/14/02 1:09PM
Subject: One More Revision

Bob,

One more update based on a comment I got from Ken O'Brien (a DRS member of the SIT). It would be more accurate to update one of the risk assessment slides to read;

•*The recirculation orifices have been installed on a staggered basis.*

–*U1 TDAFW Pump recirc orifice installed October 2002.*

–*Both MDAFW Pumps recirc orifices installed in November 2001.*

–*Unit 2 TDAFW Pump recirc orifice installed in May 2002.*

•*Common Mode failure exposure time for Unit 1 is ~ 1 month. Common Mode failure exposure time Unit 2 is ~ 5 months.*

This better portrays the time when the 3 AFWPs capable of feeding each Unit all had the recirc orifices installed that were susceptible to plugging. The previous numbers of 23 months etc, may convey a false sense of the common mode failure exposure time.

For you consideration.

Paul Krohn, SRI
Point Beach

CC: Castanedo, Michelle; Kunowski, Michael; Morris, R. Michael; O'Brien, Kenneth;
Riemer, Kenneth; Spaulding, Deirdre

A1336