

From: Steven Long *NK*
To: Mark Kirk, Wallace Norris; William Cullen *WCS*
Date: 5/28/02 8:28AM
Subject: Pictures of Davis-Besse Cavity

I went through my C-drive looking at pictures I have of the Davis-Besse cavity. The ones I attached are the best I have showing the cavity surface and the clad. One picture is the cut surface of the removed head plug that contains the cavity. It gives a decent idea of the variations in the clad thickness at the clad to carbon steel interface. I have seen another phot that looks down on the top of the clad when the cavity was dry, and it shows ridges in the clad material running across the cavity in a direction perpendicular to the major axis of the cavity. I will try to get that picture and forward it to you, later. In the mean time, please sent the attached photos to your contractors, unless they already have them

Steve

B/S2