

From: Steven Long
To: Dwight Snowberger *> NLR*
Date: 6/25/02 1:09PM
Subject: Fwd: SCSS search

B/85

From: "W. P. (Mike) Poore, III" <wpp@ornl.gov>
To: <sml@nrc.gov>
Date: 6/19/02 3:42PM
Subject: SCSS search

OAK RIDGE NAT LAB

Steve,

Attached is a HTM file with the results of an SCSS search for 1980 and newer PWR LERs where the reactor was at power or startup and where pressurizer PORVs or safety valves opened or failed to open and where the pressurizer or the RCS had an actual high pressure condition

Mike

W. P. (Mike) Poore, III
Oak Ridge National Laboratory
PO Box 2009
Oak Ridge, TN 37831-8045
Phone 865.574.0325
Fax 865.574.0382
E-Mail: poorewpiii@ornl.gov

Steve, Attached is a HTM file with the results of an SCSS search for 1980 and newer PWR LERs where the reactor was at power or startup and where pressurizer PORVs or safety valves opened or failed to open and where the pressurizer or the RCS had an actual high pressure condition. Mike W. P. (Mike) Poore, III Oak Ridge National Laboratory PO Box 2009 Oak Ridge, TN 37831-8045 Phone 865 574 0325 Fax 865 574 0382 E-Mail poorewp3iii@ornl.gov