

March 31, 2003

Mr. Lew W. Myers
Chief Operating Officer
FirstEnergy Nuclear Operating Company
Davis-Besse Nuclear Power Station
5501 North State Route 2
Oak Harbor, OH 43449-9760

SUBJECT: DAVIS-BESSE NUCLEAR POWER STATION - INSPECTION SCHEDULE
UPDATE

Dear Mr. Myers:

The purpose of this letter is to provide you with an updated schedule of U. S. Nuclear Regulatory Commission (NRC) inspections at the Davis-Besse Nuclear Power Station so you will have an opportunity to prepare for the inspections or inform us of any conflicts between planned inspections and significant plant activities. This letter is an update to our previous inspection schedule letter dated November 27, 2002.

On April 29, 2002, we informed you of the formation of the NRC's Davis-Besse Oversight Panel under NRC Inspection Manual Chapter 0350, "Oversight of Operating Reactor Facilities in a Shutdown Condition with Performance Problems." The Davis-Besse Oversight Panel assesses facility performance and utilizes the plant's performance indicators to determine the inspections necessary to be completed at the Davis-Besse facility. Where they are valid, it is expected that you will continue to submit performance indicators during the current extended shutdown.

Throughout the past months the NRC has conducted special inspections to review the effectiveness of your efforts to identify and correct the deficiencies that led to the extended shutdown of the Davis-Besse facility. The special inspections have confirmed progress in resolving the issues contained in our Restart Checklist. The NRC will continue special inspections to assess the status of Restart Checklist issue resolution as you complete your problem discovery and corrective actions in each area. The planned and ongoing special inspections are listed in Enclosure 1. Note that the "Safety System Design and Performance Capability" (IP 71111.21), "Permanent Plant Modifications" (IP 71111.17), and "Identification and Resolution of Problems"(IP 71152) inspections previously scheduled between July and December 2003 are incorporated into the special inspections scheduled to be completed prior to facility restart.

Enclosure 2 lists NRC baseline inspection activities that are planned through March 2004. Routine inspections performed by the resident inspectors are not listed due to their ongoing and continuous nature.

The inspection schedule is less firm later in 2003 and 2004 and may be adjusted due to changes in your schedule or emerging performance issues at Davis-Besse or other Region III facilities. In addition, since the terrorist attacks on September 11, 2001, the NRC has issued several Orders and threat advisories to enhance security capabilities and improve guard force readiness. We have conducted inspections to review your implementation of these requirements and have monitored your actions in response to changing threat conditions. For calendar year 2003, we plan to continue these inspections, conduct portions of the security baseline inspection program, and perform additional inspections to evaluate your compliance with any new requirements that may be ordered.

The inspection plan will be adjusted by the Davis-Besse Oversight Panel based on the NRC's assessment of facility performance and progress in addressing the items on the Restart Checklist. You will be notified of any changes in the inspection plan or schedule.

If you have any questions regarding the enclosed inspection plans, please contact Christine Lipa at (630) 829-9619.

Sincerely,

/RA/

John A. Grobe, Chairman
Davis-Besse Oversight Panel

Docket No. 50-346
License No. NPF-3

Enclosures: As stated

cc w/encl: B. Saunders, President - FENOC
Plant Manager
Manager - Regulatory Affairs
M. O'Reilly, FirstEnergy
Ohio State Liaison Officer
R. Owen, Ohio Department of Health
Public Utilities Commission of Ohio
President, Board of County Commissioners
Of Lucas County
President, Ottawa County Board of Commissioners
D. Lochbaum, Union Of Concerned Scientists

L. Myers

-2-

The inspection schedule is less firm later in 2003 and 2004 and may be adjusted due to changes in your schedule or emerging performance issues at Davis-Besse or other Region III facilities. In addition, since the terrorist attacks on September 11, 2001, the NRC has issued several Orders and threat advisories to enhance security capabilities and improve guard force readiness. We have conducted inspections to review your implementation of these requirements and have monitored your actions in response to changing threat conditions. For calendar year 2003, we plan to continue these inspections, conduct portions of the security baseline inspection program, and perform additional inspections to evaluate your compliance with any new requirements that may be ordered.

The inspection plan will be adjusted by the Davis-Besse Oversight Panel based on the NRC's assessment of facility performance and progress in addressing the items on the Restart Checklist. You will be notified of any changes in the inspection plan or schedule.

If you have any questions regarding the enclosed inspection plans, please contact Christine Lipa at (630) 829-9619.

Sincerely,

John A. Grobe, Chairman
Davis-Besse Oversight Panel

Docket No. 50-346
License No. NPF-3

Enclosures: As stated

cc w/encl: B. Saunders, President - FENOC
Plant Manager
Manager - Regulatory Affairs
M. O'Reilly, FirstEnergy
Ohio State Liaison Officer
R. Owen, Ohio Department of Health
Public Utilities Commission of Ohio
President, Board of County Commissioners
Of Lucas County
President, Ottawa County Board of Commissioners
D. Lochbaum, Union Of Concerned Scientists

DOCUMENT NAME: C:\ORPCheckout\FileNET\ML030900753.WPD

To receive a copy of this document, indicate in the box: "C" = Copy without attachment/enclosure "E" = Copy with attachment/enclosure "N" = No copy

OFFICE	RIII	RIII	RIII	RIII
NAME	DPassehl/klg	CLipa	WDean per email	JGrobe
DATE	03/27/03	03/27/03	03/28/03	03/31/03

OFFICIAL RECORD COPY

ADAMS Distribution:

AJM

DFT

SPS1

RidsNrrDipmlipb

GEG

HBC

CST1

C. Ariano (hard copy)

DRPIII

DRSIII

PLB1

JRK1

DB0350

Enclosure 1
Davis-Besse
Special Inspections

Integrated Leak Rate Test Inspection

Normal Operating Pressure Test Inspection

Programmatic Effectiveness Inspection

Sump Modification Inspection

Design Issues-Path A-System Health Readiness and Latent Issue Reviews Inspection

Design Issues-Path B-Safety Function Validation of 10 Systems Inspection

Design Issues-Path C-High Energy Line Break, Environmental Qualification and Seismic Qualification Topical Issue Inspection

Post-Fire Safe Shutdown Topical Issue Inspection*

Management and Human Performance Corrective Action Inspection (Phase 2)

Management and Human Performance Corrective Action Effectiveness Inspection (Phase 3)

Radiation Protection Program Special Inspection and Supplemental Inspection (95002)

Backlog Assessment Inspection

Corrective Action Team Inspection

Restart Readiness Assessment Team Inspection

*Depending on the outcome of the post-fire safe shutdown topical issue inspection, the baseline fire protection triennial inspection (IP 71111.05) will be conducted either from May 5-23, 2003, or during CY 2004.

Enclosure 2
Davis-Besse
Baseline Inspections

<u>Inspection Procedure</u>	<u>Title</u>	<u>Planned Dates</u>	
		<u>Start</u>	<u>End</u>
71111.06	Flood Protection	April 2003	
71122	RAM Process & Transportation	05/12/2003	05/16/2003
71114	Emergency Preparedness Inspection	06/09/2003	06/13/2003
71121	ALARA Review and Instrumentation	07/14/2003	07/18/2003
71111.01	Hot Adverse Weather	August 2003	
71111.12	Maintenance Effectiveness (Biennial)	09/15/2003	09/19/2003
TI 2515/148	Interim Compensatory Measures at Nuclear Plants	09/08/2003	09/12/2003
71121	Occupational Rad Safety Inspection	10/20/2003	10/24/2003
71111.01	Cold Adverse Weather	November 2003	
71114	Baseline EP Inspection & PI Verification	02/09/04	02/13/04
71121.01	Access Control and ALARA	02/09/04	02/13/04