

UNITED STATES
NUCLEAR REGULATORY COMMISSION
OFFICE OF NUCLEAR MATERIAL SAFETY AND SAFEGUARDS
WASHINGTON, D.C. 20555

March 6, 1991

NRC INFORMATION NOTICE NO. 91-16: UNMONITORED RELEASE PATHWAYS FROM SLIGHTLY
CONTAMINATED RECYCLE AND RECIRCULATION WATER
SYSTEMS AT A FUEL FACILITY

Addressees:

All fuel cycle facilities.

Purpose:

This Information Notice is intended to alert addressees to potential problems resulting from using runoff water and process effluents, both contaminated with radioactive materials, in non-nuclear processes. At one fuel facility, the use of these liquids resulted in a concentration and/or release of radioactive material, without an evaluation, to unrestricted areas. It is expected that recipients will review the information for applicability to their facilities and consider actions, as appropriate, to avoid similar problems. However, suggestions contained in this Information Notice do not constitute U.S. Nuclear Regulatory Commission (NRC) requirements; therefore, no specific action or written response is required.

Description of Circumstances:

A fuel facility's recycle water system was used to provide water for non-contact cooling of plant systems, the fire protection system, sanitary facilities, a grit blaster, and gaseous effluent scrubbers. Makeup water for the system was partially obtained by collecting rain water from roof and storm sewer drains. The makeup water became contaminated by particulate fallout from effluent discharges onto the buildings and the nearby ground areas. As a result, the recycle water system became contaminated.

The licensee had routinely analyzed the recycle system water for gross alpha radioactivity. However, the licensee failed to evaluate either the processes which used recycle water and could concentrate the uranium or the release pathways from the recycle water system which released excess water during heavy rain storms. The pathways included overflows from the system reservoir, the cooling tower, and the roof and storm sewer drains. The runoff eventually drained to a nearby river without an analysis for radioactivity. As a result, unmonitored release pathways existed for low levels of radioactivity.

Another unmonitored release pathway for the recycle system was from the facility's fire protection system, which used recycle water as the supply source. When the fire protection system's booster pumps were tested, the pumps discharged onto the open ground. No samples were analyzed for radioactivity before these

9102280279 ZA

IDAR-11C

releases. Additionally, recycle water was periodically provided to a local fire department to refill the water-storage tanks in its fire truck, without analysis for radioactivity. The licensee was aware that the recycle system was slightly contaminated but thought that the transfers of radioactively contaminated water were allowed because the concentrations were below the 10 CFR Part 20 release limits.

Another example of an unmonitored release pathway from the recycle system was from gaseous effluent scrubbers that used the slightly contaminated recycle water for particulate removal. The gaseous exhaust from the scrubbers had been routinely sampled for nitrous oxide but not for radioactivity. Additionally, contaminated scrubber water from two fume scrubbers had been discharged to a nonradioactive holding pond. The pond was part of the licensee's nonradioactive liquid waste treatment facility, and the introduction of the contaminated water may have caused radioactive contamination of the pond.

Recycle water was also used in the licensee's zirconium and copper recovery processes. The recycle water was used in the zirconium recovery process as part of the cleaning process. After recovery, the zirconium was then packaged and sold to various offsite vendors without testing for radioactive contamination. In the copper recovery process, the recycle water was used in the associated scrubber for gaseous effluents. Since contaminated recycle water was used in the scrubber, the transfer of water to the recovery system could have contaminated the copper recovery system and the final copper oxide product. Without testing for radioactive contamination, the product was sold to offsite vendors for use in various products.


Another water system used for the scrubber water was the recirculation water system. During 1984, the licensee installed the recirculation water system which diverted a portion of the final effluent for use in the liquid waste treatment facility. This effluent contained low concentrations of radioactive isotopes that were below 10 CFR Part 20 release limits. The recirculation water was used in the liquid waste treatment facility to prepare the lime slurry for use in both the radioactive and the nonradioactive waste treatment operations to neutralize the acidic solutions and to precipitate fluorides and metals such as aluminum, chromium, zirconium, and uranium. The precipitated sludge from the radioactive waste treatment was shipped offsite for disposal as low-level radioactive waste. The precipitated sludge from the assumed nonradioactive water treatment system was buried onsite in a State-permitted landfill. However, this sludge contained radioactive contaminants from the recirculation water lime slurry, and the State-permitted landfill was not authorized to receive radioactive material.

The licensee has initiated and/or completed corrective actions for both the recycle and the recirculation water systems to eliminate the sources of radioactive contamination and to evaluate all release points. The licensee has eliminated the use of radioactively contaminated recirculation water in the recovery operations and ceased onsite burial of the radioactively contaminated sludge. Further corrective actions will include characterization of the onsite burial areas.

Discussion:

Licensees are reminded that they must make surveys to assure compliance with 10 CFR 20.301 which describes authorized means of disposal of licensed material in waste and must make surveys to assure compliance with 10 CFR 20.106 which limits the yearly average concentration of radioactive material in air or water discharged to unrestricted areas. Furthermore, licensees are reminded that changes in plant design must be evaluated to determine whether the changes will result in the unmonitored release of radioactive material to unrestricted areas.

This Information Notice requires no specific action or written response. If you have any questions about the information in this notice, please contact the technical contact(s) listed below or the appropriate NRR project manager.


Richard E. Cunningham, Director
Division of Industrial and
Medical Nuclear Safety
Office of Nuclear Material Safety
and Safeguards

Technical Contacts: Susan S. Adamovitz, Region II
(404) 331-4774

Edwin D. Flack, NMSS
(301) 492-0405

Attachments:

1. List of Recently Issued NMSS Information Notices
2. List of Recently Issued NRC Information Notices

LIST OF RECENTLY ISSUED
 NMSS INFORMATION NOTICES

Information Notice No.	Subject	Date of Issuance	Issued to
91-14	Recent Safety-Related Incidents at Large Irradiators	03/05/91	All Nuclear Regulatory Commission (NRC) licensees authorized to possess and use sealed sources at large irradiators.
91-03	Management of Wastes Contaminated with Radioactive Materials ("Red Bag" Waste and Ordinary Trash)	01/07/91	All medical licensees.
91-02	Brachytherapy Source Management	01/07/91	All Nuclear Regulatory Commission (NRC) medical licensees authorized to use byproduct material for medical purposes.
90-82	Requirements for Use of Nuclear Regulatory Commission-(NRC-)Approved Transport Packages for Shipment of Type A Quantities of Radioactive Materials.	12/31/90	All registered users of NRC-approved packages.
90-81	Fitness for Duty	12/24/90	All U.S. Nuclear Regulatory Commission (NRC) and non-power reactor licensees.
90-75	Denial of Access to Current Low-Level Radioactive Waste Disposal Facilities	12/5/90	All Michigan holders of NRC licenses.
90-71	Effective Use of Radiation Safety Committees to Exercise Control Over Medical Use Programs	11/6/90	All NRC licensees authorized to use byproduct material for medical purposes.

OL = Operating License
 CP = Construction Permit

LIST OF RECENTLY ISSUED
 NRC INFORMATION NOTICES

Information Notice No.	Subject	Date of Issuance	Issued to
91-15	Incorrect Configuration of Breaker Operating Springs in General Electric AK-Series Metal-Clad Circuit Breakers	03/06/91	All holders of OLs or CPs for nuclear power reactors.
91-14	Recent Safety-Related Incidents at Large Irradiators	03/05/91	All Nuclear Regulatory Commission (NRC) licensees authorized to possess and use sealed sources at large irradiators.
91-13	Inadequate Testing of Emergency Diesel Generators (EDGs)	03/04/91	All holders of OLs or CPs for nuclear power reactors.
91-12	Potential Loss of Net Positive Suction Head (NPSH) of Standby Liquid Control System Pumps	02/15/91	All holders of OLs or CPs for boiling water reactors (BWRs).
91-11	Inadequate Physical Separation and Electrical Isolation of Non-safety-related Circuits from Reactor Protection System Circuits	02/20/91	All holders of OLs or CPs for W-designed nuclear power reactors.
86-99, Supp. 1	Degradation of Steel Containments	02/14/91	All holders of OLs or CPs for nuclear power reactors.
89-32, Supp. 1	Surveillance Testing of Low-Temperature Overpressure-Protection Systems	02/12/91	All holders of OLs or CPs for nuclear power reactors.
91-10	Summary of Semiannual Program Performance Reports on Fitness-for-Duty (FFD) in the Nuclear Industry	02/12/91	All holders of OLs or CPs for nuclear power reactors.

OL = Operating License
 CP = Construction Permit

Discussion:

Licensees are reminded that they must make surveys to assure compliance with 10 CFR 20.301 which describes authorized means of disposal of licensed material in waste and must make surveys to assure compliance with 10 CFR 20.106 which limits the yearly average concentration of radioactive material in air or water discharged to unrestricted areas. Furthermore, licensees are reminded that changes in plant design must be evaluated to determine whether the changes will result in the unmonitored release of radioactive material to unrestricted areas.

This Information Notice requires no specific action or written response. If you have any questions about the information in this notice, please contact the technical contact(s) listed below or the appropriate NRR project manager.

Richard E. Cunningham, Director
Division of Industrial and
Medical Nuclear Safety
Office of Nuclear Materials Safety
and Safeguards

Technical Contacts: Susan S. Adamovitz, Region II
(404) 331-4774

Edwin D. Flack, NMSS
(301) 492-0405

Attachments:

1. List of Recently Issued NMSS Information Notices
2. List of Recently Issued NRC Information Notices

EKraus:2/ /91:

OFC:IMUF:	IMUF:	RII:	IMUF:	IMUF:	IMSB:
NAME: EFlack:mh:	MHorn:	SAdamovitz:	VLTharpe:	GHBidinger:	CHaughney:
DATE: 2/ /91:	2/ /91:	2/ /91:	2/ /91:	2/ /91:	2/ /91:

OFC:DD/IMNS:	D/IMNS:
NAME: GSjoblom:	RECunningham:
DATE: 2/ /91:	2/ /91:

OFFICIAL RECORD COPY

Discussion

Licenseses are reminded that they must make surveys to assure compliance with 10 CFR 20.301 which describes authorized means of disposal of licensed material in waste and must make surveys to assure compliance with 10 CFR 20.106 which limits the yearly average concentration of radioactive material in air or water discharged to unrestricted areas. Furthermore, licenseses are reminded that changes in plant design must be evaluated to determine whether the changes will result in the unmonitored release of radioactive material to unrestricted areas.

This Information Notice requires no specific action or written response. If you have any questions about the information in this notice, please contact the technical contact(s) listed below or the appropriate Regional Administrator.

Richard E. Cunningham, Director
Division of Industrial and
Medical Nuclear Safety
Office of Nuclear Materials Safety
and Safeguards

Technical Contacts: Susan S. Adamovitz, Region II
(404) 331-4774
Edwin D. Flack, NMSS
(301) 492-0405

Attachments:

1. List of Recently Issued
NMSS Information Notices
2. List of Recently Issued
NRC Information Notices

EF/INFORMATION NOTICE

EKraus: 2/16/91:

OFC:IMUF:	IMUF:	RII: <i>2000/91</i>	IMUF:	IMUF: <i>2516</i>	IMSB: <i>011A</i>
NAME: EFlack:mh:	MHorn:	SAdamovitz:	VLKarpe:	GHBidinger:	CHaughney:
DATE: 2/26/91:	2/26/91:	2/26/91:	2/26/91:	2/26/91:	2/27/91:

OFC:DD/IMNS:	D/IMNS:
NAME: GSjoblom:	RECunningham:
DATE: 2/ /91:	2/28/91: