



**Department of Energy**  
 Yucca Mountain Site Characterization  
 Project Office  
 P. O. Box 98608  
 Las Vegas, NV 89193-8608

WBS 1.2.9.3  
 QA

MAR 19 1991

MEMORANDUM FOR FILE

AMENDED RESPONSE TO STANDARD DEFICIENCY REPORT (SDR) 596

As a result of a policy change within the Office of Quality Assurance, the corrective actions for SDR 596 have not been completed. The SDR cited deficiencies within Quality Assurance Program Description (QAPD), Revision 2, and committed to a revision of that document by March 1, 1991. The QAPD will not be revised, as the current Quality Assurance Requirements Document/QAPD document structure will be replaced with a centralized QA document. All deficiencies cited within the SDR will be incorporated into the new document.

It is estimated that the corrective actions for this SDR will be completed by August 8, 1991.

Donald G. Horton, Director  
 Yucca Mountain Quality Assurance Division

YMQAD:CEH-2557

cc:

- N. J. Brogan, SAIC, Las Vegas, NV
- S. H. Horton, SAIC, Las Vegas, NV
- R. E. Spence, SAIC, Las Vegas, NV
- J. W. Gilray, NRC, Washington, DC

1/8