

2/17/01

0945

ANPS COMPLETED PRE-JOB BRIEF FOR CEA TROUBLESHOOTING IAW CHECK SHEET 9. OLRM RESULTS FOR LOAD THREAT 1.96E-5 SAT.

1002 - COMMENCED TRANSFERING CEAS TO THE UPPER GRIPPER IAW 2-IMP-66.01.

1028 - PLACED RODS #78,72,91,89,76,61, AND 25 ON THE UPPER GRIPPER. ALL ROD TRACES LOOKED NORMAL.

1445 - RECEIVED THE "CEDMCS TROUBLE" ALARM. CEA # 25 FOUND TRANSFERRED TO LOWER GRIPPER, ABNORMAL VOLTAGE LIGHT IS LIT. ENTERED ONOP 2-0110030, CEA OFF NORMAL.

1600 - ANPS COMPLETED PRE-JOB BRIEF FOR CEA TROUBLESHOOTING IAW CHECK SHEET 9. TRANSFERING CEA # 25 BACK TO THE UPPER GRIPPER. OLRM RESULTS FOR LOAD THREAT 1.96E-5 SAT.

1607 - CEA #25 BACK ON UPPER GRIPPER, TRACE IS NORMAL.

1718 - RECEIVED THE "CEDMCS TROUBLE" ALARM. CEA # 25 FOUND TRANSFERRED TO LOWER GRIPPER, ABNORMAL VOLTAGE LIGHT IS LIT. ENTERED ONOP 2-0110030, CEA OFF NORMAL.

1040

THE FL. FISH AND WILDLIFE CONSERVATION COMMISSION WAS NOTIFIED FOR A PICK UP OF A SICK TURTLE IN NEED OF REHABILITATION.

1057 - THE NRC WAS NOTIFIED OF THE SICK TURTLE IN NEED OF REHABILITATION. NRC NOTIFICATION WAS REQUIRED DUE TO STATE NOTIFICATION BEING MADE. CR #01-0279 WAS WRITTEN.

1525

DECLARED THE LOOSE PARTS MONITOR BACK IN SERVICE.

0052 2/14

STARTED 2A BAM PP FOR QUARTERLY SURVEILLANCE IAW DS-12

0105 - SECURED 2A BAM PP. SURVEILLANCE SAT.

0113 - STARTED 2B BAM PP FOR QUARTERLY SURVEILLANCE IAW DS-13.

0123 - SECURED 2B BAM PP. SURVEILLANCE SAT.

0141 - (LATE ENTRY) DECLARED 2B BAM PP OOS FOR OIL CHANGE AND PM LUBE

0230

DECLARED HVE-6A OOS TO REPLACE MOISTURE SENSOR MT-25-1. ENTERED ACTION STATEMENT T.S. 3.6.6.1B1

B/b