

Department of Energy

Yucca Mountain Site Characterization **Project Office** P. O. Box 98608 Las Vegas, NV 89193-8608

WBS 1.2.11 QA: N/A

FFR 2 5 1993

Julie A. Canepa Technical Project Officer for Yucca Mountain Site Characterization Project Los Alamos National Laboratory University of California EES-13, Mail Stop J521 P. O. Box 1663 Los Alamos, NM 87545

VERIFICATION OF CORRECTIVE ACTION AND CLOSURE OF CORRECTIVE ACTION REQUEST (CAR) YM-93-018 RESULTING FROM YUCCA MOUNTAIN QUALITY ASSURANCE DIVISION (YMQAD) AUDIT YMP-93-02 OF LOS ALAMOS NATIONAL LABORATORY

The YMQAD staff has verified the corrective action to CAR YM-93-018 and determined the results to be satisfactory. As a result, the CAR is considered closed.

If you have any questions, please contact either Robert B. Constable at (702) 794-7945 or John R. Matras at (702) 794-7197.

Richard E. Spence, Director

Yucca Mountain Quality Assurance Division

YMOAD:RBC-2694

Enclosure:

CAR YM-93-018

K. R. Hooks, NRC, Washington, DC

S. W. Zimmerman, NWPO, Carson City, NV

N. Z. Elkins, LANL, Las Vegas, NV

S. L. Bolivar, LANL, Los Alamos, NM

R. L. Maudlin, MACTEC, Las Vegas, NV

cc w/o encl:

J. B. Tillman, LAAO

J. H. Hines, OQD, AL

J. W. Gilray, NRC, Las Vegas, NV

N. J. Brogan, SAIC, Las Vegas, NV

B. J. Verna, YMP, NV

A. V. Gil, YMP, NV

02012.

WM-11 102.7 Add: K. R. Hooks 11 DH031/1

OFFICE OF CIVILIAN **RADIOACTIVE WASTE MANAGEMENT**

8	CAR NO.:	IM-93-018	
	DATE:	11/6/92	
	SHEET: _	1 OF	1
		AQ	

	PARTMENT OF ENERG ASHINGTON, D.C.	Ϋ́	SHEET: 1 OF 1 QA	
	TIVE ACTION REQUE	ST		
1 Controlling Document TWS-QAS-QP-03.17, Revision 0			d Report No. YMP-93-02	
3 Responsible Organization	4 Discussed With			
LANL	B. Robinson/S. Bol	ivar		
5 Requirement: Section 6.2.2, "SCM Audits" states, "If actions and await resumption of the pro	cess at Step 6.2.1.	_	·	
o In the "Disposition" section of the Baseline Submission Summary, check "Not Accepted," supply an explanation under "SCM/CCB Comments," and sign and date the form and return a copy to submitter.				
o Return copies of all Review/Audit I Recommendations form to the submitt	tem Disposition forms and er for resolution.	the Revi	ew/Audit Report and	
o Remove the proposed Baseline from the LANL YMP Certification Environment."				
6 Adverse Condition:				
In contrast to the above requirement wh	en audit issued were ident	ified	·	
 (1st Bullet) The "Disposition" sect checked "Not Accepted." 	ion of the Baseline Submis	sion Sum	mary was not	
2. (3rd Bullet) The proposed baseline Environment.				
	pes a stop work condition exist?		11 Response Due Date:	
The state of the s	esNo_x_; if Yes - Attach co Yes, Circle One: A B C D		20 Working Days from Issuance	
40-			☐ Root Cause Determination	
12 Required Actions: Remedial Extent of Deficiency Preclude Recurrence Root Cause Determination 13 Recommended Actions: Revise procedures to reflect current operating practices.				
7 Initiator Services Water	[42 language A : 2 : 2		· · · · · · · · · · · · · · · · · · ·	
John R. Marras Date /	7.72	LAGO	A. Date ////3/92	
OAR Date /	16 Response Acre	Spa	ce Date/2/30/93	
17 Amended Response Accepted QAR Date	18 Amefided Respo	onșe Acce	pted / Date	
19 Corrective Actions Verified	20 Closure Approve	ed by: 19	Date	
OAR John R Matras Date 2	122/93 QADD /AC.	Sp	ncl Date 2/24/93	
V	•	/	f mmi aana	

REV. 08/91

OFFICE OF CIVILIAN RADIOACTIVE WASTE MANAGEMENT U.S. DEPARTMENT OF ENERGY WASHINGTON, D.C.

CAR NO.	YM-93-018
	12/14/92
PAGE:	OF
	QA

CORRECTIVE ACTION REQUEST (Continuation Page)

Page 1 of 1

CORRECTIVE ACTION RESPONSE FOR CAR NO. YM-93-018:

A. Remedial Action:

All in-process Baseline Submission Summaries (BSS) will be reviewed to assure that for those BSSs with identified audit issues, the "Disposition" section of the document has been checked "Not Accepted," an explanation provided, and the BSS removed from the Los Alamos YMP Certification environment. This action will be completed by January 15, 1993.

B. Investigative Action:

Investigative action indicated that when minor issues were noted during Software Configuration Management audits, it has been an occasional practice to complete a Review/Audit Item Disposition (RID) and continue the review instead of resubmitting all of the material. This practice was discussed with the auditor and it was agreed that the described method is a more logical, efficient way of doing business; however, it is not allowed by the procedure. These audit issues were minor and the quality of the reviews was not affected. This action was completed by B. Robinson on 12/4/92.

C. Root Cause Determination:

N/A

D. Corrective Action to Preclude Recurrence:

The practice of continued processing of review material after minor audit issues have been identified was stopped by B. Robinson on 11/13/92. All audit issues identified during SCM audits are now processed as required by the procedure.

Response Approved	Silde	12/10/92
	QAPL S.L. Bottver	DATE
Response Approved	Cley raise	12/14/92
	TPO J.L. Canepa	DATE / /a-
Response Approved		tras 12/29/92
·	QAR	DATE
Response Approved 🖔	Maria Le	12-30-92
KKL12.3.92	_YMQAD YMQA≟	DATE .

Sty Atl 12/14/92 - TWS - EES - 13 -12 - 92 - 029

OFFICE OF CIVILIAN RADIOACTIVE WASTE MANAGEMENT U.S. DEPARTMENT OF ENERGY WASHINGTON, D.C.

CAR NO	YM-93-018
DATE:	11-6-92
PAGE:	OF
	QA

CORRECTIVE ACTION REQUEST (Continuation Page)

VERIFICATION OF CAR YM-93-018

The remedial activities indicated in this CAR response have been completed as described in Los Alamos Memorandum TWS-EES-13-02-93-030.

John R. Matras Date 2/5/93

Los Alamos

Los Alamos National Laboratory Los Alamos New Mexico 87545

memorandum

¹⁰ B. A. Robinson, EES-4, MS D443

DATE February 5, 1993

FROM M. S. Robinson, EES-13 MM

MAIL STOP TELEPHONE J521/7-0599

SYMBOL TWS-EES-13-02-93-030

SUBJECT CORRECTIVE ACTION REQUEST NO. YM-93-018

In response to the subject Corrective Action Request, additional information is provided.

Eleven baseline summaries are still in process. These baseline summaries were reviewed and

it was determined that there are no outstanding audit issues for these baselines.

MSR/elm

Cy: S. L. Bolivar, EES-13, MS J521 Z. V. Dash, EES-4, MS D443 R. S. Shay, INC-DO, MS J514 RPC File (2), MS M321 TWS-EES-13 File, MS J521