

May 29, 2003

Mr. W. E. Cummins, Director
AP600 & AP1000 Projects
Westinghouse Electric Company
P.O. Box 355
Pittsburgh, PA 15230-0355

Dear Mr. Cummins:

As you are aware, the U. S. Nuclear Regulatory Commission (NRC) staff is preparing the draft safety evaluation report (DSER) for the AP1000 design certification application submitted by Westinghouse Electric Company (Westinghouse) on March 28, 2002. The staff expects to issue the DSER in June, 2003. As of this date, the staff has identified two potential open items for DSER Chapter 15, "Transient and Accident Analyses" which are enclosed for your information. Please note that the staff's review of the application will continue during preparation of the DSER, which may result in changes to the potential open items identified in the enclosure, or the addition of other open items.

The two potential open items in the enclosure have the original request for additional information (RAI) number included for reference. If the staff cannot resolve the potential open items before the issuance of the DSER, these items will be issued as DSER open items and be tracked with a corresponding open item number.

Previously, Westinghouse committed to provide responses to all identified open items within 9 weeks after the issuance of the DSER. The staff will be prepared to review your responses to the open items and have conference calls and meetings with your staff, as appropriate, after the DSER is issued. If Westinghouse chooses to address some or all of these open items before the issuance of the DSER, the staff may not have sufficient time to evaluate every response to the potential open items that Westinghouse submits to the NRC and make changes to the DSER before the scheduled DSER issuance in June, 2003.

Please contact one of the following members of the AP1000 project management team if you have any questions or comments concerning this matter: Mr. John Segala (Lead Project Manager) at (301) 415-1858 or jps1@nrc.gov, Mr. Joseph Colaccino at (301) 415-2752 or jxc1@nrc.gov, or Ms. Joelle Starefos at (301) 415-8488 or jls1@nrc.gov.

Sincerely,

/RA/

James E. Lyons, Director
New Reactor Licensing Project Office
Office of Nuclear Reactor Regulation

Docket No. 52-006

Enclosure: As stated

cc: See next page

May 29, 2003

Mr. W. E. Cummins, Director
AP600 & AP1000 Projects
Westinghouse Electric Company
P.O. Box 355
Pittsburgh, PA 15230-0355

Dear Mr. Cummins:

As you are aware, the U. S. Nuclear Regulatory Commission (NRC) staff is preparing the draft safety evaluation report (DSER) for the AP1000 design certification application submitted by Westinghouse Electric Company (Westinghouse) on March 28, 2002. The staff expects to issue the DSER in June, 2003. As of this date, the staff has identified two potential open items for DSER Chapter 15, "Transient and Accident Analyses" which are enclosed for your information. Please note that the staff's review of the application will continue during preparation of the DSER, which may result in changes to the potential open items identified in the enclosure, or the addition of other open items.

The two potential open items in the enclosure have the original request for additional information (RAI) number included for reference. If the staff cannot resolve the potential open items before the issuance of the DSER, these items will be issued as DSER open items and be tracked with a corresponding open item number.

Previously, Westinghouse committed to provide responses to all identified open items within 9 weeks after the issuance of the DSER. The staff will be prepared to review your responses to the open items and have conference calls and meetings with your staff, as appropriate, after the DSER is issued. If Westinghouse chooses to address some or all of these open items before the issuance of the DSER, the staff may not have sufficient time to evaluate every response to the potential open items that Westinghouse submits to the NRC and make changes to the DSER before the scheduled DSER issuance in June, 2003.

Please contact one of the following members of the AP1000 project management team if you have any questions or comments concerning this matter: Mr. John Segala (Lead Project Manager) at (301) 415-1858 or jps1@nrc.gov, Mr. Joseph Colaccino at (301) 415-2752 or jxc1@nrc.gov, or Ms. Joelle Starefos at (301) 415-8488 or jls1@nrc.gov.

Sincerely,

/RA/

James E. Lyons, Director
New Reactor Licensing Project Office
Office of Nuclear Reactor Regulation

Docket No. 52-006

Enclosure: As stated

cc: See next page

<u>Distribution:</u>		<u>E-Mail</u>	SBlack	AP1000SCs
<u>Hard Copy</u>	JLyons	SCollins	GTracy	AP1000BCs
MGamberoni	JColaccino	RBorchardt	RBarret	
JSegala	NRLPO R/F	ACRS	BBoger	
PUBLIC		AP1000 reviewers	DMatthews	
JStarefos		OGC		

ADAMS ACCESSION NUMBER: ML031480375

OFFICE	PM:NRLPO	DD:NRLPO	D:NRLPO
NAME	JColaccino	MGamberoni-w/minor cmts.	JLyons
DATE	05/28/03	05/28/03	05/28/03

OFFICIAL RECORD COPY

**Westinghouse AP1000
Draft Safety Evaluation Report
Potential Open Items
Chapter 15
Transient and Accident Analyses**

Open Item Number: 15.1.5-1

Original RAI(s): 440.002, 440.062

Summary of Issue: Westinghouse has issued three Nuclear Service Advisory Letter (NSAL), NSAL-02-3 and revision 1, NSAL-02-4 and 02-5, that document the problems with the Westinghouse-designed SG water level setpoint uncertainties. NSAL-02-3 and its revision, issued on February 15 and April 8, 2002, respectively, deal with the uncertainties caused by the mid-deck plate located between the upper and lower taps used for SG level measurements. These uncertainties affect the low-low level trip setpoint (used in the analysis for events such as the feedwater line break (FLB), ATWS and steam line break). NSAL-02-4, issued on February 19, 2002, deals with the uncertainties created because the void contents of the two-phase mixture above the mid-deck plate are not reflected in the calculation and affect the high-high level trip setpoint. NSAL-02-5, issued on February 19, 2002, deals with the initial conditions assumed in the SG water level related safety analysis. The safety analysis may not be bounding because of velocity head effects or mid-deck plate pressure differential pressure that have resulted in significant increases in the control system uncertainties. In RAI 440.062 the staff requested the applicant to discuss: (1) how the AP1000 design accounts for all these uncertainties documented in these advisory letters in determining the SG water level setpoints, and (2) the effects of the water level uncertainties on the analyses of the LOCA and non-LOCA transients and the ATWS event.

The applicant response to RAI 440.002 stated that measurement uncertainties for the reactor protective system and engineered safety features actuation system instrument can be determined only when actual instrumentation is selected for the plant. The plant specific setpoint calculations will be completed and reviewed as part of the COL. The COL applicants referencing the AP1000 certified design will provide a calculation of setpoints for protective functions consistent with the methodology discussed in WCAP-14605, "Westinghouse Setpoint Methodology for Protective Systems, AP600." The methodology can be used for performing setpoint studies independent of the hardware used for the protection system, and therefore is applicable to the AP1000. The setpoint study will include applicable uncertainties discussed in the referenced NSAL. Using the methodology in WCAP-14605, plant

Enclosure

nominal setpoints are calculated by adding the channel allowance from the setpoint study to the setpoint used in the safety analysis.

The COL applicant should perform plant-specific safety analysis to confirm the validity of the safety analysis documented in the AP1000 DCD using plant-specific setpoints and instrument uncertainties, including the SG mid-deck plate level measurement uncertainties. The COL applicants should submit in the plant specific applications the setpoint analysis and the associated safety analysis for the staff to review and approve. This is COL Action Item 15.1-1 and Open Item 15.1.5-1.

Open Item Number: 15.1.5-2

Original RAI(s): 440.091

Summary of Issue: With regard to the boron precipitation issue, the results presented in DCD transient analysis (1) did not quantify the amount of water exiting the vessel; (2) there was no clear indication of void distribution in the core; (3) did not characterize the water-steam mixture flow regime in the ADS-4; and (4) did not minimize the steam velocity through the ADS-4. At the staff's request, the applicant presented a more conservative case by assuming that all ADS-4 valves are open and the containment pressure is at a maximum. In addition, the applicant presented a qualification of the WCOBRA/TRAC model regarding ADS-4 water-steam flow (RAI responses to 440.091, Revision 1). The staff reviewed this information and (as stated above) found that there is adequate justification for the WCOBRA/TRAC ADS-4 flow model. The applicant demonstrated that the flow regime is the same as in AP600 (annular flow) which would entrain fluid particles to expel water from the vessel as required to avoid boron concentration in the vessel and/or precipitation. The amount of water to be removed from the core was quantified. In addition, literature was cited regarding flow regimes applicable to the conditions of the ADS-4 which reinforced the credibility of the results.

However, the applicant did not present a detailed enough case regarding void distribution in the core. Persistent voiding in the core could result into adiabatic heating of the fuel. This is Open Item 15.2.7-1.

AP 1000

cc:

Mr. W. Edward Cummins
AP600 and AP1000 Projects
Westinghouse Electric Company
P.O. Box 355
Pittsburgh, PA 15230-0355

Mr. H. A. Sepp
Westinghouse Electric Company
P.O. Box 355
Pittsburgh, PA 15230

Lynn Connor
Doc-Search Associates
2211 SW 1ST Ave - #1502
Portland, OR 97201

Barton Z. Cowan, Esq.
Eckert Seamans Cherin & Mellott, LLC
600 Grant Street 44th Floor
Pittsburgh, PA 15219

Mr. Ed Rodwell, Manager
Advanced Nuclear Plants' Systems
Electric Power Research Institute
3412 Hillview Avenue
Palo Alto, CA 94304-1395

Charles Brinkman, Director
Washington Operations
Westinghouse Electric Company
12300 Twinbrook Parkway, Suite 330
Rockville, MD 20852

Mr. R. Simard
Nuclear Energy Institute
1776 I Street NW
Suite 400
Washington, DC 20006

Mr. Thomas P. Miller
U.S. Department of Energy
Headquarters - Germantown
19901 Germantown Road
Germantown, MD 20874-1290

Mr. David Lochbaum
Nuclear Safety Engineer
Union of Concerned Scientists
1707 H Street NW, Suite 600
Washington, DC 20006-3919

Mr. Paul Gunter
Nuclear Information & Resource Service
1424 16th Street, NW., Suite 404
Washington, DC 20036

Mr. Tom Clements
6703 Guide Avenue
Takoma Park, MD 20912

Mr. James Riccio
Greenpeace
702 H Street, NW, Suite 300
Washington, DC 20001

Mr. James F. Mallay, Director
Regulatory Affairs
FRAMATOME, ANP
3315 Old Forest Road
Lynchburg, VA 24501

Mr. Ed Wallace, General Manager
Project Management
Lake Buena Vista Bldg., 3rd Floor
1267 Gordon Hood Avenue
Centurion 0046
Republic of South Africa
PO Box 9396 Centurion 0046

Mr. Vince Langman
Licensing Manager
Atomic Energy of Canada Limited
2251 Speakman Drive
Mississauga, Ontario
Canada L5K 1B2

Mr. Gary Wright, Manager
Office of Nuclear Facility Safety
Illinois Department of Nuclear Safety
1035 Outer Park Drive
Springfield, IL 62704

Dr. Gail H. Marcus
U.S. Department of Energy
Room 5A-143
1000 Independence Ave., SW
Washington, DC 20585

Mr. Edwin Lyman
Nuclear Control Institute
1000 Connecticut Avenue, NW
Suite 410
Washington, DC 20036

Mr. Jack W. Roe
SCIENTECH, INC.
910 Clopper Road
Gaithersburg, MD 20878

Patricia Campbell
Winston & Strawn
1400 L Street, NW
Washington, DC 20005

Mr. David Ritter
Research Associate on Nuclear Energy
Public Citizens Critical Mass Energy
and Environmental Program
215 Pennsylvania Avenue, SE
Washington, DC 20003

Mr. Michael M. Corletti
Passive Plant Projects & Development
AP600 & AP1000 Projects
Westinghouse Electric Company
P. O. Box 355
Pittsburgh, PA 15230-0355