



May 26, 2003

L-2003-132  
10 CFR 50.36  
10 CFR 50.4

U.S. Nuclear Regulatory Commission  
Attn: Document Control Desk  
Washington, DC 20555

Re: St. Lucie Unit 2  
Docket No. 50-389  
Special Report  
Steam Generator Tube Plugging Report

This letter is being sent pursuant to St. Lucie Unit 2 Technical Specification 4.4.5.5.a. The number of tubes plugged in each steam generator during the Unit 2 refueling outage (SL2-14) is listed below.

Steam Generator 2A - 197  
Steam Generator 2B - 333

Cumulative tubes plugged during this outage and previous outages:

Steam Generator 2A - 671  
Steam Generator 2B - 872

Please contact us should you have any questions regarding this information.

Very truly yours,

A handwritten signature in black ink, appearing to read 'WJ', is written over the 'Very truly yours,' text.

William Jefferson, Jr.  
Vice President  
St. Lucie Plant

WJ/spt

A047