Kevin J. Nietmann
Plant General Manager
Calvert Cliffs Nuclear Power Plant
Constellation Generation Group, LLC

1650 Calvert Cliffs Parkway Lusby, Maryland 20657 410 495-4101 410 495-4787 Fax



June 13, 2003

U. S. Nuclear Regulatory Commission Washington, DC 20555

ATTENTION:

Document Control Desk

SUBJECT:

Calvert Cliffs Nuclear Power Plant

Unit Nos. 1 & 2; Docket Nos. 50-317 & 50-318

May 2003 Operating Data Reports

The subject reports are being sent to you as required by Technical Specification 5.6.4.

Should you have questions, please contact Mr. Thomas S. O'Meara at (410) 495-6940.

Very truly yours,

KJN/CAN/bjd

Attachments

cc:

J. Petro, Esquire

J. E. Silberg, Esquire Director, Project Directorate I-1, NRC

G. S. Vissing, NRC H. J. Miller, NRC Resident Inspector, NRC

R. I. McLean, DNR

J. Wright, INPO

K. N. Larson, ANI

LE24

OPERATING DATA REPORT

**** *********** *******

Docket No. 50-317 Calvert Cliffs Unit 1 June 4, 2003 Prepared by Herman O. Olsen

Telephone: (410) 495-6734

REPORTING PERIOD MAY 2003
DESIGN ELECTRICAL RATING (NET MWe) 845
MAXIMUM DEPENDABLE CAP'Y (NET MWe) 825

		Year-	Cumulative
	This month	to-Date	to Date
1. NUMBER OF HOURS REACTOR WAS CRITICAL	744.0	3,623.0	186,912.4
2. HOURS GENERATOR ON LINE	744.0	3,623.0	183,748.7
3. UNIT RESERVE SHUTDOWN HOURS	0.0	0.0	0.0
4. NET ELECTRICAL ENERGY GENERATED (MWH)	644,534	3,147,509	150,314,772

UNIT SHUTDOWNS

DOCKET NO. UNIT NAME DATE 50-317 Calvert Cliffs - U1

June 5, 2003

Herman O. Olsen (410) 495-6734

COMPLETED BY TELEPHONE

REPORTING MONTH May 2003

3	CAUSE/CORRECTIVE ACTIONS COMMENTS	METHOD OF SHUTTING DOWN ²	REASON ¹	DURATION (HOURS)	TYPE F: FORCED S: SCHEDULED	DATE	NO.
	There were no shutdowns this month.						
	·						
	•						
j							

- 1 Reason:
- A Equipment Failure
- B Maintenance or Test
- C Refueling
- D Regulatory Restriction
- E Operator Training & License Examination
- F Administrative
- G Operational Error
- H Other

- ² Method:
- 1 Manual
- 2 Manual Scram.
- 3 Automatic Scram.
- 4 Continued
- 5 Other

DOCKET NO. 50-317 CALVERT CLIFFS - UNIT 1 June 5, 2003

SUMMARY OF OPERATING EXPERIENCE

May 2003

The unit began the month at 100% power.

Power was reduced to approximately 86% on 05/02/03 at 2200 for Main Turbine Valve Testing. Testing was completed and the unit was returned to 100% power on 05/03/03 at 0210.

The unit operated at 100% power for the remainder of the month.

*** ********* ****** ********* ******

OPERATING DATA REPORT

Docket No. 50-318
Calvert Cliffs Unit 2
June 4, 2003
Prepared by Herman O. Olsen
Telephone: (410) 495-6734

REPORTING PERIOD MAY 2003
DESIGN ELECTRICAL RATING (NET MWe) 845
MAXIMUM DEPENDABLE CAP'Y (NET MWe) 835

	This month	Year- to-Date	Cumulative to Date
1. NUMBER OF HOURS REACTOR WAS CRITICAL	716.9	2,030.0	179,589.8
2. HOURS GENERATOR ON LINE	712.5	1,996.5	177,701.2
3. UNIT RESERVE SHUTDOWN HOURS	0.0	0.0	0.0
4. NET ELECTRICAL ENERGY GENERATED (MWH)	613,526	1,707,408	146,293,838

UNIT SHUTDOWNS

DOCKET NO. UNIT NAME 50-318

Calvert Cliffs-U2
June 5, 2003

Herman O. Olsen (410) 495-6734

DATE COMPLETED BY TELEPHONE

REPORT MONTH May 2003

NO.	DATE	TYPE F: FORCED S: SCHEDULED	DURATION (HOURS)	REASON ¹	METHOD OF SHUTTING DOWN ²	CAUSE/CORRECTIVE ACTIONS COMMENTS
03-002	030528	F	31.5	В	3	On 05/28/03 at 1134 an automatic trip occurred from 100% power. The trip was caused by a short circuit that was created while connecting the test equipment used for trouble shooting in an instrument cabinet. The trouble shooting was being performed to determine the cause of and to correct the Main Turbine Governor Valve oscillations. The unit was brought to a safe shutdown condition in Mode 3. Testing was performed to verify the exact cause of the trip. The unit was returned to service on 05/29/03 at 1903. The immediate corrective action was to suspend trouble shooting of the valve oscillation problem and require management approval for any on-line maintenance performed in the affected cabinets. A detailed root cause analysis and a Licensee Event Report (LER) are in progress.

- 1 Reason:
- A Equipment Failure
- B Maintenance or Test
- C Refueling
- D Regulatory Restriction
- E Operator Training & License Examination
- F Administrative
- G Operational Error
- H Other

- ² Method:
- 1 Manual
- 2 Manual Scram.
- 3 Automatic Scram.
- 4 Continued
- 5 Other

DOCKET NO. 50-318 CALVERT CLIFFS - UNIT 2 June 5, 2003

SUMMARY OF OPERATING EXPERIENCE

May 2003

The unit began the month at 100% reactor power.

On 05/28/03 at 1134 an automatic reactor trip from 100% power occurred. The trip was caused by a short circuit that was created when connecting the test equipment that was being used for trouble shooting in an instrument cabinet. The unit was taken critical on 05/29/03 at 1442 and was paralleled to the grid at 1903. The unit reached 100% on 05/30/03 at 0400.

The unit continued to operate at 100% power for the remainder of the month.