

Mattingly Testing Services, Inc.

P.O. Box 3128
GREAT FALLS, MONTANA 59403
406-284-5471

FAX COVER SHEET


DATE/TIME: 6-17-03

PRIORITY:

IMMEDIATELY X

1 HOUR

2-4 HOUR



MESSAGE TO: Jim Montgomery

MESSAGE FROM: Cheryl Davison

NUMBER OF PAGES: 4 PLUS TRANSMITTAL SHEET

FAX TO: 925-673-0112 CONTACT NO: 406-284-5471

SPECIAL INSTRUCTIONS / ATTACHMENTS:

Jim- Here ~~out~~ are the most recent Leak tests for the four sources that you requested. All leak tests are currently up to date. If you have any further questions, please feel free to call me.

Thanks~
Cheryl Davison



INDUSTRIAL NUCLEAR CO., INC.

TRANSFERRED FROM

MATTINGLY TESTING SERVICES
P.O. BOX 3126
GREAT FALLS, MT 59403

GENTLEMEN

THIS IS TO ADVISE YOU OF A WIPE TEST AND OR SOURCE DISPOSAL

RECEIVED BY I.N.C. ON 10/22/02

IDENTIFICATION

CONTAMINATION

IRIDIUM 192 SOURCE S/N D185

LESS THAN 0.005

INDUSTRIAL NUCLEAR COMPANY

BY MD De

TECHNICIAN

DATE 10/28/02

Any analysis that exhibits a level of contamination of 0.005 microcuries or greater constitutes an incident requiring immediate regulatory notification. As with all notifications, this will be handled by the RSO.

- 14320 Wicks Blvd., San Leandro, CA 94577
- 35 Flagship Dr., North Andover, MA 01845
- 9125 Airport Blvd., C#10, Houston, TX 77061

- Tel: (510) 352-6787
- Tel: (978) 683-5211
- Tel: (713) 947-0155

- Fax: (510) 352-6772
- Fax: (978) 683-9469
- Fax: (713) 947-1384

www. In100.com

e-mail: fenshya@aol.com



**LEAK TEST REPORT FORM
(MODEL INC-A-REV.1)**

Company MATTINGLY TESTING SERVICES
Address P.O. BOX 3126
City GRANT FMS State MT Zip 59403

ISOTOPE TR-102 + U-238 ACTIVITY 50 CF/1850.6bg

Source Serial No. D 968 CAMERA S/N 4486

Swab Taken By Madison DATE 12-31-02

COMMENTS: SAMPLE ALSO ANALYZED FOR DEPLETED URANIUM (U-238)

DIRECTIONS FOR PERFORMING WIPE TEST

1. Moisten swab.
2. Wipe area to be tested (inside exposure port).
3. Replace swab in plastic bag and staple to this page.
4. Complete information requested above
5. Wipe test swab must be returned with this document in a sealed envelope.
6. Ensure that proper survey of swab is performed.

Caution: Conduct a survey on the outside of each package placed in the U.S. Mail. Any envelope or package with a reading in excess of 0.5 mr/hr shall not be mailed

Any analysis that exhibits a level of contamination of 0.005 microcuries or greater constitutes an incident requiring immediate regulatory notification. 10 CFR part 34.25(d)

U-238
40.005
1-10-03

FOR INC USE ONLY

TEST RESULTS
INDUSTRIAL NUCLEAR CO.
WIPE TEST <u>40.005</u> μ ci
BY <u>ja3</u>
DATE <u>1-10-03</u>

CA OFFICE:
2515 Williams St., San Leandro, CA 94577
Tel: (510) 352-0766-08 • Fax: (510) 352-0772
TX OFFICE:
9125 Airport Blvd., C-10, Houston, TX 77061
Tel: (713) 947-0155, 947-0632 • Fax: (713) 947-1384

FORMINC-1

ja3 B



TRANSFERRED FROM

**MATTINGLY TESTING SERVICES
 P.O. BOX 3126
 GREAT FALLS, MT 59403**

GENTLEMEN

**THIS IS TO ADVISE YOU OF A WIPE TEST AND OR SOURCE DISPOSAL
 RECEIVED BY I.N.C. ON 01/21/03**

IDENTIFICATION

CONTAMINATION

IRIDIUM 192 SOURCE S/N D303

LESS THAN 0.005

INDUSTRIAL NUCLEAR COMPANY

BY *ms*

TECHNICIAN

DATE 01/23/03

Any analysis that exhibits a level of contamination of 0.005 microcuries or greater constitutes an incident requiring immediate regulatory notification. As with all notifications, this will be handled by the RSO.

- 14320 Wicks Blvd., San Leandro, CA 94577
 - 35 Flagship Dr., North Andover, MA 01845
 - 0126 Airport Blvd., C#10, Houston, TX 77061
- www. ir100.com

Tel: (510) 382-6787
 Tel: (978) 883-5211
 Tel: (713) 947-0155

Fax: (510) 382-6772
 Fax: (978) 883-9488
 Fax: (713) 947-1384

