AUDIT PLAN AND SCHEDULE DOE-EM/343 QUALITY ASSURANCE AUDIT OF DOE/WEST VALLEY PROJECT OFFICE (WVPO) WEST VALLEY DEMONSTRATION PROJECT (WVDP)

AUDIT NUMBER:

93EA-WV-AU-01

AUDITING ORGANIZATION:

Department of Energy (DOE) Headquarters

Environmental Restoration and Waste Management

Office of Waste Management

Vitrification Projects Division (EM-343)

AUDITED ORGANIZATION:

DOE/WVPO-WVDP

AUDIT DATES:

February 22-26, 1993

AUDIT TEAM:

Lou Wade

(MACTEC)

Audit Team Leader

Jim Conway

(EM-343)

Auditor Team Manager/Auditor

Kriss Grisham Lew Sirianni

(EM-343) **Auditor**

Sid Crawford

(BDM/SAIC) Auditor (BDM/SAIC) Auditor/Technical Specialist

John LaVea

(BDM/SAIC) Auditor

Jim Flaherty

(BDM/SAIC) Auditor/Technical Specialist

OBSERVERS:

(TBD)

AUDIT SCOPE:

The following program elements will be reviewed during this audit:

1.	Criterion 2	Quality Assurance Program (QA Training)
2.	Criterion 3	Design Control
3.	Criterion 5	Instructions Procedures and Drawings
4.	Criterion 7	Control of Purchased Items and Services
5.	Criterion 8	Identification and Control of Items
6.	Criterion 9	Control of Processes
7.	Criterion 11	Test Control
8.	Criterion 12	Control of Measuring and Test Equipment
9.	Criterion 14	Inspection, Test, and Operating Status
10	Criterion 16	Corrective Action
11.	Criterion 17	QA Records
12.	Criterion 19	Software QA

AUDIT OBJECTIVES:

To evaluate the effectiveness of DOE/WVPO implementation of their Quality Assurance Program as it applies to the Criteria identified in the audit scope above. These are the Criteria that were identified as being either marginally effective or indeterminate during Audit 92EA-WV-AU-001. Additionally, implementation of corrective actions resulting from the July 1992 audit and any other remaining outstanding issues will also be evaluated by the audit team.

ACTIVITIES TO BE AUDITED:

QA program elements and activities related to High Level Radioactive Waste treatment at WVDP.

APPLICABLE REQUIREMENTS/CRITERIA:

- 1. ASME NOA-1-1989, "Quality Assurance Requirements for Nuclear Facilities" (including applicable Supplements and Appendices)
- 2. DOE/RW-0214, Rev. 4 w/ ICN 4.1, "Quality Assurance Requirements Document"
- 3. DOE/EM/WO/02, Rev 1, VPD HLW "Quality Assurance Program Description"
- 4. WVDP-074, QAPD-2 & 3 "WVDP Quality Assurance Program Description"
- WVPO Implementing QA Program Procedures WVNS Implementing Quality Assurance Procedures

PRELIMINARY AUDIT SCHEDULE:

Activity	<u>Date</u>	Time
Pre Audit Meeting	02/22/93	8:00a - 9:00a
Conduct Audit	02/22/93	9:00a - 4:00p
Conduct Audit	02/23/93	8:00 a - 4:00p
Conduct Audit	02/24/93	8:00a - 4:00p
Conduct Audit	02/25/93	8:00a - 4:00p
Prepare Audit Summary	02/26/93	8:00a - 11:00a
Post Audit Meeting	02/26/93	11:00a - 12:00p

- Note: 1. Audit Team caucuses will be held daily from 4:00p to 4:30p to discuss daily results and obtain status of the audit progress.
 - 2. Management briefings will be held with WVPO/WVNS management personnel daily from 8:00a to 8:30a to discuss the previous days results, both positive and negative.