

Union Electric

One Ameren Plaza
1901 Chouteau Avenue
PO Box 66149
St. Louis, MO 63166-6149
314.621.3222

June 27, 2003

U.S. Nuclear Regulatory Commission
ATTN: Document Control Desk
Mail Station P1-137
Washington, DC 20555-0001

Ladies and Gentlemen:

ULNRC-04869



**CALLAWAY PLANT
DOCKET NUMBER 50-483
CORE OPERATING LIMITS REPORT**

Attached is the Callaway Plant Cycle 13 Core Operating Limits Report (COLR), Revision 3. The COLR was revised to include new RCS boration requirements prior to blocking Safety Injection below the P-11 interlock (Table A.2). In accordance with Technical Specification 5.6.5, new cycle and mid-cycle revisions to the COLR are transmitted to the NRC Staff for information. If you have any questions concerning this report, please contact us.

Very truly yours,

A handwritten signature in black ink, appearing to read "Dave Shafer".

Dave Shafer
Acting Manager, Regulatory Affairs

DJW/jdg

Attachment: Appendix A, Callaway Cycle 13
Core Operating Limits Report, Rev. 3

APP01

ULNRC-04869

June 27, 2003

Page 2

cc: U. S. Nuclear Regulatory Commission (Original and 1 copy)
Attn: Document Control Desk
Mail Stop P1-137
Washington, DC 20555-0001

Dr. Thomas P. Gwynn
Acting Regional Administrator
U.S. Nuclear Regulatory Commission
Region IV
611 Ryan Plaza Drive, Suite 400
Arlington, TX 76011-4005

Senior Resident Inspector
Callaway Resident Office
U.S. Nuclear Regulatory Commission
8201 NRC Road
Steedman, MO 65077

Mr. Jack N. Donohew (2 copies)
Licensing Project Manager, Callaway Plant
Office of Nuclear Reactor Regulation
U. S. Nuclear Regulatory Commission
Mail Stop 7E1
Washington, DC 20555-2738

Manager, Electric Department
Missouri Public Service Commission
PO Box 360
Jefferson City, MO 65102