

Entergy Nuclear South

Entergy Operations, Inc. 17265 River Road Killona, LA 70066 Tel 504 739 6440 Fax 504 739 6698 kpeters@entergy.com

Ken Peters

Director, Nuclear Safety Assurance Waterford 3

W3F1-2003-0048

July 1, 2003

U.S. Nuclear Regulatory Commission Attn: Document Control Desk Washington, DC 20555

SUBJECT:

Revision to Steam Generator Tubesheet Inspection Information

Waterford Steam Electric Station, Unit 3

Docket No. 50-382 License No. NPF-38

REFERENCES:

1. Nuclear Energy Institute letter to the NRC dated February 4, 2003,

Steam Generator Tubesheet Inspection Information

2. Entergy letter W3F1-2003-0016 dated March 27, 2003, Steam

Generator Tubesheet Inspection Information

Dear Sir or Madam:

As described in reference 1, the Nuclear Energy Institute coordinated the industry response to NRC staff questions regarding steam generator tube inspections within the tubesheet. The Entergy Operations, Inc. (Entergy) response for Waterford Steam Electric Station, Unit 3 (Waterford 3) was provided in reference 2. In the attachment to reference 2, Entergy indicated that it planned to inspect +2"/-5" tubesheet hot (TSH) during the Fall 2003 Waterford 3 refueling outage. After further consideration, Entergy now plans to inspect +2"/-7" from the expansion transition TSH during the Fall 2003 Waterford 3 refueling outage.

This letter contains no new commitments. If you have any questions or require additional information, please contact D. Bryan Miller at 504-739-6692.

Sincerely,

Difector, Nuclear Safety Assurance

KJP/DBM/cbh

ADDI

W3F1-2003-0048 Page 2 of 2 July 1, 2003

CC:

Thomas P. Gwynn, NRC Region IV N. Kalyanam, NRC-NRR J. Smith

N.S. Reynolds NRC Resident Inspectors Office