

Dominion Nuclear Connecticut, Inc.
Millstone Power Station
Rope Ferry Road
Waterford, CT 06385



Dominion™

July 22, 2003

Re: 10 CFR 50.4

U.S. Nuclear Regulatory Commission
Attention: Document Control Desk
Washington, D.C. 20555-0001

Serial No.: B18863
NL&OS/TGC/MAE:R1
Docket Nos.: 50-336
50-423
License Nos.: DPR-65
NPF-49

DOMINION NUCLEAR CONNECTICUT, INC.
MILLSTONE NUCLEAR POWER STATION UNITS 2 AND 3
REVISED RESPONSE TO ORDER FOR INTERIM SAFEGUARDS AND
SECURITY COMPENSATORY MEASURES DATED FEBRUARY 25, 2002

On February 25, 2002, the U.S. Nuclear Regulatory Commission (NRC) issued an Order for Interim Safeguards and Security Compensatory Measures (the Order) to all operating nuclear power reactor licensees. Dominion Nuclear Connecticut, Inc. (DNC) answered this Order in letters dated March 15, 2002, (B18605) and March 18, 2002, (B18617). DNC provided additional information in letters dated May 9, 2002, (B18653) and July 18, 2002, (B18719) and indicated completion by letter dated August 29, 2002 (B18743).

During the February 24-28, 2003, NRC Security Order inspection (Inspection Reports 50-336/03-005 and 50-423/03-005 dated April 11, 2003), it was identified that DNC had implemented a response to Interim Compensatory Measure (ICM) B.4.b that was different from that specified in the March 18, 2002, letter. Due to an administrative oversight, DNC had not provided an updated response to the Order modifying the response to ICM B.4.b. The modified response taken to address ICM B.4.b was reviewed during the February 24-28, 2003, Security Order inspection and found to be acceptable, albeit not as described in the March 18, 2002 letter. The purpose of this letter is to formally update the response to ICM B.4.b (attached) as of this date.

**ATTACHMENT CONTAINS SAFEGUARDS INFORMATION.
UPON SEPARATION THIS PAGE IS DECONTROLLED.**

* IE53
||

The attachment contains Safeguards Information as defined by 10 CFR 73.21 and its disclosure to unauthorized individuals is prohibited by Section 147 of the Atomic Energy Act of 1954, as amended.

If you have any questions, please contact us

Very truly yours,

A handwritten signature in black ink, appearing to read "Eugene S. Grecheck". The signature is fluid and cursive, with a large loop at the end.

Eugene S. Grecheck
Vice President – Nuclear Support Services

Commitments made by this letter: None

Attachment – Revised Response to Nuclear Regulatory Commission Security Order for Interim Safeguards and Security Compensatory Measures (Safeguards Information)

**ATTACHMENT CONTAINS SAFEGUARDS INFORMATION.
UPON SEPARATION THIS PAGE IS DECONTROLLED.**

cc: U. S. Nuclear Regulatory Commission
ATTN: Mr. Glenn Tracy
Mail Stop O-6H16
One White Flint North
11555 Rockville Pike
Rockville, MD 20852-2738

Mr. Robert E. Martin
Mail Stop O-8G9
One White Flint North
11555 Rockville Pike
Rockville, MD 20852-2738

Director, Office of Nuclear Reactor Regulation
U. S. Nuclear Regulatory Commission
Washington, D. C. 20555

U. S. Nuclear Regulatory Commission
Region I
Regional Administrator
475 Allendale Road
King of Prussia, PA 19406-1415

Mr. R. B. Ennis (w/o Att.)
NRC Project Manager
Millstone Power Station Unit 2

Mr. V. Nerses (w/o Att.)
NRC Senior Project Manager
Millstone Power Station Unit 3

Mr. S. M. Schneider (w/o Att.)
NRC Senior Resident Inspector
Millstone Power Station

**ATTACHMENT CONTAINS SAFEGUARDS INFORMATION.
UPON SEPARATION THIS PAGE IS DECONTROLLED.**

Docket No. 50-336
50-423
B18863

Attachment

Millstone Power Station, Unit Nos. 2 and 3

**Revised Response to Nuclear Regulatory Commission Security Order for Interim
Safeguards and Security Compensatory Measures**

**ATTACHMENT CONTAINS SAFEGUARDS INFORMATION.
UPON SEPARATION THIS PAGE IS DECONTROLLED.**