

**Department of Energy** 

Office of Civilian Radioactive Waste Management Yucca Mountain Site Characterization Office P.O. Box 98608 Las Vegas, NV 89193-8608

SEP 0 6 1995

L. Dale Foust
Technical Project Officer
for Yucca Mountain
Site Characterization Project
TRW Environmental Safety Systems, Inc.
Bank of America Center, Suite P-110
101 Convention Center Drive
Las Vegas, NV 89109

EVALUATION OF RESPONSES TO DEFICIENCY REPORTS (DR) YMQAD-95-D-004 THROUGH YMQAD-95-D-006 RESULTING FROM YUCCA MOUNTAIN QUALITY ASSURANCE DIVISION'S (YMQAD) AUDIT YM-ARP-95-16 OF THE CIVILIAN RADIOACTIVE WASTE MANAGEMENT SYSTEM MANAGEMENT AND OPERATING CONTRACTOR (SCPB: N/A)

The YMQAD staff has evaluated the responses to DRs YMQAD-95-D-004 through YMQAD-95-D-006. The responses have been determined to be satisfactory. Verification of completion of the remedial actions will be performed after the effective date provided. Any extension to this date must be requested in writing, with appropriate justification, prior to the date. Please send a copy of extension requests to Deborah Sult, YMQAD/QATSS, 101 Convention Center Drive, Suite 640, Las Vegas, Nevada 89109.

If you have any questions, please contact either Robert B. Constable at 794-7945 or Stephen R. Maslar at 794-7762.

Richard E. Spence, Director Yucca Mountain Quality Assurance Division

YMQAD:RBC-4478

Enclosure: CARs YMQAD-95-D-004 through YMQAD-95-D-006

cc w/encl:

U. G. Spraul, NRC, Washington, DC.

S. W. Zimmerman, NWPO, Carson City, NV

T. A. Wood, HQ (RW-14) FORS

R. L. Robertson, M&O, Vienna, VA Richard Jiu, M&O, Las Vegas, NV

R. P. Ruth, M&O, Las Vegas, NV

cc w/o encl:

W. L. Belke, NRC, Las Vegas, NV

D. G. Sult, YMQAD/QATSS, Las Vegas, NV

NH03 11 1027 WM-11

### L. Dale Foust

bcc w/encl:
J. W. Estella, M&O, Las Vegas, NV
S. R. Maslar, YMQAD/QATSS, Las Vegas, NV
J. R. Matras, YMQAD/QATSS, Las Vegas, NV
R. L. Craun, YMSCO, NV
J. M. Replogle, YMSCO, NV
B. J. Verna, YMSCO, NV



8	Performance Report Deficiency Report			ort t
	MY.ON	QAD	-95-D-0	04
	PAGE	1	OF 2	•

RADIOACTIVE WASTE MANAGEMENT U.S. DEPARTMENT OF ENERGY			NO.YMQAD-95-D-004
WASHINGTON, D.C.			PAGE 1 OF 2  QA: L
PERFORMANCE	E/DEFICIENCY REPO	RT	
1 Controlling Document: QARD and QAP 2-0, "Control of Activities."		2 Related Rep YM-ARP-95-1	
3 Responsible Organization: CRWMS M&O	4 Discussed With: Hugh Benton, Tom Doeri	ng	
5 Requirement/Measurement Criteria: 1. QARD Para. 2.2.3.F "quality assurance controls (gradin or end use of the item, 2) consequence of failure"	ng) shall be applied to the d	egree commens	urate with the 1) function
<ol><li>QARD Para. 3.1 "This section provides requirements to e controlled, and verified."</li></ol>	ensure that designs (from c	onceptual throu	gh final) are defined,
QAP-2-0 Para. 5.2.A.2 "If the activity must proceed prior item will be subject to QARD requirements."	r to the item being evaluate	d in accordance	with QAP-2-3, assume the
6 Description of Condition:  1. None of the design analysis that will be resulting from war QARD requirements based on CRWMS M&O QAP-2-0 Eval QAP-2-0 Evaluation forms and does not reflect consideration Evaluation forms are being used for the next phase of Waste 2. Shielding analyses have been completed for the waste page (BB0000000-01717-2200-00026) indicates the analyses are in the Q-List or otherwise subject to the QARD. A QAP-2-3 Evaluation of the design analyses are in the Q-List or otherwise subject to the QARD.	luation forms. The rational of the requirements of QA Package design activities, I ckage transporter. The QA not subject to QARD control	le for this detern RD Paras. 2.2.3 Preliminary Des P-2-0 Evaluation Ils because, in paragraphic	nination is contained on 3.F and 3.1. The same ign. on form art, the transporter is not on
7 Initiator CM atras Date 8/2/9.	9 QA Review 5 QAR Jaka	works Ematras	Tras 1 Date 8/2/95
10 Response Due Date 20 Working Days From Issuance	11 QA Issuance App QAR (PR)/AOQAM (	DUWU	No Date 8.2.95
12 Remedial Actions:			1 3 G & 18
13 Remedial Action Response By:  SEE ATTACHED PAGES Date		ATT A CHED	PAGE Date
15 Remedial Action Response Acceptance  OAR SEE ATTACHED PAGES Date	DAR SEE STTM	osure CHED PAGES.	Date

Exhibit AP-16.1Q.1

ERGLOSURE Rev. 07/03/95

### OFFICE OF CIVILIAN RADIOACTIVE WASTE MANAGEMENT

8 DR NO. YMQAD-95-D-004 PAGE 2 OF 2

· QA: L

	U.S. DEPARTME WASHING	· ·	
	DEFICIENC	Y REPORT	
17 Recommended Actions: Update evaluation forms as appropriate.			
18 Investigative Actions:			
19 Root Cause Determination:			
	·		
20 Action to Preclude Recurrence:			
	• •		
21 Response by: 6 Sec Attacked Page	75 ate 43	22 Corrective Action Completion Due 45 See Attached	Date:
21 Response by: 6 See Attached Page 23 Response Accepted OAR See Attached D	Pages alsk	24 Response Accepted AOOAM SEG STIACHED PAGES	Date
25 Amended Response Accepted	ate	26 Amended Response Accepted AOQAM	Date
27 Corrective Actions Verified	ate	28 Closure Approved by: AOQAM	Date



8		Performance Report Deficiency Report
l	بى	Democracy maport

RADIOACTIVE V	vaste managemi	ENT	
U.S. DEPART	TMENT OF ENERGY	,	NO.YHQAD-95-D-004
WASHINGTON, D.C.			PAGE 1 OF 2
			QA: L
PERFORMANCE	DEFICIENCY REPO	RT	
1 Controlling Document:		2 Related Rep	ort No.
QARD and QAP 2-0, "Control of Activities."	'	YM-ARP-95-	
3 Responsible Organization:	4 Discussed With:		<del></del>
CRWMS M&O	Hugh Benton, Tom Doering	ng	
5 Requirement/Measurement Criteria:			
<ol> <li>QARD Para. 2.2.3.F "quality assurance controls (grading or end use of the item, 2) consequence of failure"</li> </ol>	g) shall be applied to the d	egree commens	surate with the 1) function
A CARD Ross 2.1 William and a manufacture and the continuous and the c			-t-E-ab am daE-ad
<ol><li>QARD Para. 3.1 "This section provides requirements to e controlled, and verified."</li></ol>	nsure that designs (from $lpha$	inceptual throu	igh final) are defined,
a cancon so a control of the control			:: 01900 II
3. QAP-2-0 Para. 5.2.A.2 "If the activity must proceed prior	to the item being evaluated	in accordance	with QAP-2-3, assume the
item will be subject to QARD requirements."			
6 Description of Condition:			
1. None of the design analysis that will be resulting from wa			
QARD requirements based on CRWMS M&O QAP-2-0 Eval			
QAP-2-0 Evaluation forms and does not reflect consideration	•		
Evaluation forms are being used for the next phase of Waste I	ackage design activities, i	Teliminary De	agn.
2. Shielding analyses have been completed for the waste pac	knon transporter. The OAI	D-2-A Esminati	on form
(BB0000000-01717-2200-00026) indicates the analyses are n			
the Q-List or otherwise subject to the QARD. A QAP-2-3 Ev			
mo & mai or omer mas analysis to the & me & me. If & m 2 2 27	manda has not you occar w	mproted for th	o tumportus.
7 Initiator Com R Matros Jonate 8/2/95  10 Response Due Date	9 QA Review ()		_1
John K Matron	a CA HEVIEW JOY	$\sim$ $\sim$	stras
Marc J. Meyer · Date 8/3/95	OAR Jaka R	2 matras	Date 8/2/95
10 Response Due Date	11 QA Issuance App	roval	IN Vo
20 Working Days From Issuance	QAR (PR)/AOQAM (	DRIKKLOWI	The P Date 8. 2.95
12 Remedial Actions:			
SEE RESPONSE ON P.3 OF	3		
•			
·		•	
13 Remedial Action Response By:	14 Remedial Action [	ue Date	
MMay . Date 8/30/45	DOTOBER	6. 1995	. Date
15 Remedial Action Response-Acceptance	/ 16 PR Verification/Clo	<u> </u>	
(10 M M)	6el 1	110	·

Exhibit AP-16.10.1

Date Rev. 07/03/95

### OFFICE OF CIVILIAN RADIOACTIVE WASTE MANAGEMENT

8 DR NO. YMQAD-95-D-004 PAGE 2 OF 2

	OLE MANUACEMENT
U.S. DEPARTM	ENT OF ENERGY
WASHING	STON, D.C.
BEILA:	N/ PEROPE
<u> </u>	CY REPORT
17 Recommended Actions:	
Update evaluation forms as appropriate.	
	•
·	
18 investigative Actions:	
SEE RESPONSE ON P. 3 OF	3
OLE ICEOPERIOR	
·	
19 Root Cause Determination:	
•	
SEE RESPONSE ON P.3 OF	3
	·
·	
20 Action to Preclude Recurrence:	
SEE RESPONSE ON P.3 OF	. 2
002 1000 01100 011 7 7 00 011	G
	·
21 Response by:	22 Corrective Action Completion Due Date:
	i
MN/MM/9/ Date 8/30/45	OCTOBER 6, 1995
23 Response Accepted	24 Response Appented
1 . \ ) * / /// // // / /	1 1/11/19 11 11/19 11/19 11
Jan 76	ADDAM KNOWN HWO des Date 9.5.95
25 Amended Response Accepted	26 Amended Response Accepted
QAR Date	AOQAM Date
27 Corrective Actions Verified	<u> </u>
27 CONTECTIVE ACTIONS ACTUATED	28 Closure Approved by:
QAR Date_	AOQAM_ Date

В	<b>V</b>	Performance Report Deficiency Report

NO. LVMO-95-D-004

### PR/DR CONTINUATION PAGE

Continuation of Block 12 (Remedial Actions):

- 1. All Waste Package Development Department QAP-2-0 evaluations will be reviewed and revised as necessary, to insure that QARD control of activities related to MGDS Q-List items is applied properly.
- 2. Waste Package Development Department activities which include scoping analyses will be reevaluated to determine QARD applicability.

Continuation of Block 18 (Investigative Actions):

- 1. All Waste Package Development Department QAP-2-0 evaluations have been reviewed and revised as necessary to insure proper OARD control of activities related to MGDS Q-List items.
- 2. Waste Package Development Department activities which include scoping analyses have been reevaluated to determine QARD applicability.
- 3. A review of QAP-2-0, Control of Activities, REV 02, reveals that further clarification of what constitutes being "related" to an item on the WAST/MGDS Q-List would be helpful to the user of QAP-2-0. The scope of QAP-2-0 shall meet QARD requirements addressing scoping analyses. A Procedure Action Request for QAP-2-0 will be submitted which will expand on these recommendations.
- 4. The shielding analysis in question will be evaluated to determine whether its validity is impacted by the revised QAP-2-0 evaluation.

Continuation of Block 19 (Root Cause Determination):

No root cause determination based on investigative actions.

Continuation of Block 20 (Action to Preclude Recurrence):

1. All applicable QAP-2-0 evaluations have been revised to reflect that activities which include scoping analyses will be subject to QARD control. This action will preclude the recurrence of this deficiency.

Exhibit AP-16.1Q.3 Rev. 07/03/95



8	Performance Report Deficiency Report
	NO. <b>YMQAD-95-D-00</b> 5

	OFFICE OF CIVILIAN	☑ Deficiency Report
RADIOACTIVE WASTE MANAGEMENT U.S. DEPARTMENT OF ENERGY		NO THOMPOS TO THE
0.	WASHINGTON, D.C. PAGE 1 OF 3	
	·	QA: L
PERF	ORMANCE/DEFICIENCY RE	PORT
1 Controlling Document:		2 Related Report No.
QAP 3-9, Revision 5		YM-ARP-95-16
3 Responsible Organization: CRWMS M&O	4 Discussed With: Hugh Benton	
5 Requirement/Measurement Criteria: QAP 3-9, Revision 5, Attachment I, Item 7		
Design Analysis - requires the complete presen	• • • • •	alculations, are to be included such that any
qualified individual could review the analysis v	without recourse to the originator.	
		•
6 Description of Condition:		
Contrary to the above requirement, examination	• . <del>-</del>	
Identifier BB0000000-01717-0200-00005, Rev Canister with Disposal Container (TBV-060-W	•	-
"Initial Waste Package Probabilistic Criticality	-	•
B00000000-01717-2200-00079, Revision 00 sh	•	
the basic data and do describe how the calculat	<u>-</u>	
example, on page 6 of "Analysis of Degradation		
of water at 295K was calculated by linear interp		•
not given, nor the conversion factors from Fahr		•
corresponding pressures, $0.37549$ and $0.38844$ $0.33 \times (0.3884 - 0.37519) + 0.37549 = 0.38306$		
of the interpolation for density of saturated liqu	·-	•
71.44-0	10000	7/
	8/2/95 9 QA Review OAR 8.	Maslen Date \$12/95
10 Response Due Date	11 QA Issuance	
20 Working Days from Issuance	QAR (PR)/AOQA	M (DR) (DLouslable P Date X · 2 · 95
12 Remedial Actions:		
·		
	•	
	AC 1 4 4 7 7 7 7 7 7 7 7 7 7 7 7 7 7 7 7 7	
13 Remedial Action Response By:	13 14 Remedial Acti	on Due Date ATTACHED PASES Date
SEE ATTACHED PAGES D	ate ()) >22	
I b nemediai Action Kesponse Acceptance	1 Th PK Ventication	N/I JOSU <b>IC</b>

ATTACHED PAGES

Date

N/A QAR

Rev. 07/03/95

8 DR NO.YMQAD-95-D-005 PAGE 2 OF 3

· QA: L

DEFICIENC	CY REPORT
17 Recommended Actions:	
Review extent of problem and establish corrective action.	•
18 Investigative Actions:	
·	
19 Root Cause Determination:	<del></del>
19 hoot Cause Determination:	•
·	
	•
·	•
20 Action to Preclude Recurrence:	<u> </u>
·	
21 Response by:	22 Corrective Action Completion Due Date:
15 See Attached Pages Date 8/31/	& See Attached Pages
	24 Response Accepted SEE STINGHED PIGES
CARSEL A Hacked Pages Date	AOOAM Date
25 Amended Response Accepted	AOQAM Date  26 Amended Response Accepted
OAR Date	AOQAM Date
27 Corrective Actions Verified	28 Closure Approved by:
OAR Date	AOQAM Date

	Performance Report Deficiency Report
V	Deficiency Report

NO.YMQAD-95-D-005 PAGE 3 OF 3 QA: L

### PR/DR CONTINUATION PAGE

Block 6 (Continued)

been provided. It is noted that one of these values was calculated incorrectly. Identification of, or perhaps avoidance of, the error would have been assisted by having the details of the calculation at hand during the review by the document checker.

Exhibit AP-16.1Q.3 Rev. 07/03/95



Performance Report Deficiency Report
NO. THQAD-95-D-005

OFFICE OF CIVILIAN RADIOACTIVE WASTE MANAGEMENT U.S. DEPARTMENT OF ENERGY WASHINGTON, D.C.		NT P	Performance Report  V Deficiency Report  NO. YMQAD-95-D-005  PAGE 1 OF 3  OA: L	
	/DEFICIENCY REPO			
1 Controlling Document: QAP 3-9, Revision 5		2 Related Report   YM-ARP-95-16	No.	
3 Responsible Organization: CRWMS M&O	4 Discussed With: Hugh Benton			
5 Requirement/Measurement Criteria: QAP 3-9, Revision 5, Attachment I, Item 7 Design Analysis - requires the complete presentation of the ar	nalveis including all calcul	otions are to be in	cluded such that env	
qualified individual could review the analysis without recours		Mons, mo to oc m	cidaça such dan any	
6 Description of Condition: Contrary to the above requirement, examination of "Analysis of Identifier BB0000000-01717-0200-00005, Revision 00, "Initial Canister with Disposal Container (TBV-060-WPD)" Documer "Initial Waste Package Probabilistic Criticality Analysis: Und B00000000-01717-2200-00079, Revision 00 showed that this the basic data and do describe how the calculations were performantly on page 6 of "Analysis of Degradation due to Water of water at 295K was calculated by linear interpolation. However, nor the conversion factors from Fahrenheit to Celsi corresponding pressures, 0.37549 and 0.38844 psia, the conve 0.33 x (0.3884 - 0.37519) + 0.37549 = 0.383064 psia, and the of the interpolation for density of saturated liquid water at 295	al Waste Package Probabilism I Identifier B00000000-01 canistered Fuel (TBV-069-V requirement was not complormed, but do not include an and Gases in MPC" the statever, the vapor pressure actus, nor from psia to Pa. The ersion of 295K to F(295-273 conversion to Pa should all	stic Criticality And 717-2200-00080, I VPD," Document I lied with. These do actual copy of the tement is included a light used, as cited to temperatures used in the temperatures used in the second in the temperatures used in the temperatures used in the second in the temperatures used in the temperature use	alysis: Multi-Purpose Revision 00, and Identifier locuments do provide ese calculations. For I that the vapor pressure I from the reference are ed, 71 and 72 F, the 71.33, the interpolation, I. Similarly, the details	
7 Initiator Maslar Date 8/2/93	9 QA Review	Maslen	Date 8/2/95	
10 Response Due Date 20 Working Days from Issuance	11 QA Issuance Appro		EDate V. 2.95	
12 Remedial Actions:  SEL IZES PONSE ON D. 3 O.	<b>.</b> 3			
13 Remedial Action Response By:  Date 8/30/95	14 Remedial Action D  OCTOBER 6,	1996	Date	

Rev. 07/03/95

Date

B DR NO.YMQAD-95-D-005 PAGE 2 OF 3

QA: L

	T A CHILL	31011, 5101	
	DEFICIEN	CY REPORT	
17 Recommended Actions:			
Review extent of problem and establish	h corrective action.	•	
•			
·		·	
	•	•	
18 Investigative Actions:	<del></del>	<del></del>	
SEE RESPONSE OF	., 0.2 00.	2	
See RESPUTSE EL		9	
·			
•			
·			
<b>j</b> .			
19 Root Cause Determination:		<del> </del>	
SEE RESPONSE	ON P. 3	OF 3	
·			. •
	·		
20 Action to Preclude Recurrence:			
SEE RESPONSE	ON P. 3	OF 3	
			·
· ·		•	
		•	
·			•
	·		
21 Response by:		22 Corrective Action Comple	
MMSum71/	Date 8/30/15	OCTOBER 6, N	1995
23 Response Accepted	1/, -	24 Response Accepted	_ (
CARS. K. Master	Date 9/1/93	AODAM POMA VANO	Date 9.5.95
25 Amended Response Accepted	<del></del>	26 Amended Response Acce	
QAR	Date	AOQAM	Date
27 Corrective Actions Verified		28 Closure Approved by:	
OAR	Date	AOQAM	Date

8		Performance Report Deficiency Report
	_	

NO. YMQAD-95-D-005 PAGE 3 OF 3

QA: L

#### PR/DR CONTINUATION PAGE

#### 6 (Continued)

been provided. It is noted that one of these values was calculated incorrectly. Identification of, or perhaps avoidance of, the error would have been assisted by havng the details of the calculation at hand during the review by the document checker.

#### 12 Remedial Actions:

A revision will be issued for each of the documents (B00000000-01717-2200-00080 REV 00, B00000000-01717-2200-00079 REV 00 & BB0000000-01717-0200-00005 REV 00) with attachments illustrating the steps of all hand calculations.

A PAR on QAP-3-9 will be initiated, as specified in block 20, below.

### 18 Investigative Actions:

Of the 5 Waste Package Development documents prepared under QAP-3-9, three were the subject of this DR. The other two were reviewed for compliance as part of this investigation.

In one of the documents (BB0000000-01717-0200-00003 Rev 00) there were a number of dimensions given in both the English and the metric system. All of the conversions were a single multiplication or division, by a conversion factor known to engineers generally. There were no other calculations in the document.

In the other document (BBA000000-01717-0200-00121 Rev 00) the calculations involved repeated application of a simple formula to data from a large file, and tabulation of the results. The input data were identified as belonging to the Characteristics Database (CDB), a QA certified database. This CDB file is in dBASE IV format, and the source code (in dBASE programming language) giving the formula, which was applied to the data, is included. The checking was by an independent program which applied the same formula in FORTRAN.

It is, therefore, concluded that both documents have adequate detail and explanation of the calculations.

#### 19 Root Cause Determination:

No root cause determination, based upon investigative actions.

### 20 Action to preclude recurrence:

QAP-3-9 Attachment I, section 7 (Design Analysis) should be revised to read as follows:

7. Design Analysis - The complete analysis; including calculations, shall be presented in sufficient detail that a qualified individual would be able to understand, and reproduce, the analysis without recourse to the originator.

8	Performance Report Deficiency Report
	E Delicielley Report

DADIOACTIVE	INVACTO BEARIAGERS	CRIT	E believely report
RADIOACTIVE WASTE MANAGEMENT U.S. DEPARTMENT OF ENERGY		NO.YMQAD-95-D-006	
WASI	HINGTON, D.C.		PAGE 1 OF 3
	<del></del>	<del></del>	QA: L
	E/DEFICIENCY REPO		
1 Controlling Document:		2 Related Rep	
QAP 3-9, Revision 5		YM-ARP-95-	·10
3 Responsible Organization:	4 Discussed With:		
CRWMS M&O	Hugh Benton		
5 Requirement/Measurement Criteria:	<del></del>		
Para 5.2.3A: Requires a check of the design analysis for co	mpleteness and technical ad	lequacy.	
Days 5 2 2D. Descriptor a sheek that design innute much name		4-4	ricka famoura in the decises
Para 5.2.3B: Requires a check that design inputs were corr	ectly selected and incorpora	ted, are approp	nate for use in the design.
		_	
	4.		
			•
6 Description of Condition:	<del></del>	<del></del>	
Contrary to the above requirements, the following condition	is are noted:		
1. Document BB0000000-01717-0200-00005, revision 00		•	• • • • • • • • • • • • • • • • • • •
copy reviewed does not provide objective evidence that the a			
check to verify the above requirements. The checklist used			
that was noted as satisfactory could not have been complete	<b>-</b>	e check. This	question is: Are appropriate
signatures in place with proper dates on the design analysis	review summary?		
2. Margin and text notations in the initial copy for "Initial	Waste Package Probabilisti	c Criticality Ar	obsis: Unconistered Evel
(TBV-069-WPD)" Document Identifier B00000000-01717-		•	•
calculations were checked. However, none of the back chec	•		
version, Revision 00, provide objective evidence that these of			•
7 Initiator 8 Markey 8/2/0	9 QA Reviewa		
Stephen'R Maslar Date 2/9	~   " Wherew	m. 1	8/2/9/s
\ <u></u>		"Ilang	Date Date
10 Response Due Date	11 QA Issuance App	T OF Caron	(1) ter
20 Working Days From Issuance	QAR (PR)/AOQAM	(DR) (Dan)	Chin 1 Date 8. 2. 95
12 Remedial Actions:			
·			
	•		
			•
	•		•
			•
13 Remedial Action Response By:	14 Remedial Action	Due Date	<del></del>
SEE ATTACHED PAGES Date	9/31/18 SEE ATTI	ACHED PA	RES Date
15 Remedial Action Response Acceptance	080 16 PR Verification/C	,	
Seg attached pages	11.71 (AS. 1774C)	HED PLACES-	D-4-
QAR Date	distr CAR SEE STIME		Date

Exhibit AP-16.1Q.1

disto dar see attached places-Enclusus.

Rev. 07/03/95

8 DR NO.YMQAD-95-D-006 PAGE 2 OF 3 QA: L

DEFICIEN	NCY REPORT
17 Recommended Actions:	
Evaluate extent of the problem and insure recently implemented	d corrective actions will be effective.
•	
•	
·	
18 Investigative Actions:	
•	
19 Root Cause Determination:	
	·
·	
20 Action to Preclude Recurrence:	
, · ·	
·	
·	•
·	
·	
21 Response by:	22 Corrective Action Completion Due Date:
k = 0	and Can Alle 1 - 1 Break
	2 24 Response Accepted
6 (PA / VB) a bad Pakan	PL 24 Response Accepted
	NOGAN Total
25 Amended Response Accepted	26 Amended Response Accepted
QAR Date	AOQAM Date
27 Corrective Actions Verified	28 Closure Approved by:
QAR Date	AOQAM Date

8		Performance Report Deficiency Report
	V	Deficiency Report

NO.YMQAD-95-D-006 PAGE 3 OF 3

QA: L

### PR/DR CONTINUATION PAGE

Block 6 (Continued)

consequence of a notation in revision 00A added new text and data, of which one datum was wrong. This error appears in the final document, Revision 00.

- 3. The same error also appears in the corresponding place in "Initial Waste Package Probabilistic Criticality Analysis: Multi-Purpose Canister with Disposal Container (TBV-060-WPD)," Document Identifier B00000000-01717-2200-00080, Revision 00, again with no objective evidence that calculations were rechecked. The initial review for this document was begun after the final check for the previous document.
- 4. It is also noted that for BB0000000-01717-0200-0003, Revision 00, there is no objective evidence that the checker reviewed the check copy. No initials exist on any page of the check copy. Further, the design analysis checklist is signed by a different individual than the one that signed as the checker on the design analysis review summary sheet.

Exhibit AP-16.1Q.3



EACLUSURE Rev. 07/03/95

RADIOACTIVE WASTE MANAGEMENT U.S. DEPARTMENT OF ENERGY WASHINGTON, D.C.			NO.YMQAD-95-D-006 PAGE 1 of 3
WASHINGTON, D.C.		·	QA: L
PERFORMANC	E/DEFICIENCY REPO	RT	
1 Controlling Document: QAP 3-9, Revision 5		2 Related Report YM-ARP-95-16	; No.
3 Responsible Organization:  CRWMS M&O  4 Discussed With:			
5 Requirement/Measurement Criteria:	Hugh Benton		
Para 5.2.3A: Requires a check of the design analysis for completeness and technical adequacy.  Para 5.2.3B: Requires a check that design inputs were correctly selected and incorporated, are appropriate for use in the design.			
6 Description of Condition: Contrary to the above requirements, the following conditions	s are noted:		
<ol> <li>Document BB0000000-01717-0200-00005, revision 00 and BB0000000-01717-0200-00003, revision 00 - the discipline check copy reviewed does not provide objective evidence that the above requirements were checked. The checklists used did not require a check to verify the above requirements. The checklist used is a compliance (procedure) checklist. One of the checklist questions that was noted as satisfactory could not have been completed at the time of the discipline check. This question is: Are appropriate signatures in place with proper dates on the design analysis review summary?</li> <li>Margin and text notations in the initial copy for "Initial Waste Package Probabilistic Criticality Analysis: Uncanistered Fuel (TBV-069-WPD)" Document Identifier B00000000-01717-2200-00079, Revision 00A do provide objective evidence that calculations were checked. However, none of the back check copy, Revision 00B; the final check copy, Revision 00D; nor the final version, Revision 00, provide objective evidence that these documents underwent the same careful scrutiny. Changes made as a</li> </ol>			
7 Initiator ( Maslar Date / 2/9)	9 QA Review OAR S, R.	Mada	8/2/96 Date
10 Response Due Date	11 QA Issuance App	The and	la .
20 Working Days From Issuance 12 Remedial Actions:	QAR (PR)/AOQAM (	DRI Would	10 Poate 8. 2. 95
SEE RESPONSE ON P. 3 OF3			
13 Remedial Action/Flesponse B/	14 Remedial Action I		Date (
15 Remedial Action Response Acceptance	16 PR Verification/Cl		Date
Date 9/1/9	J QAR	aln	Date

Exhibit AP-16.1Q.1

BDR NO. YMQAD-95-D-006 PAGE 2 OF 3 QA: L

DEFICIENCY REPORT		
17 Recommended Actions: Evaluate extent of the problem and ensure recently implemented	corrective actions will be effective.	
	·	
	•	
of the Product Checking Group (PCG). The MGDS Design Gui 5/29/95, requires that "the PCG manager, in conjunction with the document." Conversations with the Product Checking Group Maron a full time basis) have indicated that the deficiencies cited in process now in effect. The new Design Analysis Checklist is murchecking the four documents cited in (6). Furthermore, PCG checkling the second contents of the product Checkling the four documents cited in (6).	anager and group members (those checking engineering document (6) would without question be discovered during the checking ch more comprehensive than the checklists employed while	
19 Root Cause Determination: No root cause identification of condition is required, based on in	vestigative action.	
(question 7, with many subparts) and compliance check. Manda Checklists for Design Products Rev 00, 8/11/95. The Design An employed while checking the four documents cited in (6). Furthe PCG manager, in conjunction with the LDE, will select quare permanent PCG member, the selected person will perform only a	esign Analysis Checklist which now addresses both technical check tory use of the Design Analysis Checklist is invoked by NLP-3-28 alysis Checklist is much more comprehensive than the checklists ermore, the PCG MGDS Design Guidelines Manual requires that diffied personnel to check the engineering document." If not a technical check, unless authorized by the PCG manager to also assigned to perform a separate compliance check (thus there may	
MM1415 Date 8/30/95	10/06/95	
OAR S. Rimanda Date 9/1/95	AOQAM ROOM FOR Date Q.S.95	
25 Amended Response Accepted	26 Amended Response Accepted	
OAR Date 27 Corrective Actions Verified	AOQAM Date	

**MADOA** 

Date

**QAR** 

Date

Performance Report Deficiency Report

NO. YMQAD-95-D-006 PAGE 3 OF 3

QA: L

### PR/DR CONTINUATION PAGE

Block 6 (Continued)

consequence of a notation in revision 00A added new text and data, of which one datum was wrong. This error appears in the final document, Revision 00.

- 3. The same error also appears in the corresponding place in "Initial Waste Package Probabilistic Criticality Analysis: Multi-Purpose Canister with Disposal Container (TBV-060-WPD)," Document Identifier B00000000-01717-2200-00080, Revision 00, again with no objective evidence that calculations were rechecked. The initial review for this document was begun after the final check for the previous document.
- 4. It is also note that for BB0000000-01717-0200-00003, Revision 00, there is no objective evidence that the checker reviewed the check copy. No initials exist on any page of the check copy. Further, the design analysis checklist is signed by a different individual than the one that signed as the checker on the design analysis review summary sheet.

#### Block 12 Remedial Actions:

IOC LV.MG.AMS.8/95-129, Checking/Review by Product Checking Group (SCPB: N/A), 8/21/95 states that Product Checking Group (PCG) check is mandatory for Design Analyses, Specifications, and Drawings that are quality affecting.

Regarding Block 6 Item 1: NLP-3-28, Checklists for Design Products, Rev 0, 8/11/95, requires use of expanded technical and compliance checklists. A signed and dated notation by the technical checker (A. Roy) has been added to document BB0000000 -01717-0200-00003 Cover Sheet attesting that Dr. Roy performed the technical check on 2/15/95, the day before he signed the Review Summary sheet box #7. Document BB0000000-01717-0200-00005 will be corrected and reissued as Revision 01; the revisions will be checked by the individual(s) designated by PCG.

Regarding Block 6 Items 2 and 3: Each document (B00000000-01717-2200-00079 and B00000000-01717-2200-00080) will be corrected and reissued as Revision 01; the revisions to each will be checked by the individual(s) designated by PCG.

Regarding Block 6 Item 4: A signed and dated notation by the technical checker (A. Roy) has been added to document BB0000000-01717-0200-00003 Cover Sheet attesting that Dr. Roy performed the technical check on 2/15/95, the day before he signed the Review Summary sheet box #7. Two checker signatures will occur whenever PCG assigns different individuals to perform the technical check and the compliance check.

Exhibit AP-16.1Q.3 Rev. 07/03/95