

July 15, 1998

EA 98-367

Mr. Paul H. Kinkel
Vice President - Nuclear Power
Consolidated Edison Company of
New York, Inc.
Indian Point 2 Station
Broadway and Bleakley Avenues
Buchanan, NY 10511

SUBJECT: INDIAN POINT 2 MAINTENANCE RULE BASELINE TEAM INSPECTION
REPORT 50-247/98-10

Dear Mr. Kinkel:

This refers to the team inspection conducted on June 8 through 12, 1998, at the Indian Point 2 (IP2) reactor facility. The purpose of the inspection was to review the implementation of the maintenance rule program under 10 CFR 50.65 at IP2. The enclosed report presents the results of this inspection effort.

Overall, we concluded that your facility had implemented the maintenance rule acceptably at the time of the inspection, with the exception of the apparent violations identified below. We are concerned, however, that before January 1998 significant performance weaknesses and inadequacies existed that indicated an apparent organizational ineffectiveness in initial implementation of the maintenance rule. We noted that a number of revisions and substantial improvements to your program were implemented just prior to this inspection.

Based on the results of this inspection, the NRC has determined that apparent violations of NRC requirements occurred. The violations were identified by the NRC, in part, and included: 1) failure to place several systems into an (a)(1) status in a timely manner commensurate with safety, and 2) failure to include in the scope of the maintenance rule program as required by 10 CFR 50.65(b) the emergency lighting system, the communications system, and several annunciators.

We are continuing to review the violations as related to the past problem with maintenance rule implementation. We will contact you shortly on our enforcement decision.

9807210122 980715
PDR ADOCK 05000247
G PDR

Paul H. Kinkel

2

In accordance with 10 CFR 2.790 of the NRC's "Rules of Practice," a copy of this letter and its enclosures will be placed in the NRC Public Document Room (PDR).

Sincerely,

ORIGINAL SIGNED BY:

James Wiggins, Director
Division of Reactor Safety

Docket No. 50-247
License No. DPR-26

Enclosure: Inspection Report No. 50-247/98-10

cc w/encl:

N. Carns, Senior Vice President - Nuclear Operations
G. Hutcherson, Chief Nuclear Engineer
C. Jackson, Manager, Nuclear Safety and Licensing
B. Brandenburg, Assistant General Counsel
C. Faison, Director, Nuclear Licensing, NYPA
J. Ferrick, Operations Manager
D. Murphy, Work Control Manager
C. Donaldson, Esquire, Assistant Attorney General, New York Department of Law
P. Eddy, Electric Division, Department of Public Service, State of New York
T. Rose, Secretary - NFSC
F. William Valentino, President, New York State Energy Research
and Development Authority
J. Spath, Program Director, New York State Energy Research and Development Authority

Paul H. Kinkel

3

Distribution w/encl:

H. Miller, RA/W. Axelson, DRA

B. Boger, ADPR, NRR

D. Holody, ORA

B. Fewell, ORA

Nuclear Safety Information Center (NSIC)

PUBLIC

NRC Resident Inspector

Region I Docket Room (w/concurrences)

J. Rogge, DRP

R. Barkley, DRP

R. Junod, DRP

DRS File Copy

Distribution w/encl: (VIA E-MAIL)

B. McCabe, RI EDO Coordinator

R. Temps - Indian Point 2

S. Bajwa, NRR

J. Harold, NRR

G. Wunder, NRR

M. Campion, RI

Inspection Program Branch, NRR (IPAS)

R. Correia, NRR

F. Talbot, NRR

DOCDESK

F. Davis, OGC

A. Nicosia, OGC

J. Lieberman, OE (OEMAIL)

DOCUMENT NAME: G:\OLHP\BISSETT\IP298-10

To receive a copy of this document, indicate in the box: "C" = Copy without attachment/enclosure "E" = Copy with attachment/enclosure "N" = No copy

OFFICE	RI/DRS		RI/ORA <i>pw</i>	<input checked="" type="checkbox"/> RI/DRS		RI/DRS.	
NAME	PBissett <i>DS for</i>		DHolody <i>for</i>	RConte <i>DS for</i>		JWiggins <i>g</i>	
DATE	07/15/98		07/15/98	07/15/98		07/15/98	

OFFICIAL RECORD COPY

To receive a copy of this document, indicate in the box: "C" = Copy without attachment/enclosure "E" = Copy with attachment/enclosure "N" = No copy

OFFICE	RI/DRP						
NAME	JRogge <i>M</i>						
DATE	07/15/98						

OFFICIAL RECORD COPY