

# NRC INSPECTION MANUAL

IIPB

---

Change Notice 03-030

---

## DELETED:

	<u>Number</u>	<u>Date</u>
1.	IP 60851	05/22/00
2.	IP 60852	07/12/00

## TRANSMITTED:

	<u>Number</u>	<u>Date</u>
	IP 60851	08/08/03
	IP 60852	08/08/03

TRAINING: No special training requirements have been identified for any documents issued with this change notice.

REMARKS: IP 60851 (Design Control of ISFSI Components) has been revised for clarity and to reflect current practice.

IP 60852 (ISFSI Component Fabrication by Outside Fabricators) has been revised to comply with safety changes and recommendations of the Safety Analysis Report and the NRC's corresponding safety evaluation outlined in 10 CFR 72.

DISTRIBUTION: Standard

END