

Stephen A. Byrne
Senior Vice President, Nuclear Operations
803.345.4622



September 16, 2003

Document Control Desk
U. S. Nuclear Regulatory Commission
Washington, DC 20555


Ladies and Gentlemen:

Subject: VIRGIL C. SUMMER NUCLEAR STATION
DOCKET NO. 50-395
OPERATING LICENSE NO. NPF-12
LICENSEE EVENT REPORT (LER 2003-S02-00)
ACCESS TO PROTECTED AREA BY AN INDIVIDUAL WITH EXPIRED
TRAINING

Attached is Licensee Event Report (LER) No. 2003-S02-00, for the Virgil C. Summer Nuclear Station (VCSNS). The report describes an event in which an individual gained access to the protected area after their access authorization had been removed due to the individual's training requirements being expired. This report is being submitted in accordance with 10 CFR 73.71, Appendix G(3)(b).

Should you have any questions, please call Mr. Ronald B. Clary at (803) 345-4757.

Very truly yours,


Stephen A. Byrne
*PER DIRECTION
OF S. BYRNE
ON 9/16/03*

SBR/SAB/sr
Attachment

c: N. O. Lorick
N. S. Cams
T. G. Eppink (w/o attachment)
R. J. White
L. A. Reyes
K. R. Cotton
NRC Resident Inspector
M. N. Browne
Paulette Ledbetter
D. L. Abstance

EPIX Coordinator
K. M. Sutton
INPO Records Center
J&H Marsh & McLennan
NSRC
RTS (0-C-03-0635)
File (818.07)
DMS (RC-03-0195)

IE22

LICENSEE EVENT REPORT (LER)

(See reverse for required number of digits/characters for each block)

Estimated burden per response to comply with this mandatory information collection request: 50 hours. Reported lessons learned are incorporated into the licensing process and fed back to industry. Send comments regarding burden estimate to the Records Management Branch (T-6 E6), U.S. Nuclear Regulatory Commission, Washington, DC 20555-0001, or by internet e-mail to bjs1@nrc.gov, and to the Desk Officer, Office of Information and Regulatory Affairs, NEOB-10202 (3150-0104), Office of Management and Budget, Washington, DC 20503.

1. FACILITY NAME Virgil C. Summer Nuclear Station	2. DOCKET NUMBER 05000395	3. PAGE 1 OF 3
---	-------------------------------------	--------------------------

4. TITLE
Access to Protected Area by an individual with expired training

5. EVENT DATE			6. LER NUMBER			7. REPORT DATE			8. OTHER FACILITIES INVOLVED	
MO	DAY	YEAR	YEAR	SEQUENTIAL NUMBER	REV NO	MO	DAY	YEAR	FACILITY NAME	DOCKET NUMBER
08	22	2003	2003	S02	00	09	16	2003		05000395

9. OPERATING MODE 1	11. THIS REPORT IS SUBMITTED PURSUANT TO THE REQUIREMENTS OF 10 CFR §: (Check all that apply)									
	<input type="checkbox"/> 20.2201(b)	<input type="checkbox"/> 20.2203(a)(3)(ii)	<input type="checkbox"/> 50.73(a)(2)(ii)(B)	<input type="checkbox"/> 50.73(a)(2)(ix)(A)						
10. POWER LEVEL 100	<input type="checkbox"/> 20.2201(d)	<input type="checkbox"/> 20.2203(a)(4)	<input type="checkbox"/> 50.73(a)(2)(iii)	<input type="checkbox"/> 50.73(a)(2)(x)						
	<input type="checkbox"/> 20.2203(a)(1)	<input type="checkbox"/> 50.36(c)(1)(i)(A)	<input type="checkbox"/> 50.73(a)(2)(iv)(A)	<input type="checkbox"/> 73.71(a)(4)						
	<input type="checkbox"/> 20.2203(a)(2)(i)	<input type="checkbox"/> 50.36(c)(1)(ii)(A)	<input type="checkbox"/> 50.73(a)(2)(v)(A)	<input type="checkbox"/> 73.71(a)(5)						
	<input type="checkbox"/> 20.2203(a)(2)(ii)	<input type="checkbox"/> 50.36(c)(2)	<input type="checkbox"/> 50.73(a)(2)(v)(B)	<input checked="" type="checkbox"/>	OTHER Specify in Abstract below or in NRC Form 366A					
	<input type="checkbox"/> 20.2203(a)(2)(iii)	<input type="checkbox"/> 50.46(a)(3)(ii)	<input type="checkbox"/> 50.73(a)(2)(v)(C)							
	<input type="checkbox"/> 20.2203(a)(2)(iv)	<input type="checkbox"/> 50.73(a)(2)(i)(A)	<input type="checkbox"/> 50.73(a)(2)(v)(D)							
	<input type="checkbox"/> 20.2203(a)(2)(v)	<input type="checkbox"/> 50.73(a)(2)(i)(B)	<input type="checkbox"/> 50.73(a)(2)(vii)							
	<input type="checkbox"/> 20.2203(a)(2)(vi)	<input type="checkbox"/> 50.73(a)(2)(i)(C)	<input type="checkbox"/> 50.73(a)(2)(viii)(A)							
	<input type="checkbox"/> 20.2203(a)(3)(i)	<input type="checkbox"/> 50.73(a)(2)(ii)(A)	<input type="checkbox"/> 50.73(a)(2)(viii)(B)							

12. LICENSEE CONTACT FOR THIS LER

NAME R. B. Clary, Mgr., Nuclear Licensing	TELEPHONE NUMBER (Include Area Code) (803) 345-4757
---	---

13. COMPLETE ONE LINE FOR EACH COMPONENT FAILURE DESCRIBED IN THIS REPORT

CAUSE	SYSTEM	COMPONENT	MANUFACTURER	REPORTABLE TO EPIX	CAUSE	SYSTEM	COMPONENT	MANUFACTURER	REPORTABLE TO EPIX
A				No					

14. SUPPLEMENTAL REPORT EXPECTED				15. EXPECTED SUBMISSION DATE	MONTH	DAY	YEAR
YES (If yes, complete EXPECTED SUBMISSION DATE).	<input checked="" type="checkbox"/>	NO					

16. ABSTRACT (Limit to 1400 spaces, i.e., approximately 15 single-spaced typewritten lines)

This report is being made pursuant to the requirements of 10CFR73.71, Appendix G(3)(b).

On August 22, 2003, during a review of Security records, it was discovered that on May 28, 2003, a badged individual had not successfully completed the necessary retraining for unescorted access. The access authorization for the protected area was removed when the individual's training expired. Access authorization was subsequently restored prior to completion of training. The individual visits the plant infrequently and was not aware that his training had expired. VCSNS believes that the event occurred unintentionally.

This event was due to an oversight by access control personnel. Access control personnel authorized the change in badge status without confirming that all requirements for access had been met. Upon the discovery, the individual completed the training and his access was granted. The individual did not enter any vital areas of the plant during this time however he did enter the protected area.

LICENSEE EVENT REPORT (LER)

1. FACILITY NAME	2. DOCKET	6. LER NUMBER			3. PAGE
V.C.Summer Nuclear Station	05000395	YEAR	SEQUENTIAL NUMBER	REVISION NUMBER	2 OF 3
		2003	-- S02 --	00	

17. NARRATIVE (If more space is required, use additional copies of NRC Form 366A)

PLANT IDENTIFICATION

Westinghouse - Pressurized Water Reactor

EQUIPMENT IDENTIFICATION

N/A

IDENTIFICATION OF EVENT

On August 22, 2003, during a review of Security records, it was discovered that on May 28, 2003, a badged individual had not successfully completed the necessary retraining for unescorted access. The access authorization for the protected area was removed when the individual's training expired. Access authorization was subsequently restored prior to completion of training. The individual visits the plant infrequently and was not aware that his training had expired. VCSNS believes that the event occurred unintentionally.

This event was due to an oversight by access control personnel. Access control personnel authorized the change in badge status without confirming that all requirements for access had been met. Upon the discovery, the individual completed the training and his access was granted. The individual did not enter any vital areas of the plant during this time however he did enter the protected area.

VCSNS believes that this event occurred unintentionally. This event was documented in Condition Evaluation Report (CER) 03-2654.

DISCOVERY DATE

08/22/03

REPORT DATE

09/16/03

LICENSEE EVENT REPORT (LER)

1. FACILITY NAME	2. DOCKET	6. LER NUMBER			3. PAGE
V.C.Summer Nuclear Station	05000395	YEAR	SEQUENTIAL NUMBER	REVISION NUMBER	3 OF 3
		2003	-- S02 --	00	

17. NARRATIVE (If more space is required, use additional copies of NRC Form 366A)

CONDITIONS PRIOR TO EVENT

Mode 1, 100% power

DESCRIPTION OF EVENT

On August 22, 2003 during a review of Security records, it was determined that on May 28, 2003 a badged individual had not successfully completed the necessary retraining for unescorted access. When the individual's training expired, the access authorization for the protected area was removed. Access authorization was subsequently restored prior to completion of the required training.

CAUSE OF EVENT

This event was due to an oversight by access control personnel. Access control personnel authorized the change in badge status without confirming that all requirements for access had been met

ANALYSIS OF EVENT

During the investigation of the event it was determined that the individual did enter the protected area but did not enter any vital areas. Upon the discovery, the individual completed the training and his access was granted.

CORRECTIVE ACTIONS

A review was conducted of all Unescorted Access Change Forms generated to reinstate access for the period of 12/23/02-09/03/03. No discrepancies were discovered during the review.

Revisions will be made to the Security Plan Procedure to formalize process for reinstatement of security badge. This will be completed by 12/31/03.

PRIOR OCCURRENCES

None