



0CAN090301

September 15, 2003

U.S. Nuclear Regulatory Commission Attn: Document Control Desk Washington, DC 20555-0001

Subject:

Monthly Operating Report

Arkansas Nuclear One - Units 1 and 2

Docket Nos. 50-313 and 50-368 License Nos. DPR-51 and NPF-6

Dear Sir or Madam:

Arkansas Nuclear One (ANO), Units 1 and 2 Technical Specifications 5.6.4 and 6.9.1.6, respectively, require the submittal of a Monthly Operating Report. The purpose of this letter is to complete the reporting requirement for August 2003.

There are no new commitments contained in this submittal.

Sincerely,

Glenn R. Ashley Manager, Licensing

Ale R. ashly

GRA/SLP

Attachment(s)

IEAY

cc: Mr. Thomas P. Gwynn
Acting Regional Administrator
U. S. Nuclear Regulatory Commission
Region IV
611 Ryan Plaza Drive, Suite 400
Arlington, TX 76011-8064

NRC Senior Resident Inspector Arkansas Nuclear One P.O. Box 310 London, AR 72847

U. S. Nuclear Regulatory Commission Attn: Mr. John Minns Mail Stop 0-7 D1 Washington, DC 20555-0001

U. S. Nuclear Regulatory Commission Attn: Mr. Thomas Alexion Mail Stop 0-7 D1 Washington, DC 20555-0001

OPERATING DATA REPORT

DOCKET NO.

50-313

UNIT NAME

Arkansas Nuclear One - Unit 1

DATE

September 15, 2003

COMPLETED BY Steven L. Coffman

TELEPHONE

(479) 858-5560

REPORTING PERIOD:

August 2003

1.

Design Electrical Rating (MWe-Net):

Maximum Dependable Capacity (MWe-Net): 2.

850 836

> **CUMULATIVE** 198,239.4 195,539.3 817.5 150,690,702

		<u>MONTH</u>	YR-TO-DATE
3.	Number of Hours Reactor Was Critical	710.9	5,797.9
4.	Number of Hours Generator On-Line	686.5	5,773.5
5.	Unit Reserve Shutdown Hours	0.0	0.0
6.	Net Electrical Energy Generated (MWh)	571 320	4 870 365

UNIT SHUTDOWNS

<u> </u>						
<u>No.</u>	<u>Date</u>	Type F: Forced <u>S: Scheduled</u>	Duration (Hours)	Reason ¹	Method of Shutting <u>Down²</u>	Cause & Corrective Action <u>Comments</u>
2003-01	030829	F	57.5	Н	3	Lightning is suspected to have caused an automatic scram.

SUMMARY: The Unit began the month at 85% power, with a Heater Drain Pump motor replacement in progress. The Unit returned to full power on 08/02/2003. On 08/29/2003, an unplanned automatic scram occurred. The scram was suspected to have been caused by a lightning strike in the vicinity of the switchyard. The Unit ended the month off line, with preparations in progress to return the Unit to full power.

1

Reason:

Equipment Failure (Explain) Α

Maintenance or Test В

C Refueling

Regulatory Restriction D

Operator Training & License Examination

Administration

G Operational Error (Explain)

Other (Explain)

2

Method:

- 1 Manual
- 2 Manual Trip/Scram
- 3 Automatic Trip/Scram
- 4 Continuation
- 5 Other (Explain)

OPERATING DATA REPORT

DOCKET NO.

50-368

UNIT NAME

Arkansas Nuclear One - Unit 2

DATE

September 15, 2003

COMPLETED BY

Steven L. Coffman

TELEPHONE

(479) 858-5560

REPORTING PERIOD:

August 2003

1. **Design Electrical Rating (MWe-Net):** 912

2. Maximum Dependable Capacity (MWe-Net): 858

Number of Hours Reactor Was Critical 3.

CUMULATIVE MONTH YR-TO-DATE 744.0 5,831.0 167,705.0

4. **Number of Hours Generator On-Line** 744.0 5,831.0 165,172.5

5. **Unit Reserve Shutdown Hours** 0.0 0.0 0.0

Net Electrical Energy Generated (MWh) 6.

663,703 5,781,541.0 141,971,802

UNIT SHUTDOWNS

<u>No.</u>	<u>Date</u>	Type F: Forced S: Scheduled	Duration (Hours)	Reason ¹	Method of Shutting <u>Down²</u>	Cause & Corrective Action <u>Comments</u>
None			-			

SUMMARY: The Unit began the month at full power. On 08/06/2003, the Unit began a coast down in preparation for the 2R16 Refueling Outage. The Unit was at 77% power at the end of the month.

1 Reason:

> **Equipment Failure (Explain)** Α

Maintenance or Test В

C Refueling

Regulatory Restriction D

Ε **Operator Training & License Examination**

F Administration

G Operational Error (Explain)

Other (Explain)

2

Method:

- Manual
- Manual Trip/Scram
- Automatic Trip/Scram 3
- Continuation
- Other (Explain)