

37-30804-02

September 24, 2003

Nuclear Regulatory Commission Region I 475 Allendale Road King of Prussia, PA 19406-1415

Dr. Sattar Lodhi:

We would like to make a slight modifications made to the plenum. As per our license we are making notification. This change is to address the concerns of Reviss with water entering the plenum due to the plenum having a lower pressure than the surroundings. The change will give a conclusive way of knowing whether or not here is water in the plenum. We will no long need to rely on the moisture probe for an indication of water entering the plenum.

The change is that the check valve will be removed from the bottom of the plenum. The check valve was originally intended to be used for purging the water out of the plenum. We would now use the air line that attaches to the bottom of the plenum to purge the water out of the plenum. There would be no change to the air line. This method offers us a much more positive indication of when all the water has been purged from the plenum and it also would tells us how much water was in the plenum because we could see all the water that comes out of the line and we also could see when water stops coming out and air starts rushing out.

This is to be done so that the air can be run at a higher pressure. This will ensure that any transfer between the plenum and the outside is one of air out instead of water into plenum.

The only structural change to the plenum would be the removal of the check valve and the addition of a plug in its place. The check valve is seen on drawing number 36783-017-000.

If you need any additional information I can be reached at 215-529-9522.

Sincerely,

Marie Turner

Radiation Safety Officer

CFC Logistics

This is to acknowledge the receipt of your letter/application dated		
includes an administrative review l	•	
There were no administrative omissions. Your application was assigned to a technical reviewer. Please note that the technical review may identify additional omissions or require additional information.		
Please provide to this office within 30 days of your receipt of this card		
Branch, who will contact you separ	warded to our License Fee & Accounts Receivable rately if there is a fee issue involved.	
Your action has been assigned Ma When calling to inquire about this You may call us on (610) 337-539	nil Control Number 133717/133718 action, please refer to this control number. 8, or 337-5260.	
NRC FORM 532 (RI) (6-96)	Sincerely, Licensing Assistance Team Leader	

	: (FOR LFMS USE) : INFORMATION FROM LTS
BETWEEN:	:
and	Program Code: 03521 Status Code: 0 Fee Category: 3G Exp. Date: 20130831 Fee Comments: Decom Fin Assur Reqd: Y
LICENSE FEE TRANSMITTAL	
A. REGION	
1. APPLICATION ATTACHED Applicant/Licensee: CFC LOGISTICS, Received Date: 20030925 Docket No: 3036239 Control No.: 133717 License No.: 37-30804-02 Action Type: Amendment	INC.
2. FEE ATTACHED Amount: Check No.:	
3. COMMENTS Signed Date	M. a. Parkina 9/16/2003
B. LICENSE FEE MANAGEMENT BRANCH (Check	when milestone 03 is entered //)
1. Fee Category and Amount:	
2. Correct Fee Paid. Application may lamendment Renewal License	be processed for:
3. OTHER	
Signed	

Date