



Entergy Operations, Inc.
River Bend Station
5485 U. S. Highway 61
St. Francisville, LA 70775
Tel 225 381 4642
Fax 225 635 5068
jleavin@entergy.com

Joseph W. Leavines
Manager-Licensing

October 14, 2003

U. S. Nuclear Regulatory Commission
Document Control Desk
Washington, DC 20555

Subject: Monthly Operating Report
River Bend Station Unit 1
Docket No. 50-458
License No. NPF-47

File No.: G9.5, G4.25

RBG-46186
RBF1-03-0192

Ladies and Gentlemen:

In accordance with River Bend Station Technical Specification 5.6.4, enclosed is the Monthly Operating Report for September 2003.

Sincerely,


JWL/dhw
enclosure

JE24

Monthly Operating Report
October 14, 2003
RBG-46186
RBF1-03-0192
Page 2 of 2

cc: U. S. Nuclear Regulatory Commission
Region IV
611 Ryan Plaza Drive, Suite 400
Arlington, TX 76011

NRC Senior Resident Inspector
R-SB-14

INPO Records Center
700 Galleria Parkway
Atlanta, GA 30339-3064

Mr. Jim Calloway
Public Utility Commission of Texas
1701 N. Congress Ave.
Austin, TX 78711-3326

Dottie Sherman
American Nuclear Insurers
29 South Main Street
West Hartford, CT 06107

Docket No. 50-458
River Bend Station

Date: October 14, 2003
Completed by: Danny H. Williamson
Title: Sr. Licensing Specialist
Telephone: 225-381-4279

Page 1 of 2

OPERATING STATUS

1. Reporting period: September 2003
2. Maximum dependable capacity (MWe-Net): 966
3. Design electrical rating (MWe-Net): 966

	<u>MONTH</u>	<u>YEAR TO DATE</u>	<u>CUMULATIVE</u>
4. Number of hours reactor was critical	<u>694.2</u>	<u>5909.7</u>	<u>125,917.9</u>
5. Hours generator on line	<u>684.7</u>	<u>5843.1</u>	<u>122,188.5</u>
6. Unit reserve shutdown hours	<u>0</u>	<u>0</u>	<u>0</u>
7. Net electrical energy generated (MWH)	<u>640,667</u>	<u>5,474,822</u>	<u>109,540,198</u>

UNIT SHUTDOWNS

<u>NUMBER</u>	<u>DATE</u>	<u>TYPE</u>	<u>DURATION</u>	<u>SHUTDOWN METHOD</u>	<u>REASON</u>	<u>CAUSE / CORRECTIVE ACTIONS</u>
03-05	030922	F	35.3 hrs.	3	A	During scheduled main turbine control valve testing, an apparent malfunction in the electro-hydraulic control system caused reactor pressure to increase to the automatic scram setpoint. The results of the investigation will be documented in Licensee Event Report 50-458/03-008.

LEGEND:

TYPE:

- F - Forced
- S - Scheduled

SHUTDOWN METHOD:

- 1 - Manual
- 2 - Manual trip / scram
- 3 - Automatic trip / scram
- 4 - Continuation
- 5 - Other (explain)

REASON:

- A - Equipment failure (explain)
- B - Maintenance or Test
- C - Refueling
- D - Regulatory restriction
- E - Operator training / License Exam
- F - Administrative
- G - Operational error (explain)
- H - Other (explain)



Danny H. Williamson