

Veeco

VIRGINIA ELECTRIC AND POWER COMPANY
Surry Power Station
P.O. Box 315
Surry, Virginia 23883

April 16, 1975

Director of Regulatory Operations
230 Peachtree Street, N. W.
Suite 818
Atlanta, Georgia 30303

This is to inform you of an abnormal occurrence that occurred at the Surry Power Station on April 12, 1975.

Stop valve FCV-GW-260, which isolates Unit 2 containment vacuum pump discharge, failed to shut when a Process Vent System high radiation alarm was manually initiated for training. Preliminary investigations indicate that a control relay for this valve had malfunctioned.

E. M. Sweeney, Jr.
E. M. Sweeney, Jr.
Station Manager

8402280052 750418
PDR ADOCK 05000280
PDR
8

50-284

7 h. file

Letter to N. C. Mosely from Virginia Electric and Power Company dated April 16, 1975.

DISTRIBUTION:

50-281

H. D. Thornburg, IE

→ EE:KQS (5)

Office of Standards Development

Central Files

Division of Reactor Licensing (13)

PDR

Local PDR

NSIC

TIC

STATE